

**Veron Chen (LKKAUTO)**

---

**From:** Toh Boon Wah <bwttoh@boonsiewhonda.com.sg>  
**Sent:** Saturday, 16 May 2020 12:57 PM  
**To:** Guo Qiang (LKKAUTO)  
**Subject:** RE: Resurvey photo - Honda FBN4809K  
**Attachments:** 2090\_001.pdf

Hi Guo Qiang,

Please refer to the revised Supplementary item as attached.

We detected No. 2 Pin step bar is bend and No. 11 Step holder is also distorted resulted the No.5 Step arm unable to flip up/down.

Please let me know if you require any clarification.

Thank you,

Regards,  
Toh BW  
Boon Siew S'pore Pte Ltd  
370 Ubi Road 3  
S'pore 408651

DID: 6513 9333  
HP: 9112 1132

-----Original Message-----

From: Toh Boon Wah  
Sent: Friday, 15 May 2020 5:08 pm  
To: LKK, GUO QIANG (guoqiang@lkkauto.com) <guoqiang@lkkauto.com>  
Subject: Resurvey photo - Honda FBN4809K

Hi Guo Qiang,

Attached photo as per your request.

Please note we will be putting up Supplementary for 3 more items. (Parts diagram attached) we will require to indent the parts from overseas and due to the covid-19 some delay will be expected, we shall finalise with you once the full repair is completed.

Regards,  
Toh BW  
Boon Siew S'pore Pte Ltd  
370 Ubi Road 3  
S'pore 408651

DID: 6513 9333

HP: 9112 1132