

**BOON SIEW SINGAPORE PTE LTD**

370 Ubi Road 3 Singapore 408651

255 Alexandra Road Singapore 159937

Tel: +65 6339 9002

Website: +65 6333 4332

FINALISED

Date: 17/10/20

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

3 days

Customer : MSIG INSURANCE (SINGAPORE)
 4 SHENTON WAY
 #23-01 SGX CENTRE 2 SINGAPORE 068807
 SINGAPORE 2 SINGAPORE 068807

Registration No : FBN4809K
 Chassis No : JH2RC95A7JK109220
 Model : ADV750J ED
 Owner's Name : MSIG INSURANCE (SINGAPORE)
 Ins Policy No :
 Date of Accident : 28/10/2019

Document No. : SQT0000001 Page 1
 Date : 21. Nov 2019
 Customer No. : 902
 Svc Advisor :
 Engine No : RC88E6217923
 Date | Time : 21. Nov 2019 9:47:44 AM
 Surveyor Name : HOCK ANN
 Survey Date : 26/11/2019
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	DATE OF ACCIDENT:28.10.19						
	POLICY NO.:DMMPHQ19-001186						
	DATE TOW/DRIVE IN:13.05.20						
	SURVEYOR NAME:LKK, HOCK ANN						
	DATE SURVEY:26.11.19						
	AUTHORISED BY:CHRISTINA WONG / 10.02.20						
	EXCESS:N.A						
	3RD PARTY VEHICLE NO.:GBA377J						
070798	TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT, REALIGN AFFECTED PORTION TO ALIGNMENT	2.5	280.00		700.00	49.00	749.00
060698	USING HONDA MOTORCYCLE COMMUNICATION SYSTEM (MCS) TO ERASE/RESET MEMORY. NETT	1	120.00		120.00	8.40	128.40
WSP006	SUPPLY FRONT NUMBER PLATE(S) NETT	1	25.00		25.00	1.75	26.75
	Sum Labor				845.00	59.15	904.15
88220-MGS-D30	MIRROR COMP L,BAC	1	102.70		102.70	7.19	109.89
53196-MKH-D00	HOLDER COMP, L KNUCKLE	1	18.70		18.70	1.31	20.01
77250-MKH-D00ZD	COWL, L REAR*R381C*	1	196.80		196.80	13.78	210.58
64372-MKH-D00ZC	COWL ASSY *R381C*	1	710.80		710.80	49.76	760.56
50610-MKH-D00	STAY,R FLOOR	1	172.60		172.60	12.08	184.68
64420-MKH-D00	SKIRT COMP, RIGHT FLOOR	1	98.90		98.90	6.92	105.82
50711-MKH-D00ZC	ARM, R PILLION*NH460M*	1	93.30		93.30	6.53	99.83
64100-MKH-D00ZA	SET ILLUSTRATE*TYPE1*	1	528.20		528.20	36.97	565.17
50639-MKH-D00	PIN, STEP BAR	1	8.35		8.35	0.58	8.93
50716-MKH-D00	RUBBER, LEFT PILLION	1	18.00		18.00	1.26	19.26
50718-MKH-D00	PLATE, L. PILLION STEP	1	22.75		22.75	1.59	24.34
50750-MKH-D00ZC	HOLDER, L*NH460M*	1	443.00		443.00	31.01	474.01
90119-MKH-D00	BOLT, SPECIAL, 5X10	2	2.40		4.80	0.34	5.14
94540-06018	E-RING, 6MM	1	2.65		2.65	0.19	2.84

Printed on 17/10/2020 11:05:21 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**BOON SIEW SINGAPORE PTE LTD**

370 Ubi Road 3 Singapore 408651

255 Alexandra Road Singapore 159937

Tel: +65 6339 9002

Website: +65 6333 4332

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE)
4 SHENTON WAY
#23-01 SGX CENTRE 2 SINGAPORE 068807
SINGAPORE 2 SINGAPORE 068807

Registration No : FBN4809K
Chassis No : JH2RC95A7JK109220
Model : ADV750J ED
Owner's Name : MSIG INSURANCE (SINGAPORE)
Ins Policy No. :
Date of Accident : 28/10/2019

Document No. : SQT0000001 **Page** 2
Date : 21. Nov 2019
Customer No. : 902
Svc Advisor :
Engine No : RC88E6217923
Date | Time : 21. Nov 2019 9:47:44 AM
Surveyor Name : HOCK ANN
Survey Date : 26/11/2019
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST	Amount
						Amount	incl GST
50712-MKH-D00ZC	ARM, L PILLION*NH460M*	1	107.75		107.75	7.54	115.29
Sum Item					2529.30	177.05	2,706.35

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 3,374.30 236.20 3,610.50

Total (Inclusive of GST) 3,610.50

Printed on 17/10/2020 11:05:21 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.