

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MZ EXPRESS

BLK 189A RIVERVALE DRIVE

#04-1018

S 541189

TP Lor Pac.

Khanchana.

Date

:18.11.2019

Vehicle No

:SLK 750 T

Make/Model

:TOYOTA ALPHARD

Accident date

:15.11.2019

No	DESCRIPTION	Qty	Amount (S\$)
<u>List Items</u>			
1	Front bumper <i>Dehon</i>	1	\$ 1217.3 ✓
2	Front bumper RH side holder <i>nm</i>	1	\$ 181.9 ✓
3	Front RH headlamp <i>lt</i>	1	\$ 2800.1 ✓
4	Front RH headlamp lower garnish <i>nm</i>	1	\$ 69 ✗
5	Front RH fender <i>Repis</i>	1	\$ 789.2 ✗
6	Front RH fender inner shield <i>nm</i>	1	\$ 235 ✗
			\$ 5292.5
Less 25% Disc			\$ 1323.1
Total			\$ 3969.4

Special Nett Items

1	Front RH fender inner shield clips (1 set) <i>nm</i>		\$ 50 ✗
2	Front RH sport rim <i>nm</i>	30	\$ 1100 ✗
3	Front bumper clips (1 set) <i>nm</i>		\$ 55 30
Total			\$ 1205

Labour Cost

1	To check wheel alignment		\$ 100 ✗
2	Remove, replace & repair consistent to the accident		\$ 800 250
3	Respray painting		\$ 800 500
Total			\$ 1700

4 Wiring,

5 Remove and reinstall bumper sensor

100 30

100 50

Grand Total

\$ 6874.4

total: 5237.30

1/s: 4.2K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: