

ASS. REC. BY:

REF:

CS/SMO19020885/Asd3 n2

Special Instructions:

Surveyor: Adrian

## ASSIGNMENT (Office)

From (Person): Yang Kang Melvin

of

SMO

Date/Time: 26/11/19 @ 11:30am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SAS 9675K

Insured:

PC8828X

at Workshop in/s

Sin Yu Sin Workshop

Tel:

91993103

of

1 Kaki Bukit Ave 6 #01-52

Policy No:

Claim No:

CMID1905476/GPL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12pm @ 26/11/19

Person Contacted:

Wei Leong

Vehicle IN/OUT

Date/Time

Action/Instruction

Johny /

SAS 9675K-X

PC8828X-NS/IN 14002564/H1c b3

D.O.A. 5/12/2019

24/11/19

@ 15:58 pm revert parking estimate from report to Pau Leong via email.

Adrian

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SGS967SK Yr Regn: 2007 March  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda Stream C.C. 1799  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 183568 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RN61025477  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/45 R17  
 R: 215/45 R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Roadstone  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 26/11/19  
 Survey held at Sih Yu Sin  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Samp. COE Expiry: 31/12/21

MV: 16.5K  
 PV: 11.6K  
 Nett: 4.9K.

RECEIVED 12 FEB 2020

Adrian Confirmed L1s \$ 4,400/- @ 5 days with Bors  
 (\$ 5,092.80 red 52%)

Date/Time, File Pass is/7  
12/02/20 ☐ : Prel. Report  
Typ:st ☒ : Final Report  
 Date/Time, File Return is/7  
3

Days Of Repair: 5  
 Resurvey No. of Trip: 1

Adm Fee: ☐ Site Insp \$  
☐ Interview \$  
☐ Tech. Insp \$  
☐ Wash up \$

Survey Fee	
Transportation	
Food & Accom	
Pleas	
Other	
TOTAL	250

Report Format:  
 Long \$ 4,400/- L1s

## Nivitha (LKK Auto)

---

**From:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
**Sent:** Tuesday, 26 November 2019 11:30 AM  
**To:** sur@lkkauto.com; assignments  
**Cc:** sinyu sin  
**Subject:** FW: Accident on 23/11/2019 involving SGS9675K & PC8828X along kaki bukit ave 6  
Our ref : CMTD1905476/GPL

Dear LKK Auto,

Please make the arrangement to survey for SGS9675K on a without prejudice basis and revert with your preliminary report upon completion of survey to my colleague, Pau Loong.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



or



Download now @

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** sinyu sin <sinyusin@hotmail.com>

**Sent:** Tuesday, 26 November, 2019 11:13 AM

**To:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

**Cc:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

**Subject:** Re: Accident on 23/11/2019 involving SGS9675K & PC8828X along kaki bukit ave 6 Our ref : CMTD1905476/GPL

Dear Melvin,

Till now we still have not received any call from LKK.

Please kindly update will LKK survey coming today to survey our vehicle? SGS9675K

Thank you

Regards  
Welleang  
Sin Yu Sin Workshop  
1 Kaki Bukit Ave 6  
#01-52 (Autobay)  
Singapore 417883

Tel: 91993103 Fax: 68163103

---

**From:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>  
**Sent:** Monday, November 25, 2019 11:29 AM  
**To:** sinyu sin <[sinyusin@hotmail.com](mailto:sinyusin@hotmail.com)>  
**Cc:** Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** RE: Accident on 23/11/2019 involving SGS9675K & PC8828X along kaki bukit ave 6 Our ref : CMTD1905476/GPL

Dear LKK Auto,

Please make the arrangement to survey for SGS9675K on a without prejudice basis and revert with your preliminary report upon completion of survey to my colleague, Pau Loong.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @



or



**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** sinyu sin <[sinyusin@hotmail.com](mailto:sinyusin@hotmail.com)>

**Sent:** Monday, 25 November, 2019 11:23 AM

**To:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>

**Cc:** Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** Re: Accident on 23/11/2019 involving SGS9675K & PC8828X along kaki bukit ave 6 Our ref : CMTD1905476/GPL

Dear Melvin,

We would like to choose No 2 LKK Auto Consultants (Marcus Chua) as a SJE.

Thank you

Regards

Weileang

Sin Yu Sin Workshop

1 Kaki Bukit Ave 6

#01-52 (Autobay)

Singapore 417883

Tel: 91993103 Fax: 68163103

---

**From:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>

**Sent:** Monday, November 25, 2019 11:16 AM

**To:** sinyu sin <[sinyusin@hotmail.com](mailto:sinyusin@hotmail.com)>

**Cc:** Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** RE: Accident on 23/11/2019 involving SGS9675K & PC8828X along kaki bukit ave 6 Our ref : CMTD1905476/GPL

Our Reference : CMTD1905476/GPL

Your Reference: SGS9675K

Date: 25/11/2019

Without Prejudice

Attention:

SIN YU SIN WORKSHOP

Dear Weileang,

ACCIDENT INVOLVING SGS9675K & PC8828X ON 23.11.2019

We refer to your Notice of Accident dated 25/11/2019.

Please be informed that Mr Gnoh Pau Loong is the handler of this case.

We regret to inform that we are unable to revert on liability for direct settlement as we have yet to receive our insured's accident report.

Kindly advise should you still require us to conduct survey on a "Without Prejudice" basis.

If you are agreeable to conduct survey on a "Without Prejudice" basis, we propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** sinyu sin <[sinyusin@hotmail.com](mailto:sinyusin@hotmail.com)>

**Sent:** Monday, 25 November, 2019 10:14 AM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

**Subject:** Accident on 23/11/2019 involving SG59675K & PC8828X along kaki bukit ave 6

Dear Sirs,

We are instructed to send you the attached Notice of Accident / to conduct pre-repair survey.

Your insurer: PC8828X

Thank you

Regards

Weileang

Sin Yu Sin Workshop

1 Kaki Bukit Ave 6

#01-52 (Autobay)

Singapore 417883

Tel: 91993103 Fax: 68163103

## **Shirley Hiew (LKK Auto)**

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Wednesday, 27 November 2019 3:58 pm  
**To:** Gnoh, Pau Loong  
**Cc:** SUR; 'Ye, Yong Kang Melvin'; assignments  
**Subject:** RE: Accident on 23/11/2019 involving SGS9675K & PC8828X along kaki bukit ave 6  
Our ref : CMTD1905476/GPL

Dear Pau Loong,

Please be informed that we have inspected the vehicle SGS 9675K on 26/11/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Tuesday, 26 November 2019 12:01 pm  
**To:** 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Accident on 23/11/2019 involving SGS9675K & PC8828X along kaki bukit ave 6 Our ref : CMTD1905476/GPL

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	419C
Vehicle Information	
Vehicle No.:	SGS9675K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	R18A1728771
Chassis No.:	RN61025477
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,864.00
Original Registration Date:	28 Mar 2007
First Registration Date:	28 Mar 2007
Transfer Count:	4
Actual ARF Paid:	\$19,651.00
PARF Information	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Information	
COE Expiry Date:	31 Dec 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$27,594.00
COE Rebate Amount:	\$11,571.00
Total Rebate Amount:	\$11,571.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Nov 2019

OK

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : [Sinyusin@hotmail.com](mailto:Sinyusin@hotmail.com)

*Shirley*

25 November 2019

## QUOTATION FOR ACCIDENT REPAIR OF SGS9675K HONDA STREAM

### THIRD PARTY INSURER: SOMPO INSURANCE

S/No.	Parts List	Qty	Amount (\$)
1.	Front door LH <i>Distorted</i>	1	\$ 1109.90 ✓
2.	Front door window glass outer moulding LH <i>Re-lid</i>	1	\$ 137.30 ✓
3.	Front door outer handle LH <i>Crack</i>	1	\$ 132.10 ✓
4.	Front door outer handle end garnish LH <i>Crk</i>	1	\$ 56.40 ✓
5.	Front door black tape LH <i>New</i>	2	68.00 <del>\$ 136.00</del> 60(SW)
6.	Front door hinge U/L (LH) <i>New</i>	2	64.60 \$ 129.20 +
7.	Front checker LH <i>New</i>	1	\$ 156.80 +
8.	Front door weather strip LH <i>New</i>	1	\$ 120.60 +
9.	Front door mechanism lock LH <i>Damaged</i>	1	\$ 281.90 ✓
10.	Front door lock striker LH <i>New</i>	1	\$ 55.00 +
11.	Front door window glass regulator LH <i>Bent</i>	1	\$ 216.60 ✓
12.	Front door window glass regulator motor LH <i>New</i>	1	\$ 393.30 +
13.	Front door inner trim board LH <i>Painted</i>	1	\$ 587.10 ✓
14.	Front door inner trim board clip LH <i>New</i>	10	4.50 <del>\$ 45.00</del> 30
15.	Front door side mirror assy LH <i>New</i>	1	\$ 474.00 ✓
16.	Front door speaker LH <i>New</i>	1	\$ 168.60 +
17.	Rear door LH <i>Distorted</i>	1	\$ 1172.50 ✓
18.	Rear door window glass outer moulding LH <i>New</i>	1	\$ 137.30 +
19.	Rear door outer handle LH <i>New</i>	1	\$ 132.10 ✓
20.	Rear door outer handle end garnish cover LH <i>New</i>	1	\$ 56.40 ✓
21.	Rear door black tape LH <i>New</i>	2	68.00 <del>\$ 136.00</del> 60(SW)
22.	Rear door weather strip LH <i>New</i>	1	\$ 156.80 +
23.	Rear door hinge U/L (LH) <i>Bent</i>	2	<del>64.60</del> \$ 120.60 ✓
24.	Rear door checker LH <i>New</i>	1	\$ 68.50 ✓
25.	Rear door mechanism lock LH <i>New</i>	1	\$ 281.90 +
26.	Rear door lock striker LH <i>New</i>	1	\$ 55.00 +
27.	Rear door window glass regulator LH <i>Bent</i>	1	5408.20 \$ 235.60 ✓
28.	Rear door window glass regulator motor LH <i>New</i>	1	4326.56 \$ 401.20 +
29.	Rear door inner trim LH <i>Painted</i>	1	\$ 587.10 ✓
30.	Rear door inner trim board clip LH <i>New</i>	10	4.50 <del>\$ 45.00</del> 30
31.	Rear door speaker LH <i>New</i>	1	S.N: 120 \$ 168.60 ✓
32.	Door centre pillar LH <i>Repair</i>	1	\$ 936.60 +
Subtotal before discount			\$ 8891.00
Discount 20%			\$ 1778.20
Subtotal 1			\$ 7112.80

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : [Sinyusin@hotmail.com](mailto:Sinyusin@hotmail.com)

25 November 2019

## QUOTATION FOR ACCIDENT REPAIR OF SGS9675K HONDA STREAM

### THIRD PARTY INSURER: SOMPO INSURANCE

#### Labour

To check wirings.	\$ 80 30
To remove and reinstall rear interior trims, garnishes, seats etc. for necessary repair	\$ 200 60
To transfer front LH door component parts to new door	\$ 160 80
To transfer rear LH door component parts to new door	\$ 160 80
To apply anti-rust undercoat	\$ 80 60
To straighten, repair, realign on affected area and replace damaged parts	\$ 1000 600
To spray painting on affected area	\$ 1000 600
Total Labour Cost	\$ 2680

Total Cost Of Repairs(Total cost of parts + Total labour cost) **\$ 9792.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim  
L/s. 26/11/19.

05 Rys

total: 5956.56

L/s. 47K



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19020885/Asd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 12-02-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PC 8828X	Veh. Inspected	SGS 9675K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905476/GPL	Excess (\$)	0.00	
Assign From	YONG KANG MELVIN	Assign Date	26/11/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	RN61025477	Colour	BLACK	
Odometer	183568	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	ROADSTONE	6 mm	
L/H Front Tyre	215/45 R17	ROADSTONE	6 mm	
R/H Rear Tyre	215/45 R17	ROADSTONE	6 mm	
L/H Rear Tyre	215/45 R17	ROADSTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/11/2019	Inspection Date	26/11/2019	
Survey held at	SIN YU SIN WORKSHOP 1 KAKI BUKIT AVE 6 #01-82 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 9675K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT DOOR LH	DISTORTED	1,109.90	1,109.90
1	FRONT DOOR WINDOW GLASS OUTER MOULDING LH	DEFORMED	137.30	137.30
1	FRONT DOOR OUTER HANDLE LH	CRACKED	132.10	132.10
1	FRONT DOOR OUTER HANDLE END GARNISH LH	CUT	56.40	56.40
2	FRONT DOOR HINGE U/L (LH) @\$64.60	NOT NECESSARY	129.20	-
1	FRONT CHECKER LH	NOT NECESSARY	156.80	-
1	FRONT DOOR WEATHER STRIP LH	NOT NECESSARY	120.60	-
1	FRONT DOOR MECHANISM LOCK LH	DAMAGED	281.90	281.90
1	FRONT DOOR LOCK STRIKER LH	NOT NECESSARY	55.00	-
1	FRONT DOOR WINDOW GLASS REGULATOR LH	DAMAGED	216.60	216.60
1	FRONT DOOR WINDOW GLASS REGULATOR MOTOR LH	NOT NECESSARY	393.30	-
1	FRONT DOOR INNER TRIM BOARD LH	CRACKED	587.10	587.10
10	FRONT DOOR INNER TRIM BOARD CLIP LH @\$4.50	NECESSARY	45.00	30.00
1	FRONT DOOR SIDE MIRROR ASSY LH	DAMAGED	474.00	474.00
1	FRONT DOOR SPEAKER LH	NOT NECESSARY	168.60	-
1	REAR DOOR LH	DISTORTED	1,172.50	1,172.50
1	REAR DOOR WINDOW GLASS OUTER MOULDING LH	NOT NECESSARY	137.30	-
1	REAR DOOR OUTER HANDLE LH	NOT NECESSARY	132.10	-
1	REAR DOOR OUTER HANDLE END GARNISH COVER LH	NOT NECESSARY	56.40	-
1	REAR DOOR WEATHER STRIP LH	NOT NECESSARY	156.80	-
2	REAR DOOR HINGE U/L (LH)	BENT	120.60	120.60
1	REAR DOOR CHECKER LH	BENT	68.50	68.50
1	REAR DOOR MECHANISM LOCK LH	NOT NECESSARY	281.90	-
1	REAR DOOR LOCK STRIKER LH	NOT NECESSARY	55.00	-
1	REAR DOOR WINDOW GLASS REGULATOR LH	DAMAGED	235.60	235.60
1	REAR DOOR WINDOW GLASS REGULATOR MOTOR LH	NOT NECESSARY	401.20	-
1	REAR DOOR INNER TRIM LH	CRACKED	587.10	587.10
10	REAR DOOR INNER TRIM BOARD CLIP LH @\$4.50	NECESSARY	45.00	30.00
1	REAR DOOR SPEAKER LH	CRACKED	168.60	168.60
1	DOOR CENTRE PILLAR LH	TO REPAIR SEE LABOUR	936.60	-

Report Ref No. CS/SMO19020885/Asd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,723.80	-1,081.64
			6,895.20	4,326.56
2	FRONT DOOR BLACK TAPE LH @\$68.00 (SN)	NECESSARY	136.00	60.00
2	REAR DOOR BLACK TAPE LH @\$68.00 (SN)	NECESSARY	136.00	60.00
	LESS 20% DISCOUNT		-54.40	-
			217.60	120.00
	<b>LABOUR</b>			
	TO CHECK WIRINGS.		80.00	30.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS,GARNISHES,SEATS ETC.FOR NECESSARY REPAIR.		200.00	60.00
	TO TRANSFER FRONT LH DOOR COMPONENT PARTS TO NEW DOOR.		160.00	80.00
	TO TRANSFER REAR LH DOOR COMPONENT PARTS TO NEW DOOR.		160.00	80.00
	TO APPLY ANTI-RUST UNDERCOAT.		80.00	60.00
	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF DOOR CENTRE PILLAR LH.		1,000.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,000.00	600.00
			2,680.00	1,510.00
<b>GRAND TOTAL</b>			<b>9,792.80</b>	<b>5,956.56</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,700.00</b>

Report Ref No. CS/SMO19020885/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.