

ASS. REC. BY:

REF: CS/INC19020894/R1fd3

12

Special Instruction:

Survey: ROSU

ASSIGNMENT (Office)

From (Person): Hazalya B Ibrahim of INC

Date/Time: 26/11/19 @ 9:37am

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 711 B

Insured: SUM 751 P

at Workshop m/s Tams Gurokars

Tel: 8128 9802

of 27A Tanjung Perjump

Policy No:

Claim No: MT/1072243-002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 19/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:45am @ 26/11/19

Person Contacted: JCS

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction
	Estimate /
	SKS 711B - CS/ECIS 1702/602 / Citbn 2
	DoA. 31/10/2017
	Part by Part \$7,633.70: (Red: 2735.10: 26%)

ASS. REC. BY:

REF: INC

3894

ASSIGNMENT

From:

Date: 26/11/2019

Veh No:

SKS 711B

Yr Regn:

2015 / MAR

Estimated Cost:

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

Make:

MAZDA3 4-door Sedan / SL C.C. 1496

To Inspect Vehicle No:

SKS711B

Colour:

GREY

A/C:

Insured / Std / NI / NA

at Workshop m/s

Trans Eurokars

Sp. Reading

56793

T/Radio: Insured / Std / NI / NA

of

27A Tanjung Perjam

Eng/No:

C/No:

JM 6BM 42A860303570

Insured:

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Policy No.

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Claims No.

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

(Client's Record)

Modi: Nil / ☒ S/Rim / STD A/Rim or

Make of Veh:

2pm - 4pm

Tyre Size:


F:

205/60R16

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

19/11/19

D.O.I.

26/11/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

TRANSEUROKARS

2.13pm

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 24 MAR 2020

Date/Time, File Pass to?

11/24/3 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / O/S

TP

7083.70

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Week end (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos:

Others:

TOTAL

250

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Wednesday, 27 November 2019 9:49 AM
To: Admin-D (LKKAuto); assignments
Cc: Hazalya Binte Ibrahim; SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 26/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 26 November 2019 10:40 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Susan Ting <susan.ting@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 26/11/2019

Dear Hazalysa,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalysa Binte Ibrahim [mailto:hazalysa.ibrahim@income.com.sg]

Sent: Tuesday, 26 November 2019 9:37 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Susan Ting <susan.ting@income.com.sg>; Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 26/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Fiona Shen	MT/1072178-002	SIV8136E	CAR LIFE AUTO ENGINEERING SERVICES	BLK 1002 BUKIT MERAH LANE 3 #01-75	/ 62733810		GBG182Y	20/11/19	
2	Cyndie Yong	MT/1072920-002	SHB2379P	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	VADIVELAN MOHAN / 62657130 / 96891857		SIY9469Y	24/11/19	
3	Cyndie Yong	MT/1072650-002	SHA9526R	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	VADIVELAN MOHAN / 62657130 / 96891857		SKB9548L	22/11/19	

4	Eng Huey	MT/1072027-002	SCR784R	HIN LUNG WORKSHOP	BLK 1008 #01-20 BUKIT MERAH LANE 3 SINGAPORE 159722	Anna / 6858 3000	10:00- 12:00	F24485A	18/11/19	
5	Juliana Lee	MT/1072062-002	FX7628X	LEONG SENG MOTOR PTE LTD	BLK 1006 #01-08 BUKIT MERAH LANE 2 SINGAPORE 159762	c s teo / 62737469	10:00- 12:00	SJY6501G	16/11/19	will be on half day leave tomorrow afternoon**
6	Juliana Lee	MT/1072594-002	SLS6866L	MILLION AUTO SERVICE	4 PENIURU PLACE #01-12 2.8 PENIURU TECH HUB	Ms Chong / 82285020 / 62649091		SMN787K	21/11/19	
7	Chester Chong	MT/1072243-002	SKS711B	TRANS EUOKARS PTE LTD	27A TANJONG PERIURU SINGAPORE 609042	Jess Francis Carlos / 8128 9802	14:00- 16:00	SGM751P	19/11/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/11/2019 17:23
Date Of Accident	19/11/2019 07:45
Exact Location Of Accident	JURONG PIER CIRCUS (BELOW JURONG PIER FLYOVER)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS711B
Insured/Policyholder	
Name Of Registered Owner	MR ERIK LOW KIM LEE
NRIC No	S1586389G
Email Address	ERIK.LOW@SEMBMARINE.COM
Mobile Phone No	(LOCAL) +65-96356716
Alternative Phone No	OFFICE-96356716

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.4 SEDAN 1.5L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	MR ERIK LOW KIM LEE
NRIC No	S1586389G
Date Of Birth	02/07/1963
Occupation	INDOOR
Date Of Driving Pass	26/01/1984
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96356716
Fax Number	
Contact Number	OFFICE-96356716
Email Address	ERIK.LOW@SEMBMARINE.COM

Address	BKL 212 JURONG EAST STREET 21 #20-289
Postcode	600212
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - ROUNDABOUT
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE SKETCH PLAN

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGM751P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	BLADEN NG KEE YU
NRIC/Passport Number	
Contact Number	97980487
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SKS 711 B

ACCIDENT DATE: 19/11/2019	CONTACT NUMBER: 96356716
ACCIDENT TIME: 0745 HRS	EMAIL: eiklow66@gmail.com
LOCATION: JURONG PIER CIRCUS (UNDER JURONG PIER FLYOVER)	
My car SKS 711 B was behind SGM 751 P at the traffic getting into Jurong Pier Circus.	
SGM 751 P was travelling on inner circus (right lane).	
My car filtered to the left lane and drove up towards Jalan Buruh exit.	
SGM 751 P did not signal on my right but make a left turn towards exit to Jurong Island, thereby his left front bumper area hit my right hind tyre/tire side.	
I drove my car up and park safely at exit Jalan Buruh, walked to the exit to Jurong Island where SGM 751 P stopped his car and we only exchange phone numbers. Later we exchanged photos of damage.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.	
PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
PLEASE STATE: ☐ CLAIM OWN POLICY ☒ CLAIM THIRD PARTY ☐ (REPORTING ONLY)	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 19/11/2019
1157 hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature

Date & Time: 19/11/2019

1540 HRS

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Erik Low Kim Lee
Period of Insurance : 24 Mar 2019 To 23 Mar 2020
Engine No. : P520267606
Chassis No. : JM6BM42A8G0303570

Vehicle No. : SKS711B
Policy No. : 2100406735-04
Endorsement No. :
Issued Date : 12 Mar 2019

ABOUT THE COVER

Make/Model : MAZDA 3 1.5 SKYACTIV

Engine Capacity/Tonnage : 1,496.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2015

Insuring with COE/PARF : No

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" (IDR) if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods (other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade).

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Erik Low Kim Lee - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Trans Eurokars Pte Ltd. Add: 27A Tanjong Pagar Road, Singapore 069042 63310508

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 5200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1969 (Malaysia).

0503599190

ARF (AP) PTE LTD - MAZDA

7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX

SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPLC



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

NTUC INCOME INSURANCE 1 MARITIME SQUARE #10-01 HARBOURFRONT CENTRE SINGAPORE 099253 ATTN.: MOTOR CLAIMS FAX:		NAME: LTPI Mr Yeo Seck Kan ADDRESS: 525 Serangoon North Avenue 4 #14-70 Singapore 550525 TEL: 96288408MS		WIP: 56414 EXCESS: DATE: 20-Nov-19	
VEH NO:	SKS7117X	DATE IN:		CONTACT PERSON:	Jess 63957874
CHASSIS NO:	JM6GL1072K0312585	MILEAGE:	56793	TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA6	DATE REG.:	21-Mar-19	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	RETAINER RHS	X Svc 1	MGJR9-50-2H1	\$ 41.00
2	FASTENER, REAR BUMPER	X Svc 6	MB45A-56-146A	\$ 18.00
3	GROMMET, REAR BUMPER	X Svc 2	M9991-00-501	\$ 6.00
4	RIVET, REAR BUMPER	X Svc 2	MTK21-50-355	\$ 18.40
5	RIVET, REAR BUMPER	X Svc 6	MEA01-50-037	\$ 48.00
6	TAPE PROTECTOR, SENSOR	X Svc 4	MBCKA-50-EM1	\$ 18.80
7	GASKET LHS, TAILLAMP	na / 1	MGRF5-51-163	\$ 22 46.00
8	GASKET RHS, TAILLAMP	na / 1	MGRF5-51-153	\$ 22 46.00
9	REAR FENDER RHS	bt / 1	MGSY7-70-41X	1233 \$ 1,312.50
10	REAR WINDSCREEN MOULDING	na / 1	MGHK1-50-611B	77 \$ 117.10
11	SPACER, REAR WINDSCREEN	na / 1	MGJ6A-50-897	470 \$ 12.80
12	GUARD STONE RHS	na / 1	MGHP9-50-4P2A	18.70 \$ 17.40
13	REAR WHEEL RIM RHS	Svc / 1	M9965-16-7570	1156.40 \$ 1,196.80
TOTAL PARTS				\$ 2,898.80
TOTAL PARTS COST				\$ 2,898.80

Labour Description

1	TO REPLACE REAR FENDER RH. TO REPAIR REAR BUMPER, REAR DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	1650 ✓	\$ 1,980.00
2	TO RESPRAY REAR BUMPER, REAR FENDER RH AND REAR DOOR RH.	1260 ✓	\$ 1,890.00
3	MZ-BR-GLASS1 TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT	\$ 560.00
4	MZ-BR-GLASS2 TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	\$ 120.00
5	MZ-BR-REVSER TO TRANSFER REVERSE SENSORS.	X NETT	\$ 330.00

6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	330	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	100	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	100	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11		TO SUPPLY BRILA PREMIUM COATING. <i>nn ?</i>	NETT X	\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ ²⁰ 100.00

TOTAL LABOUR	\$ -	\$ 7,520.00
TOTAL PARTS	\$ -	\$ 2,898.80
TOTAL	\$ -	\$ 10,418.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

11099.60

Authorised Signature

Passer
4p 900/1000s
7 days
26/11/19 @ 1410
Respray before paint



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

NTUC INCOME INSURANCE		NAME : LTPI Mr Yeo Seck Kan		WIP : 56414	
1 MARITIME SQUARE		ADDRESS : 525 Serangoon North Avenue 4		EXCESS :	
#10-01 HARBOURFRONT CENTRE		#14-70		DATE: 20-Nov-19	
SINGAPORE 099253		Singapore 550525			
ATTN : MOTOR CLAIMS		TEL : 96288408MS			
FAX :					
VEH NO : SKS7117X		DATE IN :		CONTACT PERSON : Jess 63957874	
CHASSIS NO : JMB B1142A8G0303570		MILEAGE : 56793		TYPE OF CLAIM : THIRD PARTY CLAIM	
MODEL : MAZDA6 W3		DATE REG.: 21-Mar-19		POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	RETAINER RHS X SUC	1			\$ 41.00
2	FASTENER, REAR BUMPER X SUC	6			\$ 18.00
3	GROMMET, REAR BUMPER X SUC	2			\$ 6.00
4	RIVET, REAR BUMPER X SUC	2			\$ 18.40
5	RIVET, REAR BUMPER X SUC	6			\$ 48.00
6	TAPE PROTECTOR, SENSOR X SUC	4			\$ 18.80
7	GASKET LHS, TAILLAMP ne /	1			\$ 45.00 77
8	GASKET RHS, TAILLAMP ne /	1			\$ 45.00 77
9	REAR FENDER RHS bt /	1			\$ 1,332.50 1277
10	REAR WINDSCREEN MOULDING ne /	1			\$ 117.10 77
11	SPACER, REAR WINDSCREEN ne /	1			\$ 12.80 80470
12	GUARD STONE RHS ne /	1			\$ 17.40 17-4018-21
13	REAR WHEEL RIM RHS SUC	1			\$ 1,155.80 1126.81
TOTAL PARTS					\$ 2,898.80
TOTAL PARTS COST					\$ 2,898.80
Labour Description					
1	TO REPLACE REAR FENDER RH. TO REPAIR REAR BUMPER, REAR DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			1650	\$ 1,980.00
2	TO RESPRAY REAR BUMPER, REAR FENDER RH AND REAR DOOR RH.			1260	\$ 1,890.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		NETT	\$ 120.00
5	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.		NETT	\$ 330.00



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

NTUC INCOME INSURANCE		NAME : ERIC LOW KIM LEE		WIP : 56395	
1 MARITIME SQUARE		ADDRESS : 212 Jurong East Street 21		EXCESS :	
#10-01 HARBOURFRONT CENTRE		#20-289		DATE: 20-Nov-19	
SINGAPORE 099253		Singapore 600212			
ATTN. : MOTOR CLAIMS		TEL : 96356716			
FAX :					
VEH NO :	SKS711B	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BM42A8G0303570	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	21-Mar-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	RETAINER RHS	1	MGJR9-50-2H1		\$ 41.00
2	FASTENER, REAR BUMPER	6	MB45A-56-146A		\$ 18.00
3	GROMMET, REAR BUMPER	2	M9991-00-501		\$ 6.00
4	RIVET, REAR BUMPER	2	MTK21-50-355		\$ 18.40
5	RIVET, REAR BUMPER	6	MEA01-50-037		\$ 48.00
6	TAPE PROTECTOR, SENSOR	4	MBCKA-50-EM1		\$ 18.80
SUPPLEMENTARY ITEMS					
7	GASKET LHS, TAILLAMP	1	MBHN1-51-163	\$ 22.00	\$ 22.00
8	GASKET RHS, TAILLAMP	1	MBHN1-51-153	\$ 22.00	\$ 22.00
9	REAR FENDER RHS	1	MB6Y5-70-41X	\$ 1,233.00	\$ 1,233.00
10	REAR WINDSCREEN MOULDING	1	MBHN1-50-611	\$ 77.00	\$ 77.00
11	SPACER, REAR WINDSCREEN	1	MC001-50-897	\$ 4.70	\$ 4.70
12	GUARD STONE RHS	1	MBHS2-50-4P2	\$ 18.20	\$ 18.20
13	REAR WHEEL RIM RHS	1	M99650-06560	\$ 1,156.80	\$ 1,156.80
TOTAL PARTS				\$ 2,533.70	\$ 2,683.90
TOTAL PARTS COST				\$ 2,533.70	\$ 2,683.90
Labour Description					
1	TO REPLACE REAR FENDER RH. TO REPAIR REAR BUMPER AND AREAS AFFECTED BY THE ACCIDENT.			\$ 1,650.00	\$ 1,980.00
2	TO RESPRAY REAR BUMPER AND REAR FENDER RH.			\$ 1,260.00	\$ 1,890.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		\$ 560.00	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS		\$ 120.00	\$ 120.00

5	MZ-BR-REVS2N	TO TRANSFER REVERSE SENSORS.		\$ 330.00
6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 330.00	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 100.00	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 100.00	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
11		TO SUPPLY BRILA PREMIUM COATING.		\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
SUPP	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	\$ 560.00	\$ 560.00
SUPP	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 120.00	\$ 120.00
			TOTAL LABOUR	\$ 5,150.00 \$ 8,200.00
			TOTAL PARTS	\$ 2,533.70 \$ 2,683.90
			TOTAL	\$ 7,683.70 \$ 10,883.90
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 7,683.70
			GST 7%	\$ 537.86 \$ -
			GRAND TOTAL	\$ 8,221.56 \$ -

REMARKS:

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	330	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	100	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	100	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11		TO SUPPLY BRILA PREMIUM COATING.	NETT X	\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 20 100.00

TOTAL LABOUR	\$ -	\$ 7,520.00
TOTAL PARTS	\$ -	\$ 2,898.80
TOTAL	\$ -	\$ 10,418.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

27/11/19
Rasul
4p 900/10068
7 days
26/11/19 @ 1410
Resurvey before paint



TRANS EUROKARS PTE LTD



SUPPLEMENTARY ESTIMATE COST OF REPAIRS

NTUC INCOME INSURANCE 1 MARITIME SQUARE #10-01 HARBOURFRONT CENTRE SINGAPORE 099253 ATTN. : MOTOR CLAIMS FAX :		NAME : LTPI Mr Yeo Seck Kan ADDRESS : 525 Serangoon North Avenue 4 #14-70 Singapore 550525 TEL : 96288408MS		WIP : 56395 EXCESS : DATE: 20-Nov-19	
VEH NO :	SKS711B	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BM42A8G0303570	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	21-Mar-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	GASKET LHS, TAILLAMP	1	MBHN1-51-163		\$ 22.00
2	GASKET RHS, TAILLAMP	1	MBHN1-51-153		\$ 22.00
3	REAR FENDER RHS	1	MB6YS-70-41X		\$ 1,233.00
4	REAR WINDSCREEN MOULDING	1	MBHN1-50-611		\$ 77.00
5	SPACER, REAR WINDSCREEN	1	MC001-50-897		\$ 4.70
6	GUARD STONE RHS	1	MBHS2-50-4P2		\$ 18.20
7	REAR WHEEL RIM RHS	1	M9965-D0-6560		\$ 1,156.80
TOTAL PARTS					\$ 2,533.70
TOTAL PARTS COST					\$ 2,533.70
Labour Description					
1	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.			NETT \$ 560.00 (A)
2	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			NETT \$ 120.00 (A)
TOTAL LABOUR				\$ -	\$ 680.00
TOTAL PARTS				\$ -	\$ 2,533.70
TOTAL				\$ -	\$ 3,213.70
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING

TRANS EUROKARS PTE LTD

CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020894/R1td3n2
73 BRAS BASAH ROAD Date: 26-03-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: CHESTER CHONG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGM 751P	Veh. Inspected	SKS 711B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1072243-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	26/11/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 4-DOOR SEDAN 1.5L	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0303570	Colour	GREY
Odometer	56793 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	PIRELLI	6 mm
L/H Front Tyre	205/60 R16	PIRELLI	6 mm
R/H Rear Tyre	205/60 R16	PIRELLI	6 mm
L/H Rear Tyre	205/60 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/11/2019	Inspect Date / Time	26/11/2019 (02:13 PM)
Survey held at	27A TANJONG PENJURU		
Repairer	TRANS EUROKARS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 711B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RETAINER RHS (SN)	SERVICEABLE	41.00	-
6	FASTENER,REAR BUMPER (SN)	SERVICEABLE	18.00	-
2	GROMMET,REAR BUMPER (SN)	SERVICEABLE	6.00	-
2	RIVET,REAR BUMPER (SN)	SERVICEABLE	18.40	-
6	RIVET,REAR BUMPER (SN)	SERVICEABLE	48.00	-
4	TAPE PROTECTOR,SENSOR (SN)	SERVICEABLE	18.80	-
1	GASKET LHS,TAILLAMP (SN)	NECESSARY	46.00	22.00
1	GASKET RHS,TAILLAMP (SN)	NECESSARY	46.00	22.00
1	REAR FENDER RHS (SN)	BENT	1,312.50	1,233.00
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	117.10	77.00
1	SPACER,REAR WINDSCREEN (SN)	NECESSARY	12.80	4.70
1	GUARD STONE RHS (SN)	NECESSARY	18.20	18.20
1	REAR WHEEL RIM RHS (SN)	SCRATCHED	1,196.80	1,156.80
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			2,999.60	2,553.70
<u>LABOUR</u>				
TO REPLACE REAR FENDER RH.TO REPAIR REAR BUMPER,REAR DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			1,980.00	1,650.00
TO RESPRAY REAR BUMPER,REAR FENDER RH AND REAR DOOR RH.			1,890.00	1,260.00
TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			560.00	560.00
TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			120.00	120.00
TO TRANSFER REVERSE SENSORS.			330.00	-
TO REMOVE & REFIT CARPET & TRIMS PN THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.			990.00	330.00
TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.			350.00	100.00
TO CARRY-OUT BODY CAVITY PRESERVATION.			250.00	100.00
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			250.00	150.00

Report Ref No. CS/INC19020894/R1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Reg. No. 199007100N-COT Reg. No. 10-000-100				
Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NOT NECESSARY	350.00	180.00
	TO SUPPLY BRILA PREMIUM COATING.		350.00	-
	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING (ADDITIONAL).		560.00	560.00
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT (ADDITIONAL).		120.00	120.00
			8,100.00	5,130.00
GRAND TOTAL			11,099.60	7,683.70
RECOMMENDED COST OF REPAIRS (CONFIRMED)				7,683.70

Report Ref No. CS/INC19020894/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.