

ASS. REC. BY:

REF:

CS/CT1 19020901/ESB⁵²

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Ben Tang

of CT1

Date/Time: 26.11.19 2.33p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 4525B

Insured:

GBH 7514Y

at Workshop m/s Performance

Tel:

63190174

of 303 Alexandra Road

Policy No:

Claim No:

SNM 190205572

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20.11.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 26.11.2019 2.30p.m

Person Contacted:

Caroline

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 4525B - X
	GBH 7514Y - X

Surveyor

Steve


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR. Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM04525B Yr Regn: 20/8/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW X3 c.c. 1998
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 26625 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 CiNo: WBATR12970LC94288
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modl: NII / S/Rlm / STD A/Rlm or
 Tyre Size: F: 245/50R19
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli

Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 20/11/19 D.O.I. 26/11/19

Survey held at Performance Motors
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/1/20 MV-179K
Finalize \$14,364.30, 11 days (M/Tob)
(\$ 1,743.00 - Red - 11%)

20/1/2020

RECEIVED 21 JAN 2020

Date/Time, File Pass to?

21/01/20

1) Type
 Date/Time, File Return to?

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 1

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S - RS, - SI

) Phone

) Others

TOTAL

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I.: (\$ 14,364.30 p/p)

Summer Lee (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Tuesday, 26 November, 2019 2:33 PM
To: assignments
Subject: FW: OUR REF: SNM19D205572/GBH7514Y/BEN & YOUR REF: SMD4525B - CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SMD4525B.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, November 25, 2019 4:55 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205572/GBH7514Y/BEN & YOUR REF: SMD4525B - CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT

Dear Sirs,

We are agreeable to use a common surveyor below as the SJE.

5. XING QUO QIANG

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Ben Tang <Ben.Tang@sg.cntaiping.com>

Sent: Monday, 25 November 2019 4:24 PM

To: PBSP <pml-pbsp@simedarby.com.sg>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D205572/GBH7514Y/BEN & YOUR REF: SMD4525B - CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of 25.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

Without admission of liability, please provide our surveyor with repair estimates to facilitate direct settlement.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, November 25, 2019 3:47 PM

To: Ben Tang <Ben.Tang@sg.cntaiping.com>; PBSP <pml-pbsp@simedarby.com.sg>

Subject: OUR REF: SNM19D205572/GBH7514Y/BEN & YOUR REF: SMD4525B - CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT

Dear Ben,

Please conduct PRS-SMD4525B –soonest possible.

File with officer-in-charge –Ben Tang- DID 6389 6175

Dear Caroline,

**** kindly quote our reference number when replying ****

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

TEL: (65) 63896116 - F: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Monday, November 25, 2019 12:50 PM

To: Claims Dept of CTI

Subject: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SMD4525B & GBH7514Y ON 20/11/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2019 14:12
Date Of Accident	20/11/2019 17:50
Exact Location Of Accident	YISHUN AVE 2 (BEFORE YISHUN RING RD JUNCTION)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD4525B
Insured/Policyholder	
Name Of Registered Owner	GAETAU LOUIS JANKOWSKI
Passport No/FIN	G5621272N
Email Address	RUNCE3178@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91501842
Alternative Phone No	OFFICE-84181736

Vehicle Particulars

Manufacturer	BMW
Model	X3
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VAI/GA393155
Cover Note Number	

Driver

Name of Driver	HAIRUNNISA BINTE HUSSAIN
NRIC No	S8616386A
Date Of Birth	06/06/1986
Occupation	INDOOR
Date Of Driving Pass	17/11/2014
Driving Experience	5 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84181736
Fax Number	
Contact Number	
Email Address	RUNCE3178@YAHOO.COM.SG

Address	134 SPRINGLEAF AVE
Postcode	786363
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHARLOTTE IMAN JANKOWSKI GENDER: : FEMALE
Passenger 2	NAME: : RISMA XULI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH7514Y
Vehicle Make/Model/Colour	TOYOTA DYNA WHITE
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	SELVARAJ KARTHICK
NRIC/Passport Number	G2428626L
Contact Number	83066657
Address	
Postcode	

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

1

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21 Nov 2019
1320

Reporting Centre Personnel's Signature
Name: Indran A/L. Indrasen
NRIC/FIN No.: Performance Motors Limited
303 Alexandra Road
Some Darby Performance Centre
Singapore 159941

Signature of the Insurer's Representative

Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20 NOV 2018 at 1748, I am - Halunura Janikowski, was the driver of vehicle, SMD4525B, with 2 passengers on board, Annammy, my daughter, Charlotte Maria Janikowski, and helper, Kichu Yuli. I was travelling around Yichun Avenue 2 towards Lenter Avenue, just before Yichun Ring Road Junction, when vehicle, GBT7514Y, driven by Selvakrishnan Karthick collided into my rear end. It was raining and the road conditions was wet. After the collision, both vehicles were not being moved. Pictures were taken and particulars exchanged. There were no injury crime. Video recording from car dash cam was also available.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 21 Nov 2019
13:30

Reporting Centre Personnel Signature: inthan M. Thiraseemy
 Name: Performance Mobils Limited
 NRIC/FIN No.: 303 155941
Singapore 159941

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	272N
Vehicle Details	
Vehicle No.:	SMD4525B
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X3 SDRIVE20I
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	F1941984B48B20A
Chassis No.:	WBATR12070LC94288
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,483.00
Original Registration Date:	20 Aug 2018
First Registration Date:	20 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$50,077.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Aug 2028
PARF Rebate Amount:	\$37,557.00
Intended COE Rebate Details	
COE Expiry Date:	19 Aug 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,420.00
COE Rebate Amount:	\$29,179.00
Total Rebate Amount:	\$66,736.00

The information contained herein is correct as at 26 Nov 2019

OK

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Car In

GST REG. NO : M2 - 0020081 - X

25 NOV 2019

E S T I M A T E

Estimate No. : b1 53560
Date Estimated : 25/11/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Jankowski Gaetan Louis
134 Springleaf Ave

Singapore 786363

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD4525B	WBATR12070LC94288	20/08/2018	X3 sDrive20i	0

DESCRIPTION

To replace rear bumper, tailgate and attachments. 850

Painting rear bumper and tailgate.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

To replace bootlid smart opener control unit, top and bottom sensor lines including program and conduct checks for proper function. 562

To remove and install rear windscreen glass to facilitate the repair job.

To conduct water leak tests.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To carry out body cavity preservation. (Per panel).

Sundries.

VALUE

2,550.00

2,006.00

177.00

177.00

661.00

574.00

75.00

531.00

80.00

150.00

Total Labour 1: 6,981.00

DESCRIPTION

RUBBER MOUNTING

CLAMPING BUSH

REAR SILENCER LH BRACKET

SWING SUPPORT

QTY

2 45.50

1 60.60

21 38.15

1 44.00

VALUE

91.00

60.60

76.30

44.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



305, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53560
Date Estimated : 25/11/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD4525B	WBATR12070LC94288	20/08/2018	X3 sDrive20i	0

DESCRIPTION	QTY	PRIC	VALUE
REAR SILENCER ? / BT	1	1,257.55	1,257.55
TRUNK LID / BT	1	1,973.35	1,973.35
REAR BUMPER CARRIER ? / BT	1	743.50	743.50
LH SIDE GUIDE FOR BUMPER ? / BT	1	58.25	58.25
RH SIDE GUIDE FOR BUMPER ? / BT	1	58.25	58.25
REAR BUMPER BOTTOM REINFORCEMENT ? / BT	1	78.85	78.85
REAR UNDERRIDE GUARD (X LINE) ? / BT	1	227.90	227.90
REAR BUMPER PANEL PRIMED (X LINE PM) ? / BT	1	1,555.40	1,555.40
REAR BUMPER CLADDING (PDC) ? / BT	1	608.05	608.05
REAR BUMPER TOWING EYE COVER ? / BT	1	47.85	47.85
EMBLEM GROMMET ? / BT	2	0.85	1.70
LETTERING X3 ? / BT	1	64.45	64.45
PLAQUE 82MM ? / BT	1	71.60	71.60
Velcro ? / BT	2	2.60	5.20
REAR SILENCER HEAT INSULATION ? / BT	1	70.75	70.75
SET MOUNTING PDC/PMA SENSOR REAR ? / BT	1	69.35	69.35
SENSOR WIRE FOR SMART OPENER TOP ? / BT	1	43.15	43.15
SENSOR WIRE FOR SMART OPENER BOTTOM ? / BT	1	41.50	41.50
ULTRASONIC SENSOR BLACK ? / BT	2	249.95	499.90
DECOUPLING RING PDC TORQUE CONVERTER ? / BT	4	5.10	20.40
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) ? / BT	2	131.55	263.10

Total Parts : 8,031.95

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Labour 1	:	6,981.00
Parts	:	8,031.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,050.91
Grand Total	:	16,063.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53560**
Date Estimated : **25/11/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Jankowski Gaetan Louis
134 Springleaf Ave

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 786363

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD4525B	WBATR12070LC94288	20/08/2018	X3 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace rear bumper and attachments, bootlid and attachments, both rear LH/RH light in trunk lid including make good the tail end panel and knock out dented area caused by the accident.	2,150.00		2,150.00
* To respray rear bumper, bootlid and tail end panel.	2,547.00		2,547.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.	150.00		150.00
To remove and install rear windscreen glass to facilitate repairs.	574.00		574.00
To conduct water leak tests.	75.00		75.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	451.00		451.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
Sundries.	150.00		150.00

6347

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
① # EXPANDING NUT / MC	2.85	2.00		5.70 ✓
② # BLIND RIVET NUT M6 / MC	2.70	4.00		10.80 ✓
③ CLAMPING BUSH / BR MC	60.60	1.00		60.60 ✓
④ REAR SILENCER LH BRACKET / BR	38.15	1.00		38.15 ✓
⑤ # TAILPIPE TRIM CHROME D=90MM / 00	122.20	1.00		122.20 ✓
⑥ REAR SILENCER	1,257.55	1.00		1,257.55 ✓
⑦ TRUNK LID	1,973.35	1.00		1,973.35 ✓
⑧ REAR BUMPER CARRIER	743.50	1.00		743.50 ✓
⑨ LH SIDE GUIDE FOR BUMPER	58.25	1.00		58.25 ✓
⑩ RH SIDE GUIDE FOR BUMPER	58.25	1.00		58.25 ✓
⑪ REAR BUMPER BOTTOM REINFORCEMENT	78.85	1.00		78.85 ✓
⑫ REAR UNDERRIDE GUARD (X LINE)	227.90	1.00		227.90 ✓

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

13	REAR BUMPER PANEL PRIMED (X LINE PM	1,555.40	1.00	1,555.40 ✓
14	REAR BUMPER CLADDING (PDC)	608.05	1.00	608.05 ✓
15	# BOOT LID/TAILGATE PUSH BUTTON (RFK) / <i>GR</i>	48.65	1.00	48.65 ✓
16	# BUMP STOP / <i>MC</i>	3.75	10.00	37.50 ✓
17	# REAR LH LIGHT IN THE TRUNK LID / <i>GR</i>	407.75	1.00	407.75 ✓
18	# REAR RH LIGHT IN THE TRUNK LID / <i>GR</i>	407.75	1.00	407.75 ✓
19	# (DG) CLEANER R1 (100ML) / <i>MC</i>	26.15	1.00	26.15 ✓
20	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) / <i>MC</i>	131.55	2.00	263.10 ✓
21	# (DG/SL) GLASS PRIMER 30ML (VP206) / <i>MC</i>	27.85	1.00	27.85 ✓

SUPPLEMENTARY ITEMS

Total Labour :	6,347.00 ✓
Total Parts :	8,017.30 ✓
Total Labour & Parts :	14,364.30
Deduction for Excess :	0.00
Total Repair Costs less Excess:	14,364.30
GST @7%:	1,005.50
Grand Total :	15,369.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53560**
Date Estimated : **25/11/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Jankowski Gaetan Louis
134 Springleaf Ave

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 786363

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD4525B	WBATR12070LC94288	20/08/2018	X3 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT	2.85	2.00		5.70 ✓ nec
# BLIND RIVET NUT M6	2.70	4.00		10.80 ✓ nec
# TAILPIPE TRIM CHROME D=90MM	122.20	1.00		122.20 ✓ DG
# BOOT LID/TAILGATE PUSH BUTTON (RFK)	48.65	1.00		48.65 ✓ Br
# BUMP STOP	3.75	10.00		37.50 ✓ nec
# REAR LH LIGHT IN THE TRUNK LID	407.75	1.00		407.75 ✓ Br
# REAR RH LIGHT IN THE TRUNK LID	407.75	1.00		407.75 ✓ Br
# (DG) CLEANER R1 (100ML)	26.15	1.00		26.15 ✓ nec
# (DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85 ✓ nec

Supp

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	1,094.35
Total Labour & Parts :	1,094.35

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Nov 2019		21 Jan 2020 10:20 Edit Adj Rpt	S\$14,364.30 Edit Estimates	S\$14,364.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	GAETAU LOUIS JANKOWSKI		
Vehicle Reg. No.:	SMD4525B	Date of Loss:	20/11/2019 17:00 - :59 [15 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205572	Policy/Cover Note No.:	DMCVSN18287119011
Vehicle Reg. No. (Insured):	GBH7514Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 31/01/2020]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMD4525B (SNM19D205572)**
[GBH7514Y]

TP

GAETAU LOUIS JANKOWSKI





























Nov 20 2019 5:00PM



[-]

Performance Motors Limited

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
2	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
3	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
5	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
6	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
15	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
31	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/01/20 10:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	21/01/20 10:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	21/01/20 10:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

Reset
Save
Print

There are no document checklists configured.

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19020901/ESF3S2

Date: 05/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18287119011
Claimant Vehicle No :	SMD4525B	Insured Vehicle No :	GBH7514Y
Date of Loss:	20/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205572

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD4525B	Engine No:	F1941984B48B20A
Make & Model:	BMW X3, 2.0 I SDRIVE (A)	Chassis No:	WBATR12070LC94288
Reg. Date:	20/08/2018 (Man. Year: 2018)	Odometer:	26625 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,276.30	8,167.30	1,109.00	11.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,831.00	6,197.00	634.00	9.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,107.30	14,364.30	1,743.00	10.82
+ GST 7.00/7.00% (S\$)	1,127.51	1,005.50	122.01	10.82
Nett Amount (S\$)	17,234.81	15,369.80	1,865.01	10.82

INSPECTION

Date of Assignment:	21/01/2020	
Date Inspected:	26/11/2019 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	11.0 days	

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2020)
Parts:	M1-SUV	BMW X3 2.0 I SDRIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD4525B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*RUBBER MOUNTING	Not Necessary	91.00 FS	*- FS
2	1		*CLAMPING BUSH	Necessary	60.60 FS	*60.60 FS
3	1		*REAR SILENCER LH BRACKET	Broken 1pc Only	76.30 FS	*38.15 FS
4	1		*SWING SUPPORT	Not Necessary	44.00 FS	*- FS
5	1		*REAR SILENCER	Bent	1,257.55 FS	*1,257.55 FS
6	1		*TRUNK LID	Dented	1,973.35 FS	*1,973.35 FS
7	1		*REAR BUMPER CARRIER	Bent	743.50 FS	*743.50 FS
8	1		*LH SIDE GUIDE FOR BUMPER	Broken	58.25 FS	*58.25 FS
9	1		*RH SIDE GUIDE FOR BUMPER	Broken	58.25 FS	*58.25 FS
10	1		*REAR BUMPER BOTTOM REINFORCEMENT	Broken	78.85 FS	*78.85 FS
11	1		*REAR UNDERRIDE GUARD (X LINE)	Broken	227.90 FS	*227.90 FS
12	1		*REAR BUMPER PANEL PRIMED (X LINE PM)	Broken	1,555.40 FS	*1,555.40 FS
13	1		*REAR BUMPER CLADDING (PDC)	Broken	608.05 FS	*608.05 FS
14	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	47.85 FS	*- FS
15	2		*EMBLEM GROMMET	Not Necessary	1.70 FS	*- FS
16	1		*LETTERING X3	Not Necessary	64.45 FS	*- FS
17	1		*PLAQUE 82MM	Not Necessary	71.60 FS	*- FS
18	2		*VELCRO	Not Necessary	5.20 FS	*- FS
19	1		*REAR SILENCER HEAT INSULATION	Not Necessary	70.75 FS	*- FS
20	1		*SET MOUNTING PDC/PMA SENSOR REAR	Not Necessary	69.35 FS	*- FS
21	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	43.15 FS	*- FS
22	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	41.50 FS	*- FS
23	2		*ULTRASONIC SENSOR BLACK	Not Necessary	499.90 FS	*- FS
24	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.40 FS	*- FS
25	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
26	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
27	2		*EXPANDING NUT	Necessary	5.70 FS	*5.70 FS
28	4		*BLIND RIVET NUT M6	Necessary	10.80 FS	*10.80 FS
29	1		*TAILPIPE TRIM CHROME D=90MM	Dented	122.20 FS	*122.20 FS
30	1		*BOOTLID / TAILGATE PUSH BUTTON (RFK)	Broken	48.65 FS	*48.65 FS
31	10		*BUMP STOP	Necessary	37.50 FS	*37.50 FS
32	1		*REAR LH LIGHT IN THE TRUNK LID	Broken	407.75 FS	*407.75 FS
33	1		*REAR RH LIGHT IN THE TRUNK LID	Broken	407.75 FS	*407.75 FS
34	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
35	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
Total Parts (\$\$)					9,276.30	8,167.30

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, TAILGATE AND ATTACHMENTS.	New	2,550.00	2,150.00
2	PAINTING REAR BUMPER AND TAILGATE.	New	2,006.00	2,547.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	New	177.00	150.00
5	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT, TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	661.00	0.00
6	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR JOB.	New	574.00	574.00
7	TO CONDUCT WATER LEAK TEST.	New	75.00	75.00
8	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
9	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	80.00	100.00
Gross Labour Cost (\$\$)			6,831.00	6,197.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >