

Not Authenticated

Main

3 days

3.11.20

Page No. 1

L/S \$3400

To be kept after repair

VEHICLE NO. SKD 24175

VW PASSAT CC

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front Bumper 1579.77	DD/pe	1680.00	X
2	Front Bumper Side Retainer @\$77	11	154.00	X
1	Front bumper reinforcement	11	598.00	X
1	Front Bumper foam 116.42	Torn	185.00	X
1	Front Bumper lower grille	11	310.00	X
2	Front Bumper daylight lamps @272.50	11	545.00	X
2	Front fog lamp @492.00	11	984.00	X
2	Front fog lamp cover @142.00	11	284.00	X
1	Front support panel complete	11	780.00	X
1	Front support panel top cover	CFA	298.00	X
1	Front radiator grille	Cru	372.00	X
1	Front radiator grille chrome	Cru	480.00	X
1	RHS Front fender	11	982.00	X
1	RHS Front fender inner shield	11	232.00	X
1	RHS Front door	REPAIR 11	0.00	X
2	RHS & LHS Headlamp @\$1450 988	o/s cno	2900.00	IPC
2	RHS & LHS headlamp lower panel @210.00	11	420.00	X
2	RHS & LHS Headlamp top panel @172.00	11	344.00	X
1	Bonnet	11	1798.00	X
1	Bonnet damper	REUSE 11	0.00	X
1	Bonnet lock	11	245.00	X
			13591.00	
less 10%			1359.10	10%
			12231.90	
SPECIAL NETT ITEMS				
1set	Front bumper clips	11	60.00	50
1set	Front PDC sensor	11	480.00	X
1set	Front support panel top cover clips	11	60.00	X
1set	RHS Front fender shield clips	11	60.00	X
1	Front number plate w/holder	311	75.00	40
1	Front number plate garnish	Torn	90.00	60
1	Front grille VW badge	11	132.00	X
TOTAL PARTS			13188.90	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO. SKD 2417S VW PASSAT CC

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts & components	1200.00 —	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired (front door)	1000.00 —	300
3	To remove and refix wiring at damaged areas and focus headlamp beam	120.00 —	20
4	To remove and replace front PDC sensors and check for proper function	120.00 —	40
5	To clear fault code with diagnostic computer and reset to specification	300.00 —	11x
6	To perform anti rust treatment on affected areas	120.00 —	11x
	Labour Total :	2860.00	
	TOTAL (PARTS & LABOUR):	16048.90	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

P-3834.19
 10%
 P-3450.77
 S.N-150.00
 L-660.00
 4260.77
 202
 3408