

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19020924/GPA3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GBH8075R	Insured Vehicle No :	SHC8641L
Date of Loss: 17/08/2019	Nature of Claim: TP	Claim No: MCT19080882

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH8075R		
Make & Model:	NISSAN NV350, 2.5 (A)	Engine No:	YD25425673A
Reg. Date:	01/10/2018 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0009136
Colour:	White/Blue	Odometer:	36457 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,155.18	195.00	1,960.18	90.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	600.00	1,050.00	63.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,805.18	795.00	3,010.18	79.11
+ GST 7.00/7.00% (\$\$)	266.36	55.65	210.71	79.11
Nett Amount (\$\$)	4,071.54	850.65	3,220.89	79.11
+ Loss of Use (3.0 x S\$90.00/day) (\$\$)		270.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,128.10		

INSPECTION

Date of Assignment:	26/11/2019	
Date Inspected:	02/12/2019 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Jul 2020)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH8075R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	578.90 FN	*- FN
2	1		*FRONT DOOR LH	Repair	1,071.40 FN	*- FN
3	1		*FRONT STEP GARNISH LH	Repair	49.90 FN	*- FN
4	1		*COMPANY STICKER	Necessary	600.00 FS	*180.00 FS
5	1		*LH FRONT DOOR STICKER	Necessary	25.00 FS	*15.00 FS
					Sub Total (\$\$)	2,325.20
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	170.02
					Total Parts (\$\$)	2,155.18
						195.00

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOFR PANEL BEATING	New	800.00	200.00
2	LABOUR FOR SPRAYPAINTING	New	800.00	400.00
3	WIRING	New	50.00	0.00
Gross Labour Cost (\$\$)			1,650.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >