


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 12:08

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014976 Date: 10/03/2020 Order: SMF2645R Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SMF2645R (V 39472) Regn Date: 31/10/2018 Mileage: 16715 WIP No.: 20360

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF41JA231770 Engine: CVK 068771 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-550.00	1.00	-550.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE RHS FRONT DOOR PANEL TRIM. O REMOVE AND REINSTALL RHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0807065D GRU	(SK) COVER Less 020%	1.00	1999.00	1,599.20
X	A8W0807284	GUIDE Less 020%	1.00	33.90	27.12
X	A8W0821106A	FENDER Less 020%	1.00	699.50	559.60
X	A8W0821092	PLATE AP Less 020%	1.00	45.00	36.00
X	AN 0161857	POP-RIVET Less 020%	6.00	3.00	14.40
X	A8W0821136C	SUPPORT AP Less 020%	1.00	107.00	85.60
X	A8W0821172A	WHEEL HOUS AP Less 020%	1.00	219.50	175.60
X	A8W0853888L	SPOILER AP Less 020%	1.00	65.40	52.32
X	A8W0853824B 9B9	STONEGUARD Less 020%	1.00	45.80	36.64
X	A8W0823746	COVER Less 020%	1.00	20.20	16.16
X	A8W0820582C	COVER Less 020%	1.00	27.80	22.24
X	A8W0941774A	(SK) HEADLIGHT Less 020%	1.00	7087.00	5,669.60

Parts 8,294.48
Labour 0.00
Sublet 3,872.00
Menus 0.00
Lubricant 0.00

Sub-Total 11,616.48

7% GST 813.15

Grand Total 12,429.63



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMK 26 45 R

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1396/2019/KS
20 Dec 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF41JA231770
Vehicle Regn No. : **SMF 2645 R**
Vehicle Mileage : 16715 KM
Vehicle Owner : Mr. Choo Chuen Sin
Certificate No : 1800130211-01
Own Damage Excess : \$ 588.50 (Inclusive GST)
Accident Date : 21/11/2019
Place : Orchard Road
Repair Cost : S\$ 12429.63
WIP No. : 20360
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

21/12/19