



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19020929/Hba3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 28-08-2020



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                      |                       |            |
|---------------------|----------------------|-----------------------|------------|
| <b>Insured Veh.</b> | SJX 6972K            | <b>Veh. Inspected</b> | YP 8062M   |
| <b>Policy No.</b>   | Z19VP05023788        | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | 19/19/19/VP05/022692 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | ONG LI LI            | <b>Assign Date</b>    | 26/11/2019 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |            |
|-------------------------|-------------------|---------------------|------------|
| <b>Make &amp; Model</b> | MITSUBISHI CANTER | <b>c.c</b>          | 2998       |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2017       |
| <b>Chassis No.</b>      | FEB50543005       | <b>Colour</b>       | ORANGE     |
| <b>Odometer</b>         | 53736             | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | FAIR              |                     |            |

### 3. Conditions of Tyres

|                       |                |             |                |
|-----------------------|----------------|-------------|----------------|
|                       | <b>Size</b>    | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 205/75 R16     | BRIDGESTONE | 5 mm           |
| <b>L/H Front Tyre</b> | 205/75 R16     | BRIDGESTONE | 5 mm           |
| <b>R/H Rear Tyre</b>  | 205/75 R16 (D) | BRIDGESTONE | 5/5 mm         |
| <b>L/H Rear Tyre</b>  | 205/75 R16 (D) | BRIDGESTONE | 5/5 mm         |

### 4. Description of Damages

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

### 5. General Information

|                       |   |                        |            |
|-----------------------|---|------------------------|------------|
| <b>Accident Date</b>  | 25/11/2019  | <b>Inspection Date</b> | 27/11/2019 |
| <b>Survey held at</b> | THINK ONE AUTOCARE PTE LTD<br>NO.18 DEFU AVENUE 2<br>SINGAPORE 539522 |                        |            |

### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>8 Working Days</b> |
|-------------------------------------|-----------------------|