

AFORTDELGRO ENGINEERING PTE LTD

DATE: AIR ESTIMATE*

VEHICLE NO : SHD3037J
 MAKE : HYUNDAI
 MODEL : i40

DATE: 26. Nov. 2019

DOA: 22. Nov. 2019

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover x (R)			\$1,052.20
1	Front Bumper Side Bracket - RH xun			\$24.60
1	Front Bumper Top Bracket - RH xun			\$22.40
10	Front Bumper Clips xun		\$2.20	\$22.00
1	Front Bumper Grille - RH xun			\$41.60
1	Headlamp - RH cra			\$1,388.00
1	Headlamp Support Panel xun			\$907.40
1	Front Fender - RH x (R)			\$566.30
SUB TOTAL				\$4,024.50
LESS 20%				\$804.90
DISCOUNTED TOTAL				\$3,219.60
1 Advertisement - RHF Fender ✓ nec				\$100.00
				Nett
				\$100.00
Labour Charge				
1	Panel Beating		\$480	\$500.00
1	Spray Painting Charge		\$400	\$500.00
1	Tuff Kote		xun	\$50.00
1	Wiring Charge			\$50.00
TOTAL LABOUR				\$1,100.00
ESTIMATE TOTAL				\$4,419.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Ram (LKR)
 26/11/19 1330V5Xun
 Ram@lkkauto.com
 88622720
 aft repair photo
 45
 3 repair days
 45: \$1650/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.