



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

BIZLINK RENT-A-CAR PTE LTD

25/11/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP FWD.

Xiao Tong

Accident date: 25/11/2019

Estimated repair cost for vehicle no: SJV9778X MITSUBISHI LANCER 1.6 A '10

CHASSIS: JMYSTCS3A9U006110

S/n	Qty	Items / Nett	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$587.00 ✓
2	2	Rear Boot Lid Hinge <i>XH m</i>	\$69.00	\$138.00 ✓
3	1	Rear Boot Lid Emblem Logo		\$51.00 ✓
4	1	Rear Boot Lid Lancer Logo		\$46.00 ✓
5	1	Rear Boot Lid GLX Logo		\$42.00 ✓
6	1	Rear Boot Lid C&C Logo		\$55.00 ✓
7	1	Rear Boot Lid Number Plate <i>3 m</i>		\$50.00 ✓
8	2	Rear Boot Lid Number Plate Lamp <i>2 m</i>	\$42.90	\$85.80 ✓
9	1	Rear Boot Lid Center Garnish <i>HE m</i>		\$197.00 ✓
10	1	Rear Boot Lid Inner Lock <i>Dented</i>		\$125.00 ✓
11	1	Rear Boot Lid Inner Rubber <i>W</i>		\$158.00 ✓
12	2	Rear Tail Lamp <i>crushed</i>	\$436.00	\$872.00 688
13	4	Rear Tail Lamp Clip <i>m</i>	\$8.00	\$32.00 ✓
14	2	Rear Tail Lamp Panel <i>Repair</i>	\$109.00	\$218.00 ✓
15	1	Rear Bumper <i>Deformed</i>		\$674.00 ✓
16	8	Rear Bumper Clip <i>m</i>	\$6.50	\$52.00 30
17	2	Rear Bumper Side Retainer <i>m</i>	\$41.00	\$82.00 ✓
18	12	Rear Bumper Side Retainer Rivet <i>m</i>	\$3.50	\$42.00 20
21	1	Rear Bumper Centre Beam <i>Best</i>		\$188.00 ✓
22	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$350.00 200/cw
23	1	Rear End Panel - <i>Dented</i>		\$398.00 ✓
24	1	Rear End Panel Top Garnish <i>Deformed</i>		\$141.00 ✓
25	6	Rear End Panel Top Garnish Clip <i>m</i>	\$6.50	\$39.00 10
28	2	Rear Fender Inner Trim Board <i>3 m</i>	\$232.00	\$464.00 ✓
29	16	Rear Fender Inner Trim Board Clip <i>3 m</i>	\$6.50	\$104.00 ✓

3327

Subtotal :- \$5,190.80

2994.30 S.N : 200

Labour charges

To remove & refit cushion & trim board	\$280.00 60
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 X
To remove & refit rear windscreen	\$120.00 X
Gum	\$50.00 X
To check wiring	\$60.00 30
Tuff kote	1800 \$150.00 60
Towing fee	\$120.00 X
Panel beating	\$1,400.00 800
Spray painting	\$1,400.00 800

Subtotal :- \$4,060.00

Total:- \$9,250.80

Total: 4994.30.
h/s: 3/K (Nett Value)
06 Days
3/K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____