



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJX 3260 B
HONDA CIVIC

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT GRILLE	1	
2	FRONT GRILLE CHROME	1	
3	FRONT LOGO (HONDA)	1	
4	HEADLAMP (L+R)	2	
5	HEADLAMP BRACKET (L+R)	2	
6	FRONT BUMPER	1	
7	FRONT BUMPER RETAINER (L+R)	2	
8	FRONT BUMPER REINFORCEMENT BAR	1	
9	FRONT BUMPER BRACKET (L+R)	2	
10	FRONT BUMPER BEAM	1	
11	FRONT BUMPER SPONGE	1	
12	FRONT BUMPER GRILLE	1	
13	FRONT BUMPER FOG LAMP (L+R)	2	
14	FRONT BUMPER FOG LAMP GARNISH (L+R)	2	
15	FRONT BUMPER UNDERCOVER	1	
16	FRONT FENDER (RH)	1	
17	FRONT FENDER QUARTER WINDOW MOULDING (RH)	1	
18	FRONT FENDER QUARTER WINDOW GARNISH (RH)	1	
19	FRONT FENDER INNER PANEL (RH)	1	
20	FRONT FENDER COWLING (RH)	1	
21	FRONT FENDER MUDFLAP (RH)	1	
22	FRONT SUPPORT PANEL	1	
23	FRONT SUPPORT PANEL TOP GARNISH	1	
24	WIPER WASHER TANK	1	
25	WIPER WASHER MOTOR	1	
26	FRONT DOOR (L+R)	2	
27	FRONT DOOR SIDE MIRROR ASSY (RH)	1	
28	FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH)	1	
29	FRONT DOOR LOCK CYLINDER (RH)	1	
30	FRONT DOOR WINDOW MOULDING (RH)	1	
31	FRONT DOOR SIDE PROTECTOR (RH)	1	
32	FRONT DOOR SIDE PROTECTOR CHROME STRIP (RH)	1	
33	FRONT DOOR LOCK (RH)	1	
34	FRONT DOOR LOCK CATCH (RH)	1	
35	FRONT DOOR INNER BOARD (RH)	1	
36	FRONT DOOR INNER BOARD SWITCH (RH)	1	
37	FRONT DOOR POWER WINDOW MOTOR (RH)	1	
38	FRONT DOOR WINDOW REGULATOR (RH)	1	
39	FRONT DOOR HINGE (UPPER & LOWER) (RH)	2	
40	FRONT DOOR CHECKER (RH)	1	

*not consistent
Nanyang*

41	FRONT DOOR WEATHERSTRIP (RH)		1	) not consistent Damage
42	FRONT DOOR INNER WEATHERSTRIP (RH)		1	
43	ROCKER PANEL (L+R)	L/H only ✓ (cut) R/H X (svc)	21	
44	ROCKER PANEL GARNISH (L+R)	L/H only ? - per. R/H X (svc)	21	
45	REAR WINDSCREEN SEALANT	✓ new	1	
46	BOOTLID		1	
47	BOOTLID LOGO (HONDA)		1	
48	BOOTLID EMBLEM (CIVIC)		1	
49	BOOTLID EMBLEM		1	
50	BOOTLID LAMP (L+R)		2	
51	BOOTLID HANDLE		1	
52	BOOTLID LOCK CYLINDER		1	
53	BOOTLID CARPLATE LAMP (L+R)	X (not consistent Damage)	2	
54	BOOTLID INNER TRIM		1	
55	BOOTLID LOCK		1	
56	BOOTLID LOCK COVER		1	
57	BOOTLID LOCK CATCH		1	
58	BOOTLID HINGE (L+R)		2	
59	BOOTLID HINGE COVER (L+R)		2	
60	BOOTLID STOPPER BIG (L+R)		2	
61	BOOTLID STOPPER SMALL (L+R)		2	
62	BOOTLID WEATHERSTRIP		1	
63	TAIL LAMP (LH)	X (svc)	1	
64	TAIL LAMP PANEL (LH)	X (svc)	1	
65	REAR BUMPER	✓ CRU	1	
66	REAR BUMPER RETAINER (L+R)	✓ L/H only (new) R/H X (svc)	12	
67	REAR BUMPER REINFORCEMENT BAR	X (svc)	1	
68	REAR BUMPER BRACKET (L+R)	X SVC	2	
69	REAR BUMPER BEAM	X SVC	1	
70	REAR BUMPER SPONGE	X SVC	1	
71	REAR BUMPER UNDERCOVER	X SVC	1	
72	REAR FENDER (LH)	✓ cut	1	
73	REAR FENDER INNER PANEL (LH)	X (R)	1	
74	REAR FENDER INNER TRIM (LH)	X (svc)	1	
75	REAR FENDER PETROL COVER (LH)	X (svc)	1	
76	REAR FENDER COWLING (LH)	? - per	1	
77	REAR FENDER MUDFLAP (LH)	✓ (CRU)	1	
78	C PILLAR LOWER (LH)	X	1	
79	REAR DOOR (LH)	✓ BT	1	
80	REAR DOOR WINDOW MOULDING (LH)		1	
81	REAR DOOR SIDE PROTECTOR (LH)		1	
82	REAR DOOR SIDE PROTECTOR CHROME STRIP (LH)		1	
83	REAR DOOR LOCK (LH)	✓ JM	1	
84	REAR DOOR LOCK CATCH (LH)	X SVC	1	
85	REAR DOOR INNER BOARD (LH)	X SVC	1	
86	REAR DOOR INNER BOARD SWITCH (LH)	X SVC	1	
87	REAR DOOR POWER WINDOW MOTOR (LH)	? - per	1	
88	REAR DOOR REGULATOR (LH)	? - per	1	

89	REAR DOOR HINGE (UPPER & LOWER) (LH)	X (sve)	2	
90	REAR DOOR CHECKER (LH)	X (sve)	1	
91	REAR DOOR WEATHERSTRIP (LH)	✓ new	1	
92	REAR DOOR INNER WEATHERSTRIP (LH)	✓ new	1	
93	FRONT ABSORBER (RH)		1	
94	FRONT LOWER ARM (RH)		1	
95	FRONT KNUCKLE (RH)		1	
96	FRONT KNUCKLE BEARING (RH)		1	
97	FRONT BEARING HUB (RH)		1	
98	FRONT CROSSMEMBER		1	
99	FRONT STEERING RACK AND PINION ASSY		1	
100	FRONT DRIVE SHAFT (RH)		1	
101	FRONT TIE ROD (RH)		1	
102	FRONT TIE ROD END (RH)		1	
103	FRONT STABILIZER BAR		1	
104	FRONT STABILIZER LINK (RH)		1	
105	REAR ABSORBER (LH)		1	
106	REAR LOWER ARM (LH)		1	
107	REAR KNUCKLE (LH)		1	
108	REAR KNUCKLE BEARING (LH)		1	
109	REAR BEARING HUB (LH)		1	
110	REAR AXLE	X (sve)	1	

SUBTOTAL

\$ -

LESS 10%

\$ -

PARTS TOTAL

\$ -

SPECIAL NETT			QTY	PRICE
1	BONNET INSULATOR CLIPS		10	\$ 100.00
2	FRONT BUMPER CLIPS		10	\$ 100.00
3	FRONT FENDER INNER PANEL SEALANT		1	\$ 120.00
4	FRONT FENDER QUARTER WINDOW SEALANT		1	\$ 120.00
5	FRONT FENDER COWLING CLIPS		10	\$ 100.00
6	FRONT FENDER MUDFLAP CLIPS		5	\$ 50.00
7	FRONT SUPPORT PANEL TOP GARNISH CLIPS		10	\$ 100.00
8	FRONT DOOR INNER BOARD CLIPS		10	\$ 100.00
9	FRONT DOOR VISOR SET		2	\$ 400.00
10	FRONT DOOR HANDLE CHROME (RH)		1	\$ 800.00
11	FRONT DOOR HANDLE END CAP CHROME (RH)		1	\$ 300.00
12	ROCKER PANEL SEALANT	✓ new	1	\$ 120.00
13	REAR WINDSCREEN MOULDING SEALANT	✓ new	1	\$ 120.00
14	BOOTLID SPOILER	X	1	\$ 2,000.00
15	BOOTLID INNER TRIM CLIPS	X	10	\$ 100.00
16	TAIL LAMP CLIPS (L+R)	L/H only ✓ new R/H X	2	\$ 80.00
17	REAR BUMPER CLIPS	✓ new	10	\$ 100.00
18	REAR BUMPER REVERSE SENSOR SET	X	2	\$ 300.00
19	REAR FENDER SEALANT	✓ new	1	\$ 120.00
20	REAR FENDER INNER TRIM CLIPS	✓ new	10	\$ 100.00
21	REAR FENDER COWLING CLIPS	✓ new	3	\$ 100.00

30

30

10

25

30

20

10

22	REAR FENDER MUDFLAP CLIPS	X (50c)	10	\$ 100.00	
23	C PILLAR SEALANT	X	1	\$ 120.00	
24	REAR DOOR HANDLE (LH)	X	1	\$ 800.00	
25	REAR DOOR HANDLE END CAP (LH)	X	1	\$ 300.00	
26	REAR DOOR INNER BOARD CLIPS	✓ m	10	\$ 100.00	20
SPECIAL NETT TOTAL				\$ 6,850.00	
LABOUR			QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN		1	\$ 6,000.00	1400
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		1	\$ 4,200.00	1000
3	TO RUST PROOF ACCIDENT AFFECTED AREA	X	1	\$ 400.00	
4	TO RNR REAR WINDSCREEN	✓	1	\$ 400.00	100
5	TO RNR REAR BOOT MECHANISM	X	1	\$ 400.00	
6	TO RNR REAR LUGGAGE COMPARTMENT	X	1	\$ 400.00	
7	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	X	1	\$ 400.00	
8	TO RNR DOOR MECHANISM	X	1	\$ 800.00	
9	TO RNR REVERSE SENSOR & CHECK FUNCTION.	✓	1	\$ 120.00	20
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	X	1	\$ 250.00	
11	TO RNR UNDERCARRIAGE SYSTEM	? photo	1	\$ 250.00	150?
12	TO CHECK WHEEL ALIGNMENT	✓	1	\$ 250.00	60
13	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	X	1	\$ 150.00	
14	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	✓	1	\$ 150.00	25
15	TO RNR TYRE AND WHEEL BALANCING	X	1	\$ 250.00	
16	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	✓	1	\$ 400.00	120
17	TO DO WATER LEAK TEST.	✓	1	\$ 80.00	30
18	TO RNR FUEL TANK TO ASSIST WORK LOAD	X	1	\$ 250.00	
TOTAL				\$ 15,150.00	
GRAND TOTAL COST				\$ 22,000.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

L/S upon
9 days

without problem.

Heck Am
85314883

26/11/19
6:30pm

Heck Am @ LKK Auto. com
Resurvey after paint