

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 26/11/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLK7497D

CHASSIS NO : RU31216443

MAKE / MODEL : Honda VEZEL Hybrid 1.5 X Auto

DATE OF ACCIDENT : 24/07/2019

YOUR INSURED: SMQ885U

MILEAGE : 133595 km

PARTS DESCRIPTION

- 1 F/L fender
- 2 F/L fender wheel arch moulding
- 3 Front bumper

QTY	UNIT PRICE	LIST PRICE
1PC	\$780.00	\$780.00
1 PC	\$300.00	\$300.00
1 PC	\$955.00	\$955.00
LIST TOTAL S\$:		\$1,080.00
20.00% DISCOUNT S\$:		\$270.00
		\$810.00

SPECIAL NETT

- 1 Bumper clips
- 2 F/L fender wheel moulding clips

1 SET	\$200.00	X500
2 SET	\$100.00	20
Special Nett Total S\$:	\$200.00	NEC

LABOUR CHARGES

- 1 To labour charge for removing front bumper and F/L fender out to facilitate repairs
- 2 To respray front bumper, F/L fender and F/L fender wheel arc moulding

\$400.00
\$400.00

LABOUR TOTAL S\$:	\$800.00
TOTAL S\$:	\$1,810.00
7% GST	\$126.70
GRAND TOTAL S\$:	\$1,936.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

805
- 20%
P = 644
N = 20
L = 750
1,414
- 20%
1,131.2

Sun Pm (Lkk)
26/11/2019

5.30pm

TP without prejudice

Repair days 3-4 days

Lump Sum Repair

After spray photo

L/S \$1,150
3 days