

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 26/11/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLK7497D

CHASSIS NO : RU31216443

MAKE / MODEL : Honda VEZEL Hybrid 1.5 X Auto

DATE OF ACCIDENT : 24/07/2019

YOUR INSURED: SMQ885U

MILEAGE : 133595 km

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DESCRIPTION

	QTY	UNIT PRICE	LIST PRICE
1 F/L fender	1PC	\$780.00	\$780.00 ✓ DO
2 F/L fender wheel arch moulding	1 PC	\$300.00	\$300.00 ✓ SCR
3 Front bumper	1 PC	\$955.00	\$955.00 XSVU
LIST TOTAL S\$:			\$1,080.00
20.00% DISCOUNT S\$:			\$270.00
			\$810.00

SPECIAL NETT

1 Bumper clips	1 SET	\$200.00 XSVU
2 F/L fender wheel moulding clips	2 SET	\$100.00 ✓ 20
Special Nett Total S\$:		\$200.00

LABOUR CHARGES

1 To labour charge for removing front bumper ad F/L fender out to facilitate repairs	\$400.00 350
2 To respray front bumper, F/L fender and F/L fender wheel arc moulding	\$400.00 ✓

LABOUR TOTAL S\$:	\$800.00
TOTAL S\$:	\$1,810.00
7% GST	\$126.70
GRAND TOTAL S\$:	\$1,936.70

Sun Pm (LKK)

26/11/2019

5.30pm.

TP without prejudice.

Repair days 3-4 days

Lump Sum Repair.

After spray photo.