COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 1841H

MAKE :

26/11/2019 11:18 DSUM

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT		
REAR BUMPER X (M) CVO			\$	458.60	1
REAR BUMPER UNDER COVER CUL			\$	552.60	
REAR BUMPER SIDE RETAINER XXX			\$	112.70	
REAR BUMPER TOWING COVER DEF			\$	82.70	
REAR BUMPER CLIPS hec			\$	22.00	
SUB TOTAL			\$	1,228.60	-
LESS 25%			\$	307.15	
DISCOUNTED TOTAL			\$	921.45	-
				407.70	
REAR BUMPER REVERSE SENSOR XVV			\$	135.70	
REAR BUMPER RUBBER MAT			\$	50.00	1
REAR FENDER ADVERTISEMENT LOGO (LH/RH)	6 (-	\$ 100.00	\$	200.00	NET
6			\$	385.70	
Keinforcement B+]
Reinforcement B+ Bumperside cra					
LABOUR CHARGE					
Panel Beating		9240	\$	350.00	
Spray Painting Charge		4200	\$	250.00	
Wiring Charge			\$	50.00	
Remove/Refix Reverse Sensor		XIII	\$	80.00	
LKK Auto Consultants hence notify the Repairer of the following: TOTAL LABOUR • To resurvey before/after spray painting		Ram (LXXX)	\$	730.00	
To display damaged part(s) during resurvey		Ram (LKK	\$	2,037.15	
Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis		ALLIN		2,007.10	
No illegal modification(s) is allowed		26111	100	5	
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		1 1501	1	DICC	act
Acknowledged by Repairer		2012218	1	(43)	
Signature:		Phromana	M	1405	2
Date:		98622	100	1-1901-	
		111			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.