

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19020949/EPA3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLD6138J	Insured Vehicle No :	SHD3521C
Date of Loss: 22/11/2019	Nature of Claim: TP	Claim No: MCT19110604

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD6138J		
Make & Model:	CITROEN GRAND C4 PICASSO, 1.6 BLUEHDI EAT6 (A)	Engine No:	10JBHD3014084
Reg. Date:	27/01/2016 (Man. Year: 2015)	Chassis No:	VF73ABHZTFJ763816
Colour:	White	Odometer:	78400 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,314.00	1,441.00	1,873.00	56.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,500.00	2,200.00	59.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,014.00	2,941.00	4,073.00	58.07
+ GST 7.00/7.00% (S\$)	490.98	205.87	285.11	58.07
Nett Amount (S\$)	7,504.98	3,146.87	4,358.11	58.07
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		3,467.87		

INSPECTION

Date of Assignment:	26/11/2019	
Date Inspected:	04/12/2019 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Jan 2020)	
Parts:	N/A	CITROEN GRAND C4 PICASSO 1.6 BLUEHDI EAT6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD6138J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*REAR BUMPER	Dented	910.00 FS	*910.00 FS
3	1		*BUMPER BRACKET	Not Necessary	317.00 FS	*- FS
4	1		*BUMPER SKIRT	Cut	331.00 FS	*331.00 FS
5	1		*RECESS DOOR	Not Necessary	53.00 FS	*- FS
6	1		*SET BRACKET	Not Necessary	107.00 FS	*- FS
7	1		*BRACKET SET LAT	Not Necessary	107.00 FS	*- FS
8	1		*BUMPER SEAL	Not Necessary	50.00 FS	*- FS
9	1		*BUMPER BRACKET	Not Necessary	314.00 FS	*- FS
10	1		*ANGLEPLATE	Not Necessary	46.00 FS	*- FS
11	1		*STIFFENER LH	Not Necessary	62.00 FS	*- FS
12	1	6	*STIFFENER RH	Not Necessary	62.00 FS	*- FS
13	1		*LOW RR PAN FIX	Necessary	170.00 FS	*170.00 FS
14	1		*SENSOR SUPPORT	Not Necessary	131.00 FS	*- FS
15	1		*CTR RH SENSOR	Not Necessary	139.00 FS	*- FS
16	1		*CTR LH SENSOR	Not Necessary	139.00 FS	*- FS
17	1		*CORNER RH SENSOR	Not Necessary	163.00 FS	*- FS
18	1		*CORNER LH SENSOR	Not Necessary	163.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,314.00	1,441.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER ,REAR BUMPER REINFORCEMENT ,REPAIR REAR END PANEL	New	1,800.00	600.00
2	REMOVE AND INSTALL PARKING ASSIST	New	120.00	120.00
3	PAINT WORK SPRAY REAR END PANEL ,REAR BUMPER AND AFFECTED PORTION	New	1,260.00	420.00
4	APPLY BODY SEALANT	New	80.00	0.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	60.00	60.00
6	PERFORM RUST PREVENTION	New	80.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	300.00	300.00
Gross Labour Cost (\$\$)			3,700.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >