

ESTIMATE

Invoice Name & Address				Owner Name & Vehicle Info		
Low Chin Heng				Cust No/Name	/Low Chin Heng	
Blk 26 Telok Blangah Crescent				Reg No/Reg Date	SLD6138J / 27/01/2016	
#08-89				Date In/Mileage	/ 0	
Singapore 090026				Chassis No	VF73ABHZTFJ763816	
				Engine No	10JBHD3014084	
				Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT	
Contact No Mobile: 96480261				Colour/Trim	WPP / 8MF	
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00073	Cash	25/11/2019/ 15:20	QUD	247 / DonBong	14942	
Description of Goods / Services				Qty	Unit Price	Disc% Amount
E PNT88000						1800.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, 550 600						120.00 ✓
REAR BUMPER REINFORCEMENT, REPAIR REAR END PANEL						
E PNT88000						1260.00
REMOVE AND INSTALL PARKING ASSIST						
E PNT98000						80.00X
PAINT WORK SPRAY REAR END PANEL, REAR BUMPER AND 4/1						60.00 ✓
AFFECTED PORTION						
M SUNDRY						80.00X
APPLY BODY SEALANT						60.00 ✓
A 54900099						80.00X
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM						300.00 ✓
M SUNDRY						
PERFORM RUST PREVENTION						
A 10028901						50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST						
USING HI-SCAN PRO TEST						
M SUNDRY						
SUNDRIES						
M REAR BUMPER ✓ 00				1.00	910.00	0.00 910.00
M BUMPER BRACKET ?				1.00	317.00	0.00 317.00
M BUMPER SKIRT ✓ CM				1.00	331.00	0.00 331.00
M RECESS DOOR ?				1.00	53.00	0.00 53.00
M BRACKET SET ?				1.00	107.00	0.00 107.00
M BRACKET SET LAT ?				1.00	107.00	0.00 107.00
M BUMPER SEAL ?				1.00	50.00	0.00 50.00
M BUMPER BRACKET ?				1.00	314.00	0.00 314.00
M ANGLEPLATE ?				1.00	46.00	0.00 46.00
M STIFFENER LH ?				1.00	62.00	0.00 62.00
M STIFFENER RH ?				1.00	62.00	0.00 62.00
M LOW RR PAN FIX ?				1.00	170.00	0.00 170.00
M SENSOR SUPPORT ?				1.00	131.00	0.00 131.00
M CTR RH SENSOR ?				1.00	139.00	0.00 139.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Low Chin Heng		Cust No/Name	/Low Chin Heng
Blk 26 Telok Blangah Crescent		Reg No/Reg Date	SLD6138J / 27/01/2016
#08-89		Date In/Mileage	/ 0
Singapore 090026		Chassis No	VF73ABHZTFJ763816
Contact No Mobile: 96480261		Engine No	10JBHD3014084
		Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT
		Colour/Trim	WPP / 8MF

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	25/11/2019/ 15:20	QUD	247 / DonBong	14942			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	CTR LH SENSOR				1.00	139.00	0.00	139.00
M	CORNER RH SENSOR				1.00	163.00	0.00	163.00
M	CORNER LH SENSOR				1.00	163.00	0.00	163.00

Estimate

SURVEYOR NAME: Steve (LKK)
 SURVEYOR SIGNATURE: [Signature]
 DATE: 4/12/19, 10.30 am
 REMARKS: wrt Prejudice, P/P
Ry Def spy
3 days

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by

Parts	3,264.00
Labour	3,540.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	210.00
Total (w/o GST)	7,014.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.