



Exceptional Journeys

Surveyor : Steve - LKK
Company : India
DOA : 22/11/2019
CSE : Don
Date of Survey : 04/12/2019

VEHICLE NO : SLD6138J
MODEL : CIT/ GC4P 1.6 BLUEHDI EAT6
WIP : 14942

Material	:	\$	1,411.00
Labour	:	\$	1,530.00
Sub-Total	:	\$	2,941.00
Less Excess	:	\$	-
Total	:	\$	2,941.00
GST 7%	:	\$	205.87
Grand Total	:	\$	3,146.87
Finalise By/Date	:	JoJo dtd 23/12/2019	

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS + Days () Weekends
+ Days () Public Holiday
+ 1 Survey - 04/12/2019 - Wed
TOTAL DAYS REPAIR TOOK = 4

☒ TP Claim India - SHD3521C

☐ Claim GIA / LTA fee

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE P/L ATTN: MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 Contact No	Cust No/Name /Low Chin Heng Reg No/Reg Date SL06138J / 27/01/2016 Date In/Mileage 19/12/2019/ 78808 Chassis/Package VF73ABHZTFJ763816 /CC17P Engine No 10JBHD3014084 Make/Model CIT/6C4P 1.6 BLUEHDI EAT6 CONFORT Colour/Trim WPP / BMF



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	23/12/2019/ 17:44	TLD	881 / Jojo Cheng	14942	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW DAMAGED PARTS ON REAR BUMPER				✓ 600.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				✓ 120.00
E PNT98000 RESPRAY REAR BUMPER AND AFFECTED PORTION				✓ 420.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 60.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 300.00
M SUNDRY SUNDRIES				✓ 30.00
X REAR BUMPER	1.00	910.00	0.00	✓ 910.00
X BUMPER SKIRT	1.00	331.00	0.00	✓ 331.00
X LOW RR PAN FIX	1.00	170.00	0.00	✓ 170.00
Z TEXT INDIA TP CLAIM SHD3521C DOA: 22/11/2019 SURVEYOR: STEVE LKK 04/12/2019				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	1,411.00	Nett	2,941.00
Labour	1,500.00	7% GST on	205.87
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	3,146.87
Sundry/Others	30.00	Paid	0.00
Total(w/o GST)	2,941.00	Total Due	3,146.87

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

ESTIMATE

Invoice Name & Address				Owner Name & Vehicle Info			
Low Chin Heng				Cust No/Name	/Low Chin Heng		
Blk 26 Telok Blangah Crescent				Reg No/Reg Date	SLD6138J / 27/01/2016		
#08-89				Date In/Mileage	/ 0		
Singapore 090026				Chassis No	VF73ABHZTFJ763816		
Contact No Mobile: 96480261				Engine No	10JBHD3014084		
				Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT		
				Colour/Trim	WPP / 8MF		
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00073	Cash	25/11/2019/ 15:20	QUD	247 / DonBong	14942		
Description of Goods / Services					Qty	Unit Price	Amount
E PNT88000							1800.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, 550 600						600	550
REAR BUMPER REINFORCEMENT, REPAIR REAR END PANEL							120.00 ✓
E PNT88000							
REMOVE AND INSTALL PARKING ASSIST							1260.00
E PNT98000							
PAINT WORK SPRAY REAR END PANEL, REAR BUMPER AND 4/1							80.00 X
AFFECTED PORTION							60.00 ✓
M SUNDRY							
APPLY BODY SEALANT							80.00 X
A 54900099							300.00 ✓
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							
PERFORM RUST PREVENTION							50.00
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							
SUNDRIES							
M REAR BUMPER ✓ DO					1.00	910.00	910.00 ✓
M BUMPER BRACKET ? X NAI					1.00	317.00	317.00
M BUMPER SKIRT ✓ CM					1.00	331.00	331.00 ✓
M RECESS DOOR ? X NAI					1.00	53.00	53.00
M BRACKET SET ? X NAI					1.00	107.00	107.00
M BRACKET SET LAT ? X NAI					1.00	107.00	107.00
M BUMPER SEAL ? X NAI					1.00	50.00	50.00
M BUMPER BRACKET ? X NAI					1.00	314.00	314.00
M ANGLEPLATE ? X NAI					1.00	46.00	46.00
M STIFFENER LH ? X NAI					1.00	62.00	62.00
M STIFFENER RH ? X NAI					1.00	62.00	62.00
M LOW RR PAN FIX ✓ MC					1.00	170.00	170.00 ✓
M SENSOR SUPPORT ? X NAI					1.00	131.00	131.00
M CTR RH SENSOR ? X NAI					1.00	139.00	139.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Low Chin Heng		Cust No/Name	/Low Chin Heng
Blk 26 Telok Blangah Crescent		Reg No/Reg Date	SLD6138J / 27/01/2016
#08-89		Date In/Mileage	/ 0
Singapore 090026		Chassis No	VF73ABHZTFJ763816
Contact No Mobile: 96480261		Engine No	10JBHD3014084
		Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT
		Colour/Trim	WPP / BMF

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	25/11/2019/ 15:20	QUD	247 / DonBong	14942			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M CTR LH SENSOR					1.00	139.00	0.00	139.00
M CORNER RH SENSOR					1.00	163.00	0.00	163.00
M CORNER LH SENSOR					1.00	163.00	0.00	163.00

Estimate

K.A.V. Consultants hence notify
 the Repairer of the following:

- To repair before/after spray painting
- To inspect damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SURVEYOR NAME: Steve (LKK)
 SURVEYOR SIGNATURE: [Signature]
 DATE: 4/12/19, 10.30 am
 REMARKS: W/L Prejudice, P/P
Ry Ref spy
3 days

Confirm & accepted by

Authorized signatory and company stamp

Parts	3,264.00
Labour	3,540.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	210.00
Total(w/o GST)	7,014.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.