



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2003174  
INV Date 15/04/2020  
Reference CC3/CTI19020952/Fda3q2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHB 8437R  
Insured Veh. GBH 8329J  
Claim No. SNM19D205654  
Policy No. DMCVSN1832611901  
Accident Date 25/11/2019  
Inspection Date 25/11/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19020952/Fda3q2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 15-04-2020		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBH 8329J	Veh. Inspected	SHB 8437R	
Policy No.	DMCVSN1832611901	Coverage (\$)	0.00	
Claim No.	SNM19D205654	Excess (\$)	0.00	
Assign From		Assign Date	25/11/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5446551	Colour	SILVER	
Odometer	422901	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	5 mm	
L/H Front Tyre	205/65 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & N/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/11/2019	Inspection Date	25/11/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8437R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	WHEEL COVER	NOT NECESSARY	116.00	-
1	REAR LH FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-11.60	-
			104.40	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	30.00
			110.00	90.00
	<b><u>LABOUR</u></b>			
	TO CHECK REAR N/S WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT, CARPET ,ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK - OUT ,STRAIGHTEN ,REPAIR ,RESHAPE OF THE REAR N/S FENDER ,REAR BUMPER ETC.		550.00	360.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,REAR N/S FENDER .		400.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	30.00
			1,270.00	840.00
	<b>GRAND TOTAL</b>		<b>1,484.40</b>	<b>930.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>930.00</b>

Report Ref No. CC3/CTI19020952/Fda3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 8437R

INSPECTION





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 8437R

RE-INSPECTION

