

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Nov-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA WAGON REGN NO: SHB 8437 R

1 pc	Wheel cover XMM	\$	116.00
	REAR LH FENDER X (R)	Less 10%	\$ 11.60
	REAR bumper X (R)	\$	104.40
S/NETT			
1 pc	Rear n/s fender sticker NEC	\$	60.00
	To check rear n/s wheel alignment XMM	\$	60.00 X
	Sundry	\$	50.00 \$30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 \$50
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear n/s fender, rear bumper etc	\$	550.00 \$360
	To putty and spray painting on the rear bumper, rear n/s fender	\$	400.00 300
	To apply rustproofing on the repaired and replaced panels	\$	80.00 \$30
Total		\$	<u>1,484.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)
25/11/19 1600hrs
W/S after repair photo
3 repair days
ParaSuram @ LKK Auto car
88622778 (hy)