

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6741P

DATE 25/11/2019 9:54

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper X(R)			\$ 553.00	
	Rear Bumper Clip 10 pcs Xnn			\$ 22.00	
	Rear Bumper Under Cover SCR			\$ 228.00	
	SUB TOTAL			\$ 803.00	
	LESS 20%			\$ 160.60	
	DISCOUNTED TOTAL			\$ 642.40	
	Rear Bumper Reverse Sensor Xnn			\$ 135.70	Nett
	Rear Bumper Rubber Mat Xnn			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating		\$280	\$ 350.00	
	Spray Painting Charge		\$200	\$ 250.00	
	Wiring Charge		Xnn	\$ 50.00	
	Remove/Refix Reverse Sensor		Xnn	\$ 80.00	
	TOTAL LABOUR			\$ 730.00	
	ESTIMATE TOTAL			\$ 1,558.10	
<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div> <div style="text-align: right; margin-top: 10px;"> <p>25/11/19 1230hrs PanSuram@LKKAuto.com 86622778 (45) 2 repair plates</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					