

20985/11/19

India

25/11/19

10am

Fenneth

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Not Withstand

Repair After Rain

3 days

1 Day @ 4300

20/11/2019

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR TOYOTA VELLFIRE 2.5 - SMD7661X

1pc	front bumper	1614.20
1pc	front bumper LH side cover with chrome	
1pc	front bumper LH side retainer	
1pc	front LH headlamp	
1pc	front LH headlamp lower bracket	

CM \$ 1,812.50 ✓

PM \$ 580.50 ✓

DIY \$ 181.25 ✓

Warrant \$ 3,831.70 ✓

R \$ 181.85 X

\$ 6,587.80

less 25%

\$ 1,646.95

\$ 4,940.85

wiring
spray painting
labour charges
Total

\$ 100.00

\$ 600.00

\$ 600.00

\$ 6,240.85

201

4001

3001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

