

輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

India  
25/11/19  
10am.  
Remeth.

20/11/2019

Owner: ACE FLEET MANAGEMENT PTE LTD

Not withark  
Heavy After Rain  
3 days

**ESTIMATE TO REPAIR TOYOTA VELLFIRE 2.5 - SMD7661X**

1pc front bumper  
1pc front bumper LH side cover with chrome  
1pc front bumper LH side retainer  
1pc front LH headlamp  
1pc front LH headlamp lower bracket

CM \$ 1,812.50 ✓  
PUL \$ 580.50 ✓  
NII \$ 181.25 ✓  
MGM \$ 3,831.70 ✓ ?  
\$ 181.85 ?

less 25%

\$ 6,587.80  
\$ 1,646.95  
\$ 4,940.85

wiring  
spray painting  
labour charges  
Total

201  
\$ 100.00  
\$ 600.00 4000  
\$ 600.00 3000  
\$ 6,240.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

