

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: QBE	DATE	21/11/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: GZ2918U		
MODEL	: SSANGYONG MUSSO		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 20-Nov-19
		TIME	: 18:20HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,890.40	\$ 1,890.40
2	TAILGATE LOGO	1	\$ 90.00	\$ 90.00
3	TAILGATE EMBLEM 'MUSSO'	1	\$ 58.00	\$ 58.00
4	TAILGATE EMBLEM 'SPORT'	1	\$ 60.30	\$ 60.30
5	TAILGATE LOCK <i>New</i>	1	\$ 280.00	\$ 280.00
6	TAILGATE INNER TRIM <i>New</i>	1	\$ 630.00	\$ 630.00
7	TAILGATE WEATHER STRIP <i>New</i>	1	\$ 154.60	\$ 154.60
8	REAR BUMPER <i>Dishd.</i>	1	\$ 1,245.80	\$ 1,245.80
9	REAR BUMPER SIDE GARNISH <i>RH Dishd</i>	2	\$ 372.20	\$ 744.40
10	REAR BUMPER REFLECTOR <i>RH ut</i>	2	\$ 56.60	\$ 113.20
11	REAR BUMPER STEP GARNISH <i>Dishd</i>	1	\$ 295.80	\$ 295.80
12	REAR BUMPER STEP GARNISH TOP CHROME <i>Bed</i>	1	\$ 379.40	\$ 379.40
13	TAILLAMP RH <i>Crashd</i>	1	\$ 420.00	\$ 420.00
14	TAILLAMP PANEL RH <i>Regis</i>	1	\$ 152.30	\$ 152.30
15	TAILLAMP LOWER BRACKET <i>New</i>	1	\$ 99.60	\$ 99.60
16	REAR END PANEL <i>Regis</i>	1	\$ 1,477.10	\$ 1,477.10

TOTAL PRICE \$ 8,090.90

LESS 10% \$ 809.09

4868.50
4381.65

SUB TOTAL PRICE \$ 7,281.81

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAILGATE INNER TRIM CLIPS(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00
2	REAR BUMPER CLIPS(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00
3	REAR BUMPER SIDE GARNISH CLIP(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00
4	REAR BUMPER STEP GARNISH CLIP(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00
5	REAR BUMPER STEP GARNISH TOP CHROME CLIP(SET) <i>neu</i>	1	\$ 20.00	\$ 20.00
6	TAIL LAMP CLIP <i>neu</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL SEALANT <i>Neu</i>	1	\$ 100.00	\$ 100.00
8	REVERSE SENSOR <i>Neu neu</i>	1	\$ 220.00	\$ 220.00
TOTAL		80	\$	440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	700	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 100.00	30	
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 180.00	50	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	x.	
7	TRANFER TAILGATE MECHANISM	\$ 80.00	✓	
8	REMOVE AND REFIX CABIN BACK GLASS	\$ 100.00	x.	1620

TOTAL

\$4,190.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,721.81
 TOTAL LABOUR COST : \$ 4,190.00
 TOTAL REPAIR COST : \$ 11,911.81

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lij total: 608165
h/s 25/11/19 h/s: 210
05Apr (Nett Value)