

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KM1+DU41BR94589297.

TEO YONG BAK
BLK 343 YISHUN AVENUE 11
#11-135
S 760343

TP chimer.
Ashes.

Date :29.11.2019
Vehicle No :SJK 2993 U
Make/Model :HYUNDAI AVANTE
Accident date :19.11.2019

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Front bumper <i>Delornd</i>	1	\$ 470.9 ✓
2	Front bumper side holder @ \$46.20 <i>Nu</i>	2	\$ 92.4 ✓
3	Front bumper RH fod lamp <i>Canceled.</i>	1	\$ 172.5 ✓
4	Front bumper reinforcement <i>Best.</i>	1	\$ 274.6 ✓
5	Front bumper sponge <i>He ne</i>	1	\$ 121.7 x
6	Front bumper centre lower grille <i>N-P NEC</i>	1	\$ 76.8 x
7	Front grille <i>? NEM</i>	1	\$ 385 +
8	Front grille emblem	1	\$ 41.8 +
9	Front RH headlamp <i>cancel</i>	1	\$ 532 ✓
10	Front RH headlamp blubs @ \$28.40 <i>NEM</i>	2	\$ 56.8 +
11	Front RH headlamp lower garnish <i>He ne</i>	1	\$ 41.8 +
12	Front RH fender <i>Buckled.</i>	1	\$ 436.4 ✓
13	Front RH fender inner shield <i>He ne</i>	1	\$ 70.2 x
14	Front RH fender inner shield clips (1set) <i>NEM</i>	1	\$ 66 x
15	Front support panel <i>cancel.</i>	1	\$ 829 ✓
			\$ 3667.9
Less 20% Disc			\$ 733.58
Total			\$ 2934.32

Labour Cost

- 1 Remove & reinstall air con fill in gas
- 2 Remove ,replace & repair consistent to the accident
- 3 Respray painting
- 4 Tuff kote

	\$ 150-120
1320.	\$ 1400-600.
	\$ 1300-600.
	\$ 100 x
Total	\$ 2950

Grand Total \$ 5884.32

total: 3566.24

c/s: 28/c

OS Pays

28/c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: