

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63855592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

Date Generated : 09/12/2019
 User ID : PehSuan

Section A - Accident Details	
Registration Number	SHC4612Y
Case Reference Number	TAX/11/19/2094
Registration Date	27/8/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	POH AH CHYE
Type of Accident	Side Swipe
Accident Date and Time	21/11/2019 5:00 PM
Accident Reported Date and Time	22/11/2019 8:40 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104470
Special Instruction to ARC, if any	TP
Prepared Date and Time	22/11/2019 1:29 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$3,309.63	\$513.18
Total Other Cost	\$896.88	\$296.88
TOTAL COST	\$5,649.51	\$1,410.06
Lump Sum Total	\$5,650.00	\$1,400.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / China Taipng
ARC / Surveyor Sign Off Date	26/11/2019 1:59 PM	25/11/2019 3:57 PM
Signature		
Remarks		Lump Sum repair, Take after spray photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0056	Invoice Number	
Quotation Date	05.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
Total Other Costs	\$896.88	\$296.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
		53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given ✗
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given ✗
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given ✗
		53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given ✗
		42611-47140	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given ✗
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given ✗
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair ✓
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given ✗
		68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given ✗



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63855592
Estimator Telephone Number : 66652623
Accident Reporting Number : 6662672

Date Generated : 09/12/2019
 User ID : PehSuzn

	88610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X
	87940-47310	MIRROR ASSY,LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given X
	81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X
	87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given X
Total				\$5,440.74		\$641.48		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair dy - 3 days

$$\begin{array}{r}
 641.48 \\
 - 202 \\
 \hline
 513.18
 \end{array}$$

$$\begin{array}{r}
 + 200.00 \\
 + 696.88 \\
 \hline
 1410.06
 \end{array}$$

$$\begin{array}{r}
 45 \$1400/-
 \end{array}$$