



Case Details

Case Reference Number : BUS/11/19/5032

Company Type : SMRT Buses Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-9434-ID

Accident Date and Time : 19/11/2019 09:08

Vehicle Registration Number : SG5851R

Assigned By : Claiming Case Owner Team

AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			ALUMINIUM RR EXIT DOOR FRAME	1	905.00	905.00	10.00	814.50	Replace	1	814.50 396	Replace ▾		
One Time Key In	Main		X	RUBBER PROFILE	6	44.00	264.00	10.00	237.60	Replace	6	237.60	Replace ▾	X (
One Time Key In	Main			SMRT STICKER	1	75.00	75.00	0.00	75.00	Replace	1	75.00	Replace ▾		
One Time Key In	Main		X	SIDE PANEL L6	1	1,168.75	1,168.75	10.00	1,051.88	Replace	1	0	Repair ▾		
Total Spare Part Cost									2,178.98	Surveyor Total			1,127.10		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0		
Final Spare Part Cost									2,178.98	Final Sur Total			1,127.10		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	530	
Total:			795.00	530.00	



Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	602.00	432	
Total:			602.00	432.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,178.98	1,127.10
Total Labour Cost	795.00	530.00
Total Spray Painting	602.00	432.00
Other	0.00	0.00
Overall Total	3,575.98	2,089.10
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	2,089.10
Surveyor Approved Amount		2,089.10
No of Repair Days*	3	2
Remarks		Surveyor Remarks
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	25/11/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

vic



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/01/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG5851R
Case Reference Number	BUS/11/19/5032
Registration Date	1/2/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Han Liguu
Type of Accident	Head To Side
Accident Date and Time	19/11/2019 5:08 PM
Accident Reported Date and Time	19/11/2019 6:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104612
Special Instruction to ARC, if any	SG5851R-LEFT CENTER PORTION SDJ6896S (TP) INSURED WITH AIG
Prepared Date and Time	22/11/2019 3:39 PM
Chassis Number	WMAA95ZZ1G7003521
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$1,760.48	\$471.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,157.48	\$1,433.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	25/11/2019 9:13 AM	25/11/2019 3:35 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

PIP
\$1,433
2 days



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/01/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$602.00	\$432.00
Total Spray Painting & Panel Beating	\$602.00	\$432.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			RUBBER PROFILE	6.00	\$44.00	100.00	\$0.00	Replace	Repair
			SMRT STICKER	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			SIDE PANEL L6	1.00	\$1,168.75	100.00	\$0.00	Replace	Replace
6010568	DOOR		FRAME, EXIT DOOR: FOR MAN A22 BUS	1.00	\$440.00	10.00	\$396.00	Replace	Replace
Total					\$1,727.75		\$471.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									