

INS. CASE OWNER: **LEE MING YAO**

CC6/AIG19020969/Uha3

LKK:
IDAC:

Surveyor: **MARCUS** DOI: **27/11/2019**

Date / Time: **27.11.2019**

Registered in Meritum: **27.11.2019**

Pre-assign / CCU / FTE



Insured Vehicle No. : **SLX 2757T**
 Name of Insured : **RONALD TAN KOK BENG**
 Insured Tel No. : _____ HP: **91550080**
 Excess Sec II :SS _____ D.O.A: **25/11/19 19:40**
 Is driver the owner? (YES / **NO**) Nature of Accident : _____
 If NO, Driver Name / Age: **TAN SOON LEE STEPHEN**
 Driver Tel No. : _____ (V/L: **YES** / NO)

Claim No. : **9944825777SG**
 Policy No. : **1700074684**
 Make / Model : _____
 Place of Accident : _____

OI GIA REPORT: **YES** / NO ; TP GIA REPORT **YES** / NO
 Insured Liability : % **Final ? Yes / No**

SKW 5211Z



INSRS:
WSP: **HUP MOTOR**
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
	SKW 5211Z SLX 2757T	NA/AIG19020940/r3; DOA: 25/11/19
03/12	OINR. TO SEND LETTER. FILE PASS TO SU.	
31/12/19	MUG EQUIPMENT. OLD ACCIDENTALLY HIT PARKED TP WHILE ADJUSTING VEHICLE AT THE PARKING LOT. SEND LETTER TO OI TO NOTIFY TP CLAIM IN NCD ISSUES. BUALI LIABILITY CLERK MANAGED TP LOD IN BY BUALI	
16/12/19	UPLOADED IA IN WIKIKHUN	
16/01/2020	MG APPROVED WARRANTS	
21/01/2020	SEND ACCEPTANCE BUALI TO TP	
22/01/2020	ML DONE IN OKDOTE. TO CLOSE.	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	09/12/19 - JIC
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: **P/P** S\$ **1,030.00** (**4** days) Reduction: **79** % Email Call

FINAL SETTLEMENT Date/Time: **22/01/20** Confirm with: **DAVID** Email Call
 Final Liability: % **100** (Agreed / Assessed) BOLA S/N No. : **12** If NO or B 28, Ass. Lia : **(OLD HIT STATIONARY TP)**

Repair Cost: S\$ **1,030.00**
 Loss of Rental (LOR): S\$ **400.00** (**4** days) x **100.00**

Loss of Use (LOU): S\$ **-** (**5** x days)
 Loss of Income (LOI): S\$ **-** (**5** x days)
 LOR only LOU only LOR + LOU LOR + LOI (Tick only one)

GIA/LTA Search: S\$ **2.00**
 Medical: S\$ **-**
 Disbursement: S\$ **-** (e.g. Tow/Independent)
 Legal Cost: S\$ **-**

Total: S\$ **1,432.00** Global Sum S\$: **-**
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee: **\$320.00**

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ **1,432.00** Name 1: **HUP MOTOR TRADING & SERVICE**
 Payee 2: (Strike if N.A.) S\$ **-** Name 2: **-**
 Payee 3: (Strike if N.A.) S\$ **-** Name 3: **-**

COPY SENT
28/1/2020

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SKW5211Z
 at Workshop m/s: meade
 of: SLX22577
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/> NS	<input type="checkbox"/> O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GI/PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 1.81 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 741F
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKW5211Z Yr Regn: 9.19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA/
 Make: meade 3 Hybrid cc 1496
 Colour: Gray A/C: Insured / Std / NI / NA
 Sp. Reading: 2487 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6BP2SAAK1100840
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/45 R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

<u>Front</u>		<u>Rear</u>
R/Bal. 9 mm		R/Bal. 9 mm
L/Bal. 9 mm		L/Bal. 9 mm
D.O.A. 25/11/19		D.O.I. 27/11/19

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 MS Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTA 38610
	have video

28/11/19 contact final by 1030 with David
 (cost: 43,042.64 (79%))

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____

1) Date/Time, File Return to?

Resurvey No. of Trip: _____

2) Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
) Photos	
) Others	
TOTAL	

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

not allowed
27/11/19
1/28 1030/2

Our Ref: TP 2971/11/19 Your Ref: _____ Date: 26th NOV 2019 *Hdy*

MR LEE LAI CHYE
BLK 852, #05-211,
TAMPINES ST 82, S (520852)

Estimate cost of repair to MAZDA 3 (A) 1.5 Hybrid Astina Saloon - SKW 5211 &

1 pc rear n/s door		~	\$ 1,312.10	X
16 pcs rear n/s door inner trim board clips	@ \$ 5.00	11	80.00	X
1 pc rear n/s fender		~	1,643.60	X
8 pcs rear n/s fender inner trim board clips	@ \$ 5.00	11	40.00	X
12 pcs n/s rocker panel sideskirt clips	@ \$ 5.80	11	69.60	X
1 pc n/s rocker panel sideskirt sealant		11	60.00	X
1 pc fuel tank lid panel		11	198.00	X
			\$ 3,403.30	
	Less 20%		\$ 680.66	
			\$ 2,722.64	
To wiring check up			50.00	20
To remove & refix rear n/s door inner trim board cover, glass, regulstor, moulding, handle, lock, channel & necessary parts.			150.00	60
To diagnose & reset air-bag sensor for rear n/s door.				
To remove & refix carpet, floor mat, garnish, cushion seat, floor board cover, rear fender run & necessary parts.		11	120.00	X
To check & adjust rear wheel alignment & balancing.		11	120.00	X
To remove & refix & pump sealant for n/s rocker panel sideskirt.		11	120.00	X
To respray Tuff-Kote on all affected accident parts.		11	90.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s door & necessary parts, to weld, renew & align above parts.			700.00	400
To putty & respray painting on all affected accident parts.			800.00	550
			\$ 4,872.64	
			=====	

Dollars : Four Thousand Eight Hundred Seventy Two And Cents Sixty Four Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants Private Limited
The estimator of the following:
 • To identify defective parts and/or
 • To identify damaged parts to be replaced.
 • To provide a written estimate.
 • That any work done is done in accordance with
 • To the satisfaction of the customer.
 • Any necessary part(s) must be obtained from
 • Manufacturer and approval from Insurance Company.
 Approved by Receiver
 Signature:
 Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	741F
Vehicle Details	
Vehicle No.:	SKW5211Z
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Nov 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4DR 1.5 AT M-HYBRID ASTINA
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	P520613752
Chassis No.:	JM6BP2SAAK1100840
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$25,630.00
Original Registration Date:	25 Sep 2019
First Registration Date:	25 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$17,882.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2029
PARF Rebate Amount:	\$13,411.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,667.00
COE Rebate Amount:	\$26,199.00
Total Rebate Amount:	\$39,610.00

The information contained herein is correct as at 28 Nov 2019

OK

View Received Message

This mail is associated with :

***SKW5211Z (9944825777SG)
[SLX2757T]**

TP

LEE LAI CHYEN (LI LAICAI)

Nov 25 2019 7:00PM

[RONALD TAN KOK BENG (RONALD CHEN GUOMING)]

Hup Motor Trading & Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/11/2019 17:16 PM.
To LKK_HQ
CC Yinrul.Hor@aig.com; Divyashni.Subramaniam@aig.com; NoorMariesa.AbuKassim@aig.com
Subject NO OI GIA REPORT

Hi,

Kindly be informed OI has not reported yet. OI details as below :

Name : RONALD TAN KOK BENG (RONALD CHEN GUOMING)
Address : 306 TAMPINES STREET 32 #09-02 SINGAPORE 520306
Phone No. : 91550080

Thanks
Mariesa

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19020969/Uha3

03 December 2019

RONALD TAN KOK BENG (RONALD CHEN GUOMING)
306 TAMPINES STREET 32
#09-02
SINGAPORE 520306

Dear Sirs/Madam,

**ACCIDENT INVOLVING SLX 2757T AND SKW 5211Z ON 25/11/2019 ALONG/
AT TAMPINES STREES 11 ROUND MARKET OPEN CARPARK**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

*c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

Print Received Message

This mail is associated with :

***SKW5211Z (9944825777SG)
[SLX2757T]**

TP

LEE LAI CHYEN (LI LAICAI)

Nov 25 2019 8:00PM

[RONALD TAN KOK BENG (RONALD CHEN GUOMING)]

Hup Motor Trading & Service

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/01/2020 09:26 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1432.00) - SKW5211Z - Claim Handler: Lee, Ming-Yao

Approved:1432.00:Please make sure all docs are ready upon settlement.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Nov 2019 Edit Reg		27 Nov 2019 00:00 Edit Adj Rpt	S\$1,030.00 Edit Estimates	S\$1,030.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	RONALD TAN KOK BENG (RONALD CHEN GUOMING) , ID: -								
Main Claimant:	LEE LAI CHYEN (LI LAICAI) , ID: S7735741F								
Vehicle Reg. No.:	SKW5211Z	Date of Loss:	25/11/2019 20:00 - :59 [2 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9944825777SG	Policy/Cover Note No.:	1700074684-02 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLX2757T	Policy No. (Claimant):	1900166432						
		Excess:							
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (16/01/2020): Alert - Adj Mandate Approved (S\$1432.00) - SKW5211Z - Claim Handler: Lee, Ming-Y... AIG_SG (28/11/2019): NO OI GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW5211Z (9944825777SG)
[SLX2757T]

TP

LEE LAI CHYEN (LI LAICAI)

Nov 25 2019 8:00PM

[RONALD TAN KOK BENG (RONALD CHEN GUOMING)]

Hup Motor Trading & Service

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser <input type="button" value="v"/>	
Letters/Correspondences			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		<input type="button" value="E"/> Edit
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/12/19 13:23	Adjuster Immediate Advice		<input type="button" value="L"/> Load HTM
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/19 17:30	Odometer Reading		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
2	27/11/19 17:30	Chassis Number		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
3	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
4	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
5	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
6	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
7	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
8	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
9	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
10	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
11	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
12	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
13	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
14	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
15	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
16	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
17	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
18	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
19	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
20	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
21	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
22	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
23	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
24	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
25	27/11/19 17:30	General View		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
26	30/12/19 14:25	After Repair Photo		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
27	30/12/19 14:25	After Repair Photo		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
28	30/12/19 14:25	After Repair Photo		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
29	30/12/19 14:25	After Repair Photo		<input type="button" value="L"/> Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/19 10:27	TP ESTIMATE + TP GIA REPORT		<input type="button" value="L"/> Load PDF
2	02/12/19 11:32	TP ESTIMATE - MARKED		<input type="button" value="L"/> Load PDF
3	02/12/19 14:26	Ltr to Insured -non reporting		<input type="button" value="L"/> Load PDF
4	09/12/19 12:09	OID DRIVING LICENCE STATUS		<input type="button" value="L"/> Load PDF
5	09/12/19 15:10	LETTER TO OI		<input type="button" value="L"/> Load PDF
6	16/12/19 13:18	TP LOD		<input type="button" value="L"/> Load PDF

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
7	22/01/20 11:35	EMAIL FROM TP		Load PDF
8	30/01/20 14:23	WORKSHOP INVOICE		Load PDF
9	30/01/20 14:23	AUTHORISATION TO ACT FORM		Load PDF
10	30/01/20 14:23	Release Voucher		Load PDF
11	30/01/20 14:23	RENTAL RECEIPT		Load PDF
12	30/01/20 14:23	GIA SEARCH		Load PDF
13	30/01/20 14:23	LOD		Load PDF
No	Finalized On	ATIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	09/12/19 12:04	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLX2757T (Insd veh)	Model:	MAZDA 3 1.5 5DR M-HYBRID ASTINA (A)
	SKW5211Z (TP veh)		
Date of Accident:	25/11/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,872.64
Final Repair Cost	:	\$	1,030.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,432.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hup Motor Trading & Service	:	\$ 1,432.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

30 Jan
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19020969/UHA3Q2

Date: 30/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700074684-02

Claimant Vehicle No : SKW5211Z Insured Vehicle No : SLX2757T

Date of Loss: 25/11/2019 Nature of Claim: TP Claim No: 9944825777SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW5211Z	Engine No:	P520613752
Make & Model:	MAZDA 3, 1.5 5DR M-HYBRID ASTINA (A)	Chassis No:	JM6BP2SAAK1100840
Reg. Date:	25/09/2019 (Man. Year: 2019)	Odometer:	2487 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R18	Rear Tyre Size:	215/45 R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,722.64	0.00	2,722.64	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,030.00	1,120.00	52.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,872.64	1,030.00	3,842.64	78.86
	+ Car Rental (4.0 x S\$100.00/day) (S\$)	400.00		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	1,432.00		

INSPECTION

Date of Assignment: 27/11/2019

Date Inspected: 27/11/2019 Inspected At: Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S DOOR	Repair	1,312.10 FL	*- FL
2	16		*REAR N/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	80.00 FL	*- FL
3	1		*REAR N/S FENDER	Repair	1,643.60 FL	*- FL
4	8		*REAR N/S FENDER INNER TRIM BOARD CLIPS	Not Necessary	40.00 FL	*- FL
5	12		*N/S ROCKER PANEL SIDESKIRT CLIPS	Not Necessary	69.60 FL	*- FL
6	1		*N/S ROCKER PANEL SIDESKIRT SEALANT	Not Necessary	60.00 FL	*- FL
7	1		*FUEL TANK LID PANEL	Not Necessary	198.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,403.30	0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	680.66	0.00
Total Parts (\$\$)	2,722.64	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP	New	50.00	20.00
2	TO REMOVE & REFIX REAR N/S DOOR INNER TRIM BOARD COVER ,GLASS ,REGULATOR ,MOULDING ,HANDLE ,LOCK ,CHANNEL & NECESSARY PARTS	New	150.00	60.00
3	TO DIAGNOSE & RESET AIR-BAG SENSOR FOR REAR N/S DOOR (NPA)	New	0.00	0.00
4	TO REMOVE & REFIX CARPET ,FLOOR MAT ,GARNISH ,CUSHION SEAT ,FLOOR BOARD COVER ,REAR FENDER RUN & NECESSARY PARTS	New	120.00	0.00
5	TO CHECK & ADJUST REAR WHEEL ALIGNMENT & BALANCING	New	120.00	0.00
6	TO REMOVE & REFIX & PUMP SEALANT FOR N/S ROCKER PANEL SIDESKIRT	New	120.00	0.00
7	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	90.00	0.00
8	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR N/S DOOR & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	700.00	400.00
9	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	800.00	550.00
			Gross Labour Cost (\$)	2,150.00
				1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >