

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

not allowed
27/11/19 *2M*
1/178 1030/2

Our Ref: TP 2971/11/19 Your Ref: _____ Date: 26th NOV 2019 *Hdy*

MR LEE LAI CHYE
BLK 852, #05-211,
TAMPINES ST 82, S (520852)

Estimate cost of repair to MAZDA 3 (A) 1.5 Hybrid Astina Saloon - SKW 5211 z

1 pc rear n/s door		<i>1</i>	\$ 1,312.10	<i>X</i>
16 pcs rear n/s door inner trim board clips	@ \$ 5.00	<i>11</i>	80.00	<i>X</i>
1 pc rear n/s fender		<i>1</i>	1,643.60	<i>X</i>
8 pcs rear n/s fender inner trim board clips	@ \$ 5.00	<i>11</i>	40.00	<i>X</i>
12 pcs n/s rocker panel sideskirt clips	@ \$ 5.80	<i>11</i>	69.60	<i>X</i>
1 pc n/s rocker panel sideskirt sealant		<i>11</i>	60.00	<i>X</i>
1 pc fuel tank lid panel		<i>11</i>	198.00	<i>X</i>
			<u>\$ 3,403.30</u>	
	Less 20%		\$ 680.66	
			<u>\$ 2,722.64</u>	
To wiring check up			50.00	<i>20</i>
To remove & refix rear n/s door inner trim board cover, glass, regulstor, moulding, handle, lock, channel & necessary parts.			150.00	<i>60</i>
To diagnose & reset air-bag sensor for rear n/s door.				
To remove & refix carpet, floor mat, garnish, cushion seat, floor board cover, rear fender run & necessary parts.		<i>11</i>	120.00	<i>X</i>
To check & adjust rear wheel alignment & balancing.		<i>11</i>	120.00	<i>X</i>
To remove & refix & pump sealant for n/s rocker panel sideskirt.		<i>11</i>	120.00	<i>X</i>
To respray Tuff-Kote on all affected accident parts.		<i>11</i>	90.00	<i>X</i>
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s door & necessary parts, to weld, renew & align above parts.			700.00	<i>400</i>
To putty & respray painting on all affected accident parts.			800.00	<i>550</i>
			<u>\$ 4,872.64</u>	
			=====	

Dollars : Four Thousand Eight Hundred ~~Seventy Two~~ And Cents Sixty Four Only.

HUP MOTOR TRADING & SERVICE

.....
[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: