



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI19020981/Avd3e2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 01-06-2020



Code : EQI

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKQ 1660T	<b>Veh. Inspected</b>	SKU 7239S
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DM19HO03126-JG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JOEL GOH	<b>Assign Date</b>	27/11/2019

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA ALTIS	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	MR053REH104537482	<b>Colour</b>	SILVER
<b>Odometer</b>	106226	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	205/55 R16	YOKOHAMA	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	23/11/2019	<b>Inspection Date</b>	27/11/2019
<b>Survey held at</b>	T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>21 Working Days</b>
--	------------------------