

TK MOTOR WORKSHOP

1 KAKI BLUNT AVE #02-56
SINGAPORE 417883
TEL: 9637 3123 FAX: 4844 2641
CO. REG NO: 33089071

Too Lang Shue

Blk 837, Tampines S483, #07-80

Singapore 520837

Date: 20/05/2020

Accident Date: 23/11/2019

TPEO
Veron

Estimate Cost of Repair Bill To Toyota Altis Car No: SKU72395

CHASSIS NO MR053REN 104537482

Model ZRE171G-GEXGKZ

1 pc Front Bonnet	\$1140.40	✓	Distorted
2 pc Front Bonnet Hinge	\$119.20	✓	Bent
1 pc Front Bonnet Insulator Garnish	\$321.70	✓	crumpled 239
12 pc Front Bonnet Insulator Garnish clip	\$36.80	✓	Nec
1 pc Front Bonnet Rubber	\$33.10	✓	ut
1 pc Front Bonnet Stand clip	\$12.50	X	Nol Nec
1 pc Front No plate	\$26	✓	missing
11 pc Front No plate	\$20	✓	missing
1 pc Front Support Panel	\$1074.60	✓	Distorted.
1 pc Front Support Panel lock	\$240.70	✓	Jammed.
1 pc Front Support brace panel	\$101.70	✓	Bent.
2 pc Front Fender	\$1358.20	✓	Buckled.
2 pc Front Fender Side Garnish	\$178.20	✓	Missing
2 pc Front Fender Emblem	\$90.40	✓	Nec
1 pc Front Wiper Garnish	\$539.80	✓	ut
2 pc Front Air Bag Sensor	\$843.40	X	Nol Nec
1 pc Front Bumper	\$589.70	✓	Distorted
8 pc Front Bumper Clips	\$30.40	✓	Nec.

TK MOTOR WORKSHOP

1 KAKI DRUKIT AVE #02-36
SINGAPORE 417883
TEL: 9627 1323 FAX: 6844 2641
CO. REG NO: S30499971

Date: 20/05/2020

- 2 pc Front Bumper side, Retainer \$170.20 ✓ Nec
- 4 pc Front Bumper side clip \$12.80 ✓ Nec
- 1 pc Front Bumper Reinforcement Beam \$371.70 ✓ Bent.
- 1 pc Front Bumper sponge \$140.70 ✓ cracked
- 1 pc Front Bumper Centre Grille \$105.70 ✓ Deformed.
- 2 pc Front Bumper Fog Lamp \$643.40 ✓ cracked
- 1 pc Front Bumper Fog Lamp Cover ~~\$703.20~~ 242 ✓ Deformed
- 1 pc Front Air Cleaner Tank Assy ~~\$721.60~~ ✓ cracked 455
- 1 pc Front Intake manifold \$1821.40 ✓ ut.
- 1 pc Front wiper tank Assy \$169.40 X Not Nec
- 2 pc Front Headlamp \$3,632.20 ✓ Smashed.
- 2 pc Front Headlamp Bracket \$118.80 X Not Nec
- 1 pc Front Radiator \$1510.50 ✓ Bent.
- 1 pc Front Radiator Top Upper Guide Garnish \$99.70 ✓ cracked
- 1 pc Front Radiator Fan Cowling \$255.40 ✓ cracked.
- 1 pc Front Radiator Fan Blade \$121.60 X Not Nec
- 1 pc Front Radiator Fan Motor \$421.70 X Not Nec.
- 1 pc Front Radiator Fan Switch Assy ~~\$551.60~~ 398.40 X Not Nec
- 1 pc Front Grille \$564.80 ✓ cracked
- 1 pc Front Grille Emblem \$72.10 ✓ Nec
- 4 pc Front Grille Clip \$12.80 ✓ Nec
- 1 pc Front Grille Rubber \$49.10 ✓ ut
- 1 pc Front Air Con Condenser \$1289.24 ✓ Bent.
- 1 pc Front Air Con Discharge Hose \$439.80 ✓ Bent.
- 1 pc Front Air Con Liquid Pipe \$625.70 X Not Nec.

TK MOTOR WORKSHOP

1 KAKI BUNUT AVE #02-56
SINGAPORE 417881
TEL: 9627 1321 FAX: 6848 2841
CO. REG NO: S30490971

Date : 20/05/2020

- 1pc Front Air Con Compressor \$1561.70 X NE Nec
- 1pc Front Alternator, \$2431.90 X NE nec
- 1pc Front Fan Belt \$127.10 X NE nec
- 1pc Front Engine Cover (Top) \$399.10 X NE Nec
- 1pc Rear Bootlid \$740.20 ✓ Buckled.
- 2pc Rear Bootlid Hinge \$243.40 X Not Nec.
- 1pc Rear Bootlid Lock \$357.90 ✓ Jammed.
- 3pc Rear Bootlid Emblem \$59.10 ✓ Nec
- 1pc Rear Bootlid Chrome moulding \$280.70 ✓ cracked.
- 1pc Rear Bootlid Rubber \$184.70 ✓ cut.
- 2pc Rear Bootlid Reflector Lamp \$656.20 ✓ cracked
- 1pc Rear Bootlid Insulator Garnish \$421.70 X NE Nec
- 1pc Rear Bootlid Insulator Garnish clip \$27.50 X NE Nec
- 2pc Rear Taillamp \$1056.20 ✓ LH ut, RH cracked.
- 4pc Rear Taillamp clip \$14.60 ✓ Nec.
- 2pc Rear Taillamp Bracket \$84.20 42.10 RH cracked.
- 1pc Rear RH Taillamp Panel \$299.10 ✓ Buckled.
- 1pc Rear RH Fender \$1136.80 ✓ Buckled.
- 1pc Rear RH Fender Inner Lower Panel \$121.20 ✓ Buckled.
- 1pc Rear RH Fender Inner Trimboard \$59.60 X NE Nec
- 8pc Rear RH Fender Inner Trimboard clip \$30.40 X NE nec.
- 1pc Rear End Panel wire harness \$321.60 X NE nec.
- 1pc Rear Antenna Electrical Key sensor \$141.90 ✓ cracked.

TK MOTOR WORKSHOP

1 KAKI BUNT AVE 6 #02-56
SINGAPORE 417813
TEL: 9627 1321 FAX: 4844 2641
CO. REG NO: 13049997L

- 1 pc Rear End panel \$649.20 ✓ Dated Date: 20/05/2020
- 1 pc Rear End panel Lock \$357.80 X NE Nec.
- 1 pc Rear End panel Garnish \$202.70 ✓ delud
- 4 pc Rear End panel Garnish clip \$12 ✓ Nec
- 1 pc Rear Windscreen \$1448.50 ✓ ut.
- 1 pc Rear Windscreen moulding \$121.80 ✓ Nec
- 1 pc Rear Windscreen Inner seal \$26 S/Nett ✓ Nec.
- 1 pc Rear Windscreen sealant \$45 S/Nett ✓ Nec
- 1 pc Rear Sparewheel panel \$789.90 X Repair
- 1 pc Rear Sparewheel Garnish ~~\$421.70~~ ✓ Deformed
292
- 1 pc Rear R/H Chassis Crossmember \$1276 10 X Repair
- 1 pc Rear Exhaust pipe \$780.90 ✓ Best.
- 2 pc Rear Exhaust pipe mounting \$83.40 4170 1 piece torn.
- 1 pc Rear Reverse Camera \$130.40 X Not Nec.
- 1 pc Rear No Plate \$26 S/Nett X NE Nec
- 1 pc Rear No plate Cover \$26 S/Nett X NE Nec.
- 1 pc Rear R/H Door \$1198.50 X Repair
- 1 pc Rear Bumper \$631.90 ✓ Distorted
- 8 pc Rear Bumper clip \$30.40 ✓ Nec
- 2 pc Rear Bumper Side Retainer \$240.20 ✓ Nec
- 4 pc Rear Bumper Side clip \$12.80 ✓ Nec
- 2 pc Rear Bumper Reflector \$115.40 ✓ Missing.
- 1 set Rear Bumper Reverse Sensor \$321.70 ✓ Damaged
- 1 pc Rear Bumper Reinforcement Beam ~~\$421.90~~ ✓ Best.
395
- 2 pc Rear Bumper Side Garnish \$114.20 X NE Nec.

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE. # 02-16
SINGAPORE 417003
TEL: 9627 1321 FAX: 6844 2641
CO. REG NOY 5344007L

Nett Value
14.2K

- Labour Charge for reinstall wire harness & checking
Front & Rear wiring ~~\$150~~ 60.
- To Spray Painting ~~\$2,500~~ 2400.
- 1 Aircon Gas \$100 ✓
- To Remove & Refix Rear Interior upholstery & cushion ~~\$180~~ 80.
- To Remove & Refix Rear Exhaust pipe ~~\$80~~ ✓
- To Remove & Refix Rear Windscreen ~~\$150~~ 120
- To Conduct Chassis alignment and measurement ~~\$380~~ 200.
- To apply undercoating on the repaired and replaced panels.
for rust protection ~~\$80~~ ✓
- To measure, drill the replaced bumper position and reinstall
rear reverse sensor, control unit, check and test functioning
and rear reverse camera control unit ~~\$100~~ 50
- Labour charge to reset fault code and carry out
diagnostic checks. ~~\$150~~ 80.
- Labour charge for panel beating, welding remaining all.
damaged parts and replacing of the new parts etc..
~~\$2400~~ 2200.
- List 26883.24 Labour \$450
Less 25% 20162.43 total 25794.8
SN 117 L/S: 142K
21 Days.