

TK MOTOR WORKSHOP

1 KAKI HURIT AVE #02-56
SINGAPORE 417883
TEL: 9627 1123 FAX: 6844 2641
COR. REG NO: 53049971L

Tao Lang Shue

Date: 20/05/2020

Blk 837, Tampines St 83, #07-80

Singapore 520837

Accident Date: 23/11/2019

TPEC
Veron

Estimate Cost of Repair Bill To Toyota Alt's Car No: SKU 72395

CHASSIS NO MR 053REN 104537482

Model ZRE171G-GEXGKZ

1 pc Front	Bonnet	\$1140.40	✓	Distorted
2 pc Front	Bonnet Hinge	\$119.20	✓	Bent
1 pc Front	Bonnet Insulator Garnish	\$32.70	✓	crumpled 239
12 pc Front	Bonnet Insulator Garnish clip	\$36.80	✓	Nec
1 pc Front	Bonnet Rubber	\$33.10	✓	ut
1 pc Front	Bonnet Stand clip	\$12.50	X	Not Nec
1 pc Front	No plate	\$20	✓	missing
11 pc Front	No plate Holder	\$20	✓	missing
1 pc Front	Support Panel	\$1074.60	✓	Distorted.
1 pc Front	Support Panel lock	\$240.70	✓	Jammed.
1 pc Front	Support brace panel	\$101.70	✓	Bent.
2 pc Front	Fender	\$1358.20	✓	Buckled.
2 pc Front	Fender Side Garnish	\$178.20	✓	Missing
2 pc Front	Fender Emblem	\$90.40	✓	Nec
1 pc Front	Wiper Garnish	\$539.80	✓	ut
2 pc Front	Air Bag Sensor	\$843.40	X	Not Nec
1 pc Front	Bumper	\$589.70	✓	Distorted
8 pc Front	Bumper Clips	\$30.40	✓	Nec.

TK MOTOR WORKSHOP

1 KAKI DRIFT AVE #02-06
SINGAPORE 417003
TEL: 9627 1323 FAX: 6844 2641
CO. REG NO: 53099097L

Date: 20/05/2020

- 2pc Front Bumper side, Retainer \$170.20 ✓ Nec
- 4pc Front Bumper side clip \$12.80 ✓ Nec
- 1pc Front Bumper Reinforcement Beam \$371.70 ✓ Bent.
- 1pc Front Bumper sponge \$140.70 ✓ cracked
- 1pc Front Bumper Centre Grille \$105.70 ✓ Deformed.
- 2pc Front Bumper Fog Lamp \$643.40 ✓ Cracked
- 1pc Front Bumper Fog Lamp Cover ~~\$303.20~~ 242 ✓ Deformed
- 1pc Front Air Cleaner Tank Assy ~~\$721.60~~ ✓ Cracked 455
- 1pc Front Intake manifold \$1821.40 ✓ ut.
- 1pc Front wiper tank Assy \$169.40 X NE Nec
- 2pc Front Headlamp \$3,632.20 ✓ Smashed.
- 2pc Front Headlamp Bracket \$118.80 X NE Nec
- 1pc Front Radiator \$1510.50 ✓ Bent.
- 1pc Front Radiator Top Upper Guide Garnish \$99.70 ✓ cracked
- 1pc Front Radiator Fan Cowling \$255.40 ✓ cracked.
- 1pc Front Radiator Fan Blade \$121.60 X NE Nec
- 1pc Front Radiator Fan Motor \$421.70 X NE Nec
- 1pc Front Radiator Fan Switch Assy \$551.60 X NE Nec
- 1pc Front Grille ~~\$564.80~~ ✓ Cracked 398.40
- 1pc Front Grille Emblem \$72.10 ✓ Nec
- 4pc Front Grille clip \$12.80 ✓ Nec
- 1pc Front Grille Rubber \$49.10 ✓ ut
- 1pc Front Air Con Condenser \$1289.24 ✓ Bent.
- 1pc Front Air Con Discharge Hose \$439.80 ✓ Bent.
- 1pc Front Air Con Liquid Pipe \$625.70 X NE Nec

TK MOTOR WORKSHOP

1 KAKI BUNT AVE #03-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6841 2648
CO. REG NO: S30490971

Date : 20/05/2020

1pc Front	Air Con Compressor	\$1561.70	X	NE nec
1pc Front	Alternator	\$2431.90	X	NE nec
1pc Front	Fan Belt	\$127.10	X	NE nec
1pc Front	Engine Cover (Top)	\$399.10	X	NE nec
1pc Rear	Bootlid	\$740.20	✓	Buckled
2pc Rear	Bootlid Hinge	\$243.40	X	Not Nec
1pc Rear	Bootlid Lock	\$357.90	✓	Jammed
3pc Rear	Bootlid Emblem	\$59.10	✓	Nec
1pc Rear	Bootlid Chrome moulding	\$280.70	✓	cracked:
1pc Rear	Bootlid Rubber	\$184.70	✓	cut
2pc Rear	Bootlid Reflector Lamp	\$656.20	✓	cracked
1pc Rear	Bootlid Insulator Garnish	\$421.70	X	NE nec
11pc Rear	Bootlid Insulator Garnish clip	\$27.50	X	NE nec
2pc Rear	Taillamp	\$1056.20	✓	LH ut, RH cracked
4pc Rear	Taillamp clip	\$14.60	✓	Nec
2pc Rear	Taillamp Bracket	\$84.20 42.10		RH cracked
1pc Rear	R/H Taillamp Panel	\$299.10	✓	Buckled
1pc Rear	R/H Fender	\$1136.80	✓	Buckled
1pc Rear	R/H Fender Inner Lower Panel	\$121.20	✓	Buckled
1pc Rear	R/H Fender Inner Trimboard	\$591.60	X	NE nec
8pc Rear	R/H Fender Inner Trimboard clip	\$30.40	X	NE nec
1pc Rear	End Panel wire harness	\$321.60	X	NE nec
1pc Rear	Antenna Electrical Key sensor	\$141.90	✓	cracked

TK MOTOR WORKSHOP

1 KAKI BLUNT AVE # 002-56

SINGAPORE 417813

TEL: 9627 3323 FAX: 6844 2641

CO. REG NO: 13049097L

- 1 pc Rear End panel \$649.20 ✓ Dated Date: 2010512020
- 1 pc Rear End panel Lock \$357.80 X NE Nec.
- 1 pc Rear End panel Garnish \$202.70 ✓ & End
- 4 pc Rear End panel Garnish clip \$12 ✓ Nec
- 1 pc Rear Windscreen \$1448.50 ✓ ut.
- 1 pc Rear Windscreen moulding \$121.80 ✓ Nec
- 1 pc Rear Windscreen Inner seal \$26 S/NEH ✓ Nec
- 1 pc Rear Windscreen sealant \$45 S/NEH ✓ Nec
- 1 pc Rear Sparewheel panel \$789.90 X Rpr
- 1 pc Rear Sparewheel Garnish ~~\$421.70~~ ✓ Delomed 292
- 1 pc Rear R/H Chassis Crossmember \$1276 10 X Repair
- 1 pc Rear Exhaust pipe \$780.90 ✓ Bent.
- 2 pc Rear Exhaust pipe mounting \$83.40 4170 1 piece torn.
- 1 pc Rear Reverse Camera \$130.40 X NE Nec.
- 1 pc Rear No Plate \$26 S/NEH X NE Nec
- 1 pc Rear No plate Cover \$26 S/NEH X NE Nec
- 1 pc Rear R/H Door \$1198.50 X Repair
- 1 pc Rear Bumper \$631.90 ✓ Distorted
- 8 pc Rear Bumper clip \$30.40 ✓ Nec
- 2 pc Rear Bumper Side Retainer \$240.20 ✓ Nec
- 4 pc Rear Bumper Side clip \$12.80 ✓ Nec
- 2 pc Rear Bumper Reflector \$115.40 ✓ Missing
- 1 set Rear Bumper Reverse Sensor \$321.70 ✓ Damaged
- 1 pc Rear Bumper Reinforcement Beam ~~\$421.90~~ ✓ Best 395
- 2 pc Rear Bumper Side Garnish \$114.20 X NE Nec

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE. # 02-16
SINGAPORE 417883
TEL: 9627 1321 FAX: 6844 2641
CO. REG NO: S3449097L

Nett Value
14.2K

Labour Charge for reinstall wire harness & checking
Front & Rear wiring ~~\$150~~ 60.

To Spray Painting ~~\$2,800~~ 2400.

1 Aircon Gas \$100 ✓

To Remove & Refix Rear Interior upholstery & cushion ~~\$180~~ 80.

To Remove & Refix Rear Exhaust pipe ~~\$80~~ ✓

To Remove & Refix Rear Windscreen ~~\$150~~ 120

To Conduct Chassis alignment and measurement ~~\$380~~ 200.

To apply undercoating on the repaired and replaced panels.
for rust protection ~~\$80~~ ✓

To measure, drill the replaced bumper position and reinstall
rear reverse sensor, control unit, check and test functioning
and rear reverse camera control unit ~~\$100~~ 50

Labour charge to reset fault code and carry out
diagnostic checks. ~~\$150~~ 80.

Labour charge for panel beating, welding remaining all.
damaged parts and replacing of the new parts etc..

~~\$2400~~ 2200.

\$47,860.64

List 26883.24

Labour \$450

Less 25% 20162.43

Total 25729.48

SN 117

L/S: 14.2K

21 Days