

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

Too Lang Shue

Blk 837, Tampines St 83, #07-80

Singapore 520837

Date: 20/05/2020

Accident Date: 23/11/2019

Estimate Cost of Repair Bill To Toyota Altis Car No: SKU7239S

Classic No: MR 053REH 104537482

Model: ZRE171G-GEXGKZ

1 pc Front Bonnet	\$1140.40	
2 pc Front Bonnet Hinge	\$119.20	
1 pc Front Bonnet	Insulator Garnish	\$321.70
12 pc Front Bonnet	Insulator Garnish clip	\$36.80
1 pc Front Bonnet	Rubber	\$33.10
1 pc Front Bonnet	stand clip	\$12.50
1 pc Front No. plate	\$26 s/vett.	
1 pc Front No. plate	\$20 s/vett.	
1 pc Front support panel	\$1074.60	
1 pc Front support panel lock	\$240.70	
1 pc Front support brace panel	\$101.70	
2 pc Front Fender	\$1358.20	
2 pc Front Fender	side Garnish	\$178.20
2 pc Front Fender	Emblem	\$90.40
1 pc Front wiper	Garnish	\$539.80
2 pc Front Air Bag	Sensor	\$843.40
1 pc Front Bumper	\$589.70	
8 pc Front Bumper clip	\$30.40	

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL: 9627 3323 FAX: 6844 2641

CO. REG NO: 53049097L

Date: 20/05/2020

2 pc	Front	Bumper	side, Retainer	\$170.20
4 pc	Front	Bumper	side clip	\$12.80
1 pc	Front	Bumper	Reinforcement Beam	\$371.70
1 pc	Front	Bumper	sponge	\$140.70
1 pc	Front	Bumper	Centre Grille	\$105.70
2 pc	Front	Bumper	Fog Lamp	\$643.40
2 pc	Front	Bumper	Fog Lamp Cover	\$303.20
1 pc	Front	Air	Cleaner Tank Assy	\$721.60
1 pc	Front	Intake	manifold	\$821.40
1 pc	Front	wiper	tank Assy	\$169.40
2 pc	Front	Headlamp		\$3,632.20
2 pc	Front	Headlamp	Bracket	\$118.80
1 pc	Front	Radiator		\$1510.50
1 pc	Front	Radiator	Top Upper Guide Garnish	\$99.70
1 pc	Front	Radiator	Fan Cowling	\$255.40
1 pc	Front	Radiator	Fan Blade	\$121.60
1 pc	Front	Radiator	Fan Motor	\$421.70
1 pc	Front	Radiator	Fan switch Assy.	\$551.60
1 pc	Front	Grille	\$564.80	
1 pc	Front	Grille	Emblem	\$72.10
4 pc	Front	Grille	clip	\$12.80
1 pc	Front	Grille	Rubber	\$49.10
1 pc	Front	Air Con	Condenser	\$1289.24
1 pc	Front	Air Con	discharge Hose	\$439.80
1 pc	Front	Air Con	Liquid pipe	\$625.70

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

1 pc	Front	Air Con Compressor	\$1561.70	Date : 20/05/2020
1 pc	Front	Alternator,	\$2431.90	
1 pc	Front	Fan Belt	\$127.10	
1 pc	Front	Engine Cover (Top)	\$399.10	
1 pc	Rear	Bootlid	\$740.20	
2 pc	Rear	Bootlid Hinge	\$243.40	
1 pc	Rear	Bootlid Lock	\$357.90	
3 pc	Rear	Bootlid Emblem	\$59.10	
1 pc	Rear	Bootlid Chrome moulding	\$280.70	
1 pc	Rear	Bootlid Rubber	\$184.70	
2 pc	Rear	Bootlid Reflector Lamp	\$656.20	
1 pc	Rear	Bootlid Insulator Garnish	\$421.70	
1 pc	Rear	Bootlid Insulator Garnish clip	\$27.50	
2 pc	Rear	Tail Lamp.	\$1056.20	
4 pc	Rear	Tail Lamp clip	\$14.60	
2 pc	Rear	Tail Lamp Bracket	\$84.20	
1 pc	Rear	R/H Tail Lamp panel	\$299.10	
1 pc	Rear	R/H Fender	\$1136.80	
1 pc	Rear	R/H Fender Inner Lower panel	\$121.70	
1 pc	Rear	R/H Fender Inner Trimboard	\$591.60	
8 pc	Rear	R/H Fender Inner Trimboard clip	\$30.40	
1 pc	Rear	End panel wire harness	\$321.60	
1 pc	Rear	Antenna Electrical Key sensor	\$141.90	

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL: 9627 3323 FAX: 6844 2641

CO. REG NO: 53049097L

1 pc	Rear	End panel	\$649.20	Date: 20/05/2020
1 pc	Rear	End panel, Lock	\$357.80	
1 pc	Rear	End panel	Garnish \$202.70	
4 pc	Rear	End panel	Garnish clip \$12	
1 pc	Rear	Windscreen	\$1448.50	
1 pc	Rear	Windscreen	moulding \$121.80	
1 pc	Rear	Windscreen	Inner seal \$26 s/vet	
1 pc	Rear	Windscreen	sealant \$45 s/vet	
1 pc	Rear	Sparewheel	panel \$789.90	
1 pc	Rear	Sparewheel	Garnish \$421.70	
1 pc	Rear	RIH	Classic Crossmember \$1276.10	
1 pc	Rear	Exhaust pipe	\$780.90	
2 pc	Rear	Exhaust pipe mounting	\$83.40	
1 pc	Rear	Reverse	Camera \$630.40	
1 pc	Rear	No. plate	\$26 s/vet	
1 pc	Rear	No. plate	Cover \$26 s/vet	
1 pc	Rear	RIH	Door \$1198.50	
1 pc	Rear	Bumper	\$631.90	
8 pc	Rear	Bumper clip	\$30.40	
2 pc	Rear	Bumper side Retainer	\$240.20	
4 pc	Rear	Bumper side clip	\$12.80	
2 pc	Rear	Bumper Reflector	\$115.40	
1 set	Rear	Bumper Reverse Sensor	\$321.70	
1 pc	Rear	Bumper Reinforcement Beam	\$426.90	
2 pc	Rear	Bumper side Garnish	\$114.20	

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

Labour Charge for reinstall wire hareless & checking

- 1) Front & Rear wiring \$180
- 2) To Spray Painting \$2,800
- 3) AirCon Gas \$100
- 4) To Remove & Refix Rear Interior uphosly & cushion \$180
- 5) To Remove & Refix Rear Exhaust pipe \$80
- 6) To Remove & Refix Rear windscreen \$150
- 7) To Conduct chassic alignment & mearsurement \$380
- 8) To apply undercoating on the repired & replaced panel for rust protection \$80
- 9) To measure, drill the replaced bumper position & reinstall rear reverse sensor, control unit, check & test functioning and rear reverse Camera control unit \$100
- 10) Labour Charge to reset fault code & carry out diagnostic checks \$150
- 11) Labour Charge for panel beating, welding, removing all damage parts & replacing of the new parts etc \$2,400.