

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Nov 002/2019
Date	23/11/2019
Vehicle No	BJP3288
Make / Model	Toyota Estima

To: FWD Singapore Pte Ltd

Address: 6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

Qty	DESCRIPTION	UNIT	Amount
	Items		\$ 685.00 ✓
1 pc	rear bumper <i>Distorted</i>	\$ 110.00	\$ 220.00 X
2 pc	rear bumper inner sponge <i>Not New</i>		\$ 50.00 30 ✓
1 set	rear bumper clip <i>new</i>		\$ 300.00 ✓
1 set	rear bumper reverse sensor <i>Not New Dmgd</i>		\$ 98.00 49 ✓
2 pcs	rear bumper reflector <i>Not Canted</i>		\$ 97.00 ✓
2 pcs	rear bumper side retainer <i>new</i>		\$ 60.00 ✓
1 pc	rear no. plate <i>But</i>		\$ 785.00 ✓
1 pc	rear end panel <i>Distorted</i>		\$ 286.00 ✓
1 pc	rear end panel top garnish <i>Delcd</i>		\$ 50.00 20 ✓
1 pc	rear end panel garnish clip <i>new</i>		\$ 215.00 2 ✓
1 pc	rear end panel lock sensor <i>Canted</i>		\$ 1,390.00 687 ✓
1 pc	rear compartment top board <i>Delcd</i>		\$ 265.00 ✓
1 pc	rear w/screen glass inner top garnish		\$ 255.00 ✓
1 pc	rear w/screen glass inner side garnish		\$ 50.00 ✓
1 set	rear w/screen glass inner top garnish clip		\$ 50.00 ✓
1 set	rear w/screen glass inner side garnish clip		\$ 1,865.00 ✓
1 pc	tailgate <i>Distorted</i>		\$ 1,387.00 X
1 pc	tailgate glass <i>Not New</i>		\$ 80.00 ✓
1 pc	tailgate glass sealant <i>2 new</i>		\$ 250.00 ✓
1 pc	tailgate glass moulding		\$ 75.00 ✓
1 pc	tailgate Estima emblem <i>3 new</i>		\$ 73.00 ✓
1 pc	tailgate Aeras emblem		\$ 355.00 ✓
1 pc	tailgate outer chrome handle <i>Canted</i>		\$ 276.00 ✓
1 pc	tailgate centre reflector <i>Canted</i>		\$ 674.00 ✓
2 pcs	tailgate side reflector <i>Canted</i>	\$ 337.00	\$ 704.00 ✓
2 pcs	taillamp <i>Canted</i>	\$ 352.00	\$ 565.00 ✓
1 pc	tailgate inner trim board <i>Canted</i>		\$ 50.00 30 ✓
1 set	tailgate inner trim board clip <i>new</i>		\$ 860.00 49 X
1 pc	tailgate wiper motor <i>Not New</i>		\$ 456.00 299.80 ✓
1 pc	tailgate w/strip <i>ut</i>		\$ 485.00 396.40 ✓
1 pc	tailgate inner lock <i>Dmgd</i>	1148220	\$ 54.00 ✓
1 pc	tailgate inner lock catch <i>new</i>		\$ 45.00 ✓
1 pc	tailgate inner handle cover <i>new</i>	861165	\$ 87.00 ✓
1 pc	tailgate centre emblem <i>new</i>		\$ 47.00 ✓
1 pc	o/s rear bumper tow cover <i>Delcd</i>		\$ 974.00 ✓
1 pc	o/s rear fender <i>Buckled</i>		\$ 80.00 30 ✓
1 pc	o/s rear fender glass sealant <i>new</i>		\$ 150.00 30 ✓
1 pc	o/s rear fender glass inner seal <i>new</i>		\$ 185.00 ✓
1 pc	o/s rear fender inner trim <i>Delcd</i>		\$ 985.00 755 ✓
1 pc	o/s rear fender inner garnish <i>Delcd</i>		\$ 985.00 755 ✓
1 pc	n/s rear fender inner garnish <i>Not New Canted</i>		\$ 225 ✓
1 pc	rear end panel lower garnish <i>Delcd</i>		

01
Mazda *
3

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

1	Labour Charge		\$	1,600.00	1400
2	to dismantle damaged parts, panel beat, repair		\$	1,400.00	1300
3	to putty and spray painting on affected area		\$	150.00	100
4	anti rust		\$	50.00	30
5	wiring		\$	150.00	120
6	R&R w/screen glass		\$	120.00	60
7	fender glass		\$	80.00	50
8	reverse sensor		\$	250.00	80
9	cushion seat, roof lining, carpet etc	3510	\$	80.00	✓
10	transfer tailgate fitting		\$	80.00	60
11	towing charge		\$	300.00	X
12	solar film tailgate		\$	200.00	X
13	solar film o/s rear fender glass		\$		
13	Remove fuel tank	150 80			
Subtotal:			\$	21,063.00	

14 Remove rear camera.

100 50

15 Remove air con blower

200 100

BEST SOLUTION AUTOCARE PTE LTD

Authorized Signature

Adrian Lim

H/S 27/11/19

Supplying: 1491.75 09 Days

total 13613.40

H/S 10.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Supplementary Quotation (1)

Quotation No	Nov 002/2019
Date	23/11/2019
Vehicle No	BJP3288
Make / Model	Toyota Estima

To: FWD Singapore Pte Ltd

Address: 6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

Qty	DESCRIPTION	UNIT	Amount
1	Items rear aircon blower assy <i>cracked</i>		\$ ✓ 1,989.00
		Subtotal:	\$ 1,989.00

BEST SOLUTION AUTOCARE PTE LTD



Authorised Signature

1989
1491.75