CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHB 4724M

DATE 26/11/2019 14:43 DID MAKE MODEL : HYUNDAI i40 Parts Description/ Labour **Unit Price** Amount Qty Type 2,201.10 Rear Door (RH) XIE Front Door (RH) 2,256.40 Rocker Panel Outer Garnish (RH) X 341.40 Rear Wheel Hup-Cap (RH) 107.10 4,906.00 SUB TOTAL **LESS 20%** 981.20 3,924.80 DISCOUNTED TOTAL Rear Door Advertisement Logo (RH) 100.00 Nett \$ Rear Door Comfortdelgro & Apps Sticker (RH) 80.00 Nett Front Door Coloured Comfort Logo (RH) \$ 75.00 Nett Front Door Advertisement Logo (RH) 100.00 Nett 355.00 Labour Charge 560.00 1 80 Panel Beating \$ 600.00 \$ 550 \$ Spray Painting Charge Wiring Charge 50.00 50.00 \$ 30 Tuff Kote Transfer Of Door 120.00 \$ 240.00 \$ Rear Wheel Alignment \$ 80.00 TOWING - King dolly 150-00 10 1,580.00 TOTAL LABOUR 5,859.80 ESTIMATE TOTAL Parasovana us rauto com
Parasovana us rauto com
88622718 UR LKK Auto Consultants hence notify the Repairer of the following: . To resurvey before/after splay painting To dist lay damaged part(s) during resurve · Parts prices are subject to confirmation . Third party survey is on a "Without Prejudice" . No illegal modification(s) is allowed · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

> This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



member of COMFORTDELGRO

Name of Attending Staff/Guard

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Maintine +85 6383 6280 Facsimile +85 6280 9755

Signature of Attending Staff/Guard

CUSTOMER'S COPY

Service Centres
205 Braddel Road Singapore 579701
59 Loyang Drive Singapore 508869
45 Pandah Road Singapore 809286
383 Sin Ming Drive Singapore 578717
50 Lipis Radut Way Singapore 728791
24 Senoko Loop Singapore 758156





IOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

| b Requisition | | 4. Type of Towing: No key |
|---|---|---|
| Date: 25 11 2019 Time Received: 1610 | 3. Vehicle Type: | Normal Tow-Ithous Boarce |
| ☐ New ☐ SPARK Kakis | Taxi (CTPL/CCPL) | King Dolly PARKED |
| Name of Customer : MR TSU | Fleet | Flat Bed NEXT TO |
| Contact No. : 9651 6920 | STK (Boon Lay) | WINCH OUT. CLOS |
| Vehicle No. : SHB 4724M | 5. Nature of Service: | 6. Parts Replaced/Remarks: |
| Make/Model/Colour: + Hyunda 140 | Jumpstart Recovery | BY OMBULANCE |
| Email : | Change Tyre / Battery | |
| Location: | 8. \ | /ehicle Tow - In Workshop: |
| SUNTER CITY TOWER 3 | | Smoky Exhaust Wheel Jammed Overheating Steering Faulty |
| Preferred Workshop: | _ | ☐ Overheating☐ Steering Faulty☐ Alternator Faulty |
| Braddell Loyang | Pandan | Starting Problem Loss Power |
| Sin Ming Sungei Kadut | Ubi Cycle & Carriage (PD) | Accident Engine Stalled |
| Senoko | Cycle & Carriage (FD) | Return Taxi |
| Others: | | |
| Odometer Reading : | 11. Radio / CD Play | /er |
| 0/ | ОК | |
| Fuel Level : F 1/4 1/2 3/4 E | Faulty | |
| Fuel Level | Not teste | d |
| b Attended | | NO. |
| | GAO TZ YISHUN | OTHERS OF THE OTHERS |
| . low mack/ necovery van vne | TOWING | |
| Name of Driver : Tho MAS | | HEAR (|
| Vehicle No. : GZ8458 | | #: Cracked X: Dented |
| Time Dispatch : Ibro | | / : Scatched O : Missing |
| Time of Arrival : | | |
| Time Completed : | | Signature of Customer |
| sh Invoice Details (if applicable) | | |
| . Cash Invoice No. : | | |
| ustomer Acknowledgement | | |
| I have been advised to remove all valuable items in my vehicle, incash cards, spectacles, pen, etc. | | |
| understand that any items left behind are at my own risk and SP | ARK Car Care™ will not be held liable | for such losses. |
| Surcharge: Towing fee will be levied if the customer decides neith | ier to tow nor proceed with the repairs | |
| | | -2.3 |
| - 11 .0 | ×0 | |
| 25/1/2019 | | |
| 25/11/2019 188 | me | Signature of Customer |

Date & Time of Arrival