

ASS. REC. BY:

REF:

03/MSG19021002/K/sd301

Special Instruction:

Survey: Rasul

ASSIGNMENT (Office)

Insured (Person): Crystal Lee

of

M81G

Date/Time: 27/11/11 @ 2:23pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To inspect Vehicle No.:

SLE 6073G

Insured:

at Workshop m/s

Hitachi Capital

Tel:

6833 6282

of

8 Fourth Lok yang Road

Policy No.:

Claim No.:

Sum Insured:

Excess:

TBA \$1,500/-

Make of Veh:

(Client's Record)

D.O.A.

23/11/11

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:40pm @ 27/11/11

Person Contacted:

Jiong How

Vehicle: IN/OUT

Date/Time

Action/Instruction

Follow up ✓

SLE 6073G-X

28/11/11

Revert to Crystal by email

03/12/11

@ 09:45 am mandate approved by Jocelyn Ng via meimer.

03/12/11

@ 10:22 am informed CIA to Jiong How via email.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	399N
Vehicle Details	
Vehicle No.:	SLE6073G
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1ZR589100
Chassis No.:	MR053REH104555901
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	27 Jul 2016
First Registration Date:	27 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$16,800.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2026
PARF Rebate Amount:	\$12,600.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$35,291.00
Total Rebate Amount:	\$47,891.00

The information contained herein is correct as at 28 Nov 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 6 January 2020 3:41 pm
To: JiongHow, Ng
Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim; SUR
Subject: RE: SLE6073G OD CLAIM DOA: 23/11/2019

Dear Jiong How,

Confirmed final fig \$ 5,613.14 @ 12 days of repairs before excess \$ 1,500/- & GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

"Wishing you a Happiness and Prosperity New Year"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Sent: Monday, 30 December 2019 5:46 pm
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: SLE6073G OD CLAIM DOA: 23/11/2019

Dear all,

Please confirm COR @ \$5613.14 Before GST & Excess

12 days repair

Before paint photos attached.

Regards

Ng Jiong How

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 3 December 2019 10:22 am
To: JiongHow, Ng
Cc: SUR; Jamilah, Binte MohdKassim; Vonn, LM Siow
Subject: RE: SLE 6073G OD (MSIG)

Hi Jiong How,

As instructed by our client, please proceed to repair the insured vehicle **SLE 6073G (Excess S 1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Sent: Monday, 2 December 2019 1:28 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Subject: RE: SLE 6073G OD (MSIG)

Hi Shirley,

Merimen estimate amendment done.

Thank you

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6282
e: jionghow.ng@hcspl.com.sg
w: www.hitachi-capital.com.sg



DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.
This email is intended solely for the attention and use of the name addressee(s).
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.
If you have received this email in error, please notify the sender immediately by email and delete it from your system.

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, December 2, 2019 11:30 AM
To: JiongHow, Ng <jionghow.ng@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Subject: SLE 6073G OD (MSIG)

Dear Jiong How,

Please call back me urgently.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: ShirleyHiew@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 28 November 2019 9:48 AM
To: 'Crystal Lee'; SUR
Cc: 'Ong Zi Hui'
Subject: RE: Survey Request - Manual Assigned-SLE 6073G
Attachments: MARK EST.pdf; photo.pdf; PRELI REVISED.pdf

Dear Crystal,

Enclosed preliminary revised of vehicle SLE 6073G
Date of survey: 27/11/2019
Number of days (estimated) :12 days

We have Not authorise repair.

Kindly let us have your approval and create claim in merimen.

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 27 November 2019 3:24 PM
To: 'Crystal Lee' <crystal_lee@sg.msigs-asia.com>; assignments <assignments@lkkauto.com>
Cc: 'Ong Zi Hui' <zihui_ong@sg.msigs-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey Request - Manual Assigned

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Crystal Lee [mailto:crystal_lee@sg.msigs-asia.com]
Sent: Wednesday, 27 November 2019 2:23 PM

To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: Survey Request - Manual Assigned

SLE6073G OD CLAIM DOA: 23/11/2019

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Motor Survey

Sent: Wednesday, 27 November, 2019 1:56 PM

To: Jeannie Cheng <jeannie_cheng@sg.msig-asia.com>

Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: SLE6073G OD CLAIM DOA: 23/11/2019 (Folder in merimen-Car in, please outsource. Tks.)

Dear Jeannie,

The folder was in on 26/11/2019 @ 3.33pm.

Please assign to IHS soonest for us to outsource.

Dear Crystal,

Please outsource this case manually first to external surveyor.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG



A Member of **MS&AD** INSURANCE GROUP

From: JiongHow, Ng [<mailto:jionghow.ng@hcspl.com.sg>]
Sent: Wednesday, 27 November 2019 1:36 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Subject: SLE6073G OD CLAIM DOA: 23/11/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

Please refer to the subject above.

Vehicle in workshop.

Please arrange.

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6282
e: jionghow.ng@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.
This email is intended solely for the attention and use of the name addressee(s).
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.
If you have received this email in error, please notify the sender immediately by email and delete it from your system.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED

Our ref: CS/MSG19021002/R1sd3

Date: 28/11/2019

The Motor Claims Department
M/s MSIG INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO: SLE 6073G


We thank you for your instruction on 27/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/11/2019 at the premises of M/s HITACHI CAPITAL ASIA PACIFIC PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$10,211.90
Revised Estimate Amount	: S\$6,125.40
"Check" Items Amount	: S\$1,738.00
Total	: S\$7,863.40
Market Value	: S\$64,000.00
LTA Reimbursement Value	: S\$47,891.00
Nett Value	: S\$16,109.00

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:

Damages Consistent
Repair Cost Economical

Yours faithfully,

MOHAMMED RASUL

Automotive Assessor

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Wednesday, 27 November 2019 2:23 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: SAS2708094.PDF; SLE6073G_26112019.pdf

SLE6073G OD CLAIM DOA: 23/11/2019

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Motor Survey
Sent: Wednesday, 27 November, 2019 1:56 PM
To: Jeannie Cheng <jeannie_cheng@sg.msig-asia.com>
Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: SLE6073G OD CLAIM DOA: 23/11/2019 (Folder in merimen-Car in, please outsource. Tks.)

Dear Jeannie,

The folder was in on 26/11/2019 @ 3.33pm.

Please assign to IHS soonest for us to outsource.

Dear Crystal,

Please outsource this case manually first to external surveyor.

Best Regards

Winnie Chua



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: JiongHow, Ng [<mailto:jionghow.ng@hcspl.com.sg>]
Sent: Wednesday, 27 November 2019 1:36 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Subject: SLE6073G OD CLAIM DOA: 23/11/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

Please refer to the subject above.

Vehicle in workshop.

Please arrange.

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6282
e: jionghow.ng@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

View Received Message

This mail is associated with :

SLE6073G (MSC/V/19-001379)
OD
Nov 23 2019 2:00PM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 06/01/2020 15:02 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5613.14) - SLE6073G - Claim Handler: Jeannie Cheng Jin Rong

Approved:5613.14:a if c

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :
SLE6073G (MSC/V/19-001379)
OD
Nov 23 2019 2:00PM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From **MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG)**, sent on **03/12/2019 09:45 AM.**
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$6125.40) - SLE6073G - Claim Handler: Jeannie Cheng Jin Rong**

Approved:6125.40:a lf c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 03 Jan 2020

Preliminary Advice

Vehicle No	: SLE6073G	Accident Date	: 23/11/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MSD/VPCP/19-000825-00
Assignment Date	: 28/11/2019	Excess	: S\$1,500.00
Date of Inspection	: 27/11/2019	Est. Duration of Repair	: 12 days
Inspection At	: Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,211.90
Revised Amount	:S\$	5,613.14
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,613.14

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	47,891.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,109.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 02 Dec 2019

Preliminary Advice

Vehicle No	: SLE6073G	Accident Date	: 23/11/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MSD/VPCP/19-000825-00
Assignment Date	: 28/11/2019	Excess	: S\$1,500.00
Date of Inspection	: 27/11/2019	Est. Duration of Repair	: 12 days
Inspection At	: Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,211.90
Revised Amount	:S\$	6,125.40
Check Items (Estimated)	:S\$	1,738.00
Total	:S\$	7,863.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	47,891.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,109.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2019 16:20
Date Of Accident	23/11/2019 14:15
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE6073G
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VPCP/19-000825-00
Cover Note Number	

Driver

Name of Driver	POO CHI-MENG
NRIC No	S7429243G
Date Of Birth	02/09/1974
Occupation	OUTDOOR
Date Of Driving Pass	13/11/1997
Driving Experience	22 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98508852
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 17A TELOK BLANGAH CRESCENT #23-270
Postcode	091017
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD1564S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ANG GHIM SENG
NRIC/Passport Number	S7103631F
Contact Number	96363987
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJK8726K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD LYAS BIN BUANG
NRIC/Passport Number	S8946332G
Contact Number	82889844
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(if driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Sketch Plan Pg. 2

Towards Chongji



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the date 23/11/2019 time 2:15 pm was driving along P1E towards chongji near exit 9 on the first Right lane suddenly a taxi cab in front of me brake i cant stop my car and hit the back of the taxi cab and my back of my car got hit by another Honda car.

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature

Date & Time

Driver's Signature

(if driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name

NRIC/FIN No.:

Hitachi Capital Asia Pacific Pte Ltd
8 Fourth Lok Yang Road
629705

Insurer Reference: SLE6073G

Repairer Reference: 022591

Date calculated: 26/11/2019 3:26 PM

Full Report

Registration: SLE6073G

Printed: 26/11/2019 3:27 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Jiong How	Currency:	SGD
Claim Reference:	SLE6073G	Date of Incident:	23/11/19
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA
Sub Model:	ALTIS CLASSIC
Model Sheet Number:	70 EW 20
Registration:	SLE6073G
VIN number:	
Odometer:	

Model Specs

SINGAPORE VERSION	AUTO AIR CON	FOG LAMPS	1.6 LTR 97KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description	WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: FRONT BUMPER, BOTH FOG LAMPS AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: RADIATOR GRILLE REMOVE AND REFIT	10.0	50.00
B030	R + R RADIATOR GRILLE	1.0	5.00
B020)	RENEW FRONT BUMPER REINFORCEMENT (BUMPER REMOVED) INCLUDES: FRONT BUMPER ABSORBER REMOVE AND REFIT	1.0	5.00
NO NUMBER	R + R FRONT BUMPER IMPACT DAMPER	1.0	5.00
B040	RENEW BOTH HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS	7.0	35.00
B110	RENEW L/FRT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: L/F WHEELHOUSE COVER AND REQUIRED ATTACHED PARTS R + R.	6.0	30.00
B110	RENEW R/FRT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R/F WHEELHOUSE COVER AND REQUIRED ATTACHED PARTS R + R.	6.0	30.00
B070	RENEW BONNET INCLUDES: R + R BONNET NOT INCLUDED: INSULATION BONNET REMOVE AND REFIT.	4.0	20.00
B080	R + R BONNET HINGE/S	1.0	5.00
530121)	R + R BONNET OPENER CABLE	3.0	15.00 X
B060	R + R ENGINE COMPARTMENT INSULATION	1.0	5.00
B140	RENEW FRONT PANEL CPL	26.0	130.00
B190	R + R SILL MOULDING	1.0	5.00 X
B190	R + R RIGHT SILL MOULDING	1.0	5.00 X
B310)	RENEW L/R SIDE PANEL INCLUDES: TAILLAMP AND ALL TRIMS IN REPAIR AREA R + R NOT INCLUDED: REAR SEAT AND REAR BUMPER REMOVE AND REFIT	62.0	310.00 X
B310)	RENEW R/R SIDE PANEL INCLUDES: TAILLAMP AND ALL TRIMS IN REPAIR AREA R + R NOT INCLUDED: REAR SEAT AND REAR BUMPER REMOVE AND REFIT	59.0	295.00 X
B290	RENEW END PANEL (REAR BUMPER REMOVED) INCLUDES: BOOT COMPARTMENT FLOOR MAT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT NOT INCLUDED: R + R REAR SEAT	44.0	220.00 X
NO NUMBER	R + R COMPLETE REAR SEAT CUSHION	1.0	5.00 X
B450	R + R SEAT BACKREST CPL	2.0	10.00 X
B360	RENEW BOOTLID INCLUDES: BOOTLID, TRIM BOOTLID, BOTH INN TAILLAMPS, BOTH NUMBER PLATE LAMP, LOCK	11.0	55.00 X



Code	Description	WU	Price SGD
	BOOTLID AND REQUIRED ATTACHED PARTS R + R		
B370	R + R L/BOOTLID HINGE	1.0	5.00
B370	R + R R/BOOTLID HINGE	1.0	5.00
G020	REAR SCREEN R + R	30.0	150.00
	INCLUDES: HI-LEVEL BRAKELAMP AND REQUIRED ATTACHED PARTS R + R		
	NOT INCLUDED: HEADLINING REMOVE AND REFIT		
B420	RENEW REAR BUMPER	6.0	30.00
	INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R		
B410	R + R REAR BUMPER REINFORCEMENT	1.0	5.00
NO NUMBER	R + R EVAPORATOR/COMPRESSOR LINE	4.0	20.00
M010	DRAIN AIR CONDITIONING	3.0	15.00
NO NUMBER	R + R EVAPORATOR HOSES	4.0	20.00
M010	RENEW AIR CONDITIONING CONDENSER	11.0	55.00
	INCLUDES: DRAIN + REFILL AIR CONDITIONING FLUID		
M020	RENEW RADIATOR	8.0	40.00
	INCLUDES: BLEED COOLING SYSTEM		
160101)	R + R UPPER RADIATOR HOSE	1.0	5.00
160111)	R + R LOWER RADIATOR HOSE	1.0	5.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		31.90	319.0
Total of Labour			1,595.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	23.0 ✓
	L/F WING NEW PART PAINTING	10.0 ✓
	R/F WING NEW PART PAINTING	10.0 ✓
	LOCK CARRIER STRUT SURFACE PAINT	4.0 ✓
	INNER FRT PANEL CPL SURFACE PAINT	6.0 ✓
	REAR PANEL NEW PART PAINTING	24.0 ✓
	BOOTLID NEW PART PAINTING	17.0 ✓
	L/R SIDE PANEL NEW PART PAINTING	32.0 ✓
	R/R SIDE PANEL NEW PART PAINTING	32.0 ✓
	FRONT BUMPER NEW PART PAINT K1G	19.0 ✓
	REAR BUMPER NEW PART PAINT K1G	26.0 ✓

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	73.27
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
0988	LOCK CARRIER STRUT SURFACE PAINT	1.25
1009	INNER FRT PANEL CPL SURFACE PAINT	13.94
2711	REAR PANEL NEW PART PAINTING	22.12 30.80

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID NEW PART PAINTING	37.92 49.54
3481	L/R SIDE PANEL NEW PART PAINTING	20.67 45.65
3482	R/R SIDE PANEL NEW PART PAINTING	20.67 45.65
0281	FRONT BUMPER NEW PART PAINT K1G	60.10
2581	REAR BUMPER NEW PART PAINT K1G	86.18

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			203.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.80	8.0	40.00
Total	10 WU/h	23.60	236.0	1,180.00

Material Cost - Paint

	Price SGD
New Part Painting	281.03
New Part Painting - Plastic K1G	146.28
Surface-/Blend Paint	15.19
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	483.80

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0251	LWR RADIATOR GRILLE	53112 02630	? x suv		50.00
0281	FRONT BUMPER	52119 02955	de -		180.00
0317	L/F BUMPER BRACKET	52116 02270	ra -		28.00
0318	R/F BUMPER BRACKET	52115 02270	ra -		28.00
0340	FRT BUMPER REINF	52131 02190	bt -		110.00
0341	FRT BUMPER ABSORBER	52611 02310	de -		45.00
0410	FRONT GRILLE	53100 02670	cm -		150.00
0471	BONNET	53301 02310	bt -		280.00
0475	L/BONNET HINGE	53420 02360	bt -		25.00
0476	R/BONNET HINGE	53410 02360	bt -		25.00
0481	BONNET INSULATION	53341 02290	de -		110.00
0493	BONNET LOCK	53510 02660	bt -		50.00
0500	BONNET CABLE	53630 02310	x suv		30.00
0563	L/HEADLAMP COVER	53182 02070	? x suv		60.00
0564	R/HEADLAMP COVER	53181 02070	? x suv		60.00
0565	LEFT HEADLAMP ASSY	81170 02F50	cm -		260.00
0566	RIGHT HEADLAMP ASSY	81130 02F50	cm -		260.00
0741	L/F WING	53802 02220	bt -		200.00
0742	R/F WING	53801 02240	bt -		200.00
0813	L/F WING BADGE	75444 02A20	net -		20.00
0814	R/F WING BADGE	75444 02700	net -		20.00
0841	L/F WHEELHOUSE COVER	53876 02570	x suv		55.00
0842	R/F WHEELHOUSE COVER	53875 02540	x suv		55.00

Code	Description	Part Number	Supplier	Price SGD
0847	L/CLIP	90467 07215	ne	15.00
0848	R/CLIP	90467 07215	ne	15.00
0988	LOCK CARRIER STRUT	53208 02210	bt	35.00
1009	INNER FRT PANEL CPL	53201 02370	bt	200.00
2581	REAR BUMPER	52159 02904	de	180.00
2617	L/R UPP BUMPER BRKT	52563 02250	ne	40.00
2618	R/R UPP BUMPER BRKT	52562 02250	ne	40.00
2619	L/R BUMPER BRACKET	52576 02140	ne	30.00
2620	R/R BUMPER BRACKET	52575 02140	ne	30.00
2640	REAR BUMPER REINF	52023 02190	bt	110.00
2711	REAR PANEL	58307 02380	repair	220.00
2931	BOOTLID	64401 02B61	repair	260.00
2953	L/BOOTLID HINGE	64503 02180	x sue	35.00
2954	R/BOOTLID HINGE	64503 02180	x sue	35.00
2977	BOOTLID LOCK	64600 02080	cul	130.00
3015	REAR MANUFACT BADGE	75431 02090	ne	30.00
3017	BADGE MODEL	75442 02320	ne	25.00
3022	VERSION BADGE	75442 02340	ne	20.00
3160	REAR SCREEN BOND KIT	PZ49I 00C1131	XAN	0.00
3165	REAR SCREEN SPACER	56116 22050	XAN	0.00
3166	REAR SCREEN SPACER	56115 30120	XAN	0.00
3170	REAR SCREEN SEAL	64813 02200	XAN	0.00
3339	L/R REFLECTOR	81920 02110	x sue	25.00
3340	R/R REFLECTOR	81910 02170	x sue	25.00
3481	L/R SIDE PANEL	61602 02280	x sue	420.00
3482	R/R SIDE PANEL	61601 02270	x sue	420.00
3685	L/R MUDFLAP FRONT	65632 02260	x sue	25.00
3686	R/R MUDFLAP FRONT	65631 02260	x sue	25.00
4465	CONDENSER CPL	88450 02350	bt	270.00
4483	EVAPORATOR OUTL PIPE	88710 02700	bt	180.00
4490	EVAP/COMPR PIPE	88707 02260	bt	180.00
4985	INNER END PANEL TRIM	58387 02240	bt	90.00
7761	RADIATOR	16410 0D390	bt	350.00
7767	FAN HOUSING	16711 0T101	bt	80.00
7768	UPP RADIATOR SHROUD	16712 0D150	bt	55.00
7773	L/RADIATOR HOSE	16573 0D100	X	20.00
7776	R/RADIATOR HOSE	16572 0T130	X	20.00
7787	EXPANSION TANK	16470 0D050	X	55.00
7793	COOLING FAN	16361 0D201	bt	55.00
7797	FAN MOTOR	16363 0T140	X	150.00
9630	UPP BATTERY BRACKET	74404 02550	bt	15.00
9631	BATTERY HOLDER	74431 02280	bt	40.00
1000	umper Clips (10)	FRT Bump Clips	ne	15.00
1001	p Garn Clips (10)	Spt Up Gar Clip	ne	15.00
1002	t Insu Clips (10)	Bonnet Ins Clip	ne	15.00
1003	Bonnet Holder	Bonnet Holder	x sue	10.00
1004	RR Bumper Clips (10)	RR Bumper Clips	ne	15.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	6,321.00
Addition(+10.00%)	632.10
Total	6,953.10

Final Calculation


	SGD	SGD
Parts		
Addition(+10.00%)	6,321.00	
	632.10	
Total Parts		6,953.10
Labour Time Base 10 WU/h		
Total 319.0 WU X 50.00 SGD/h	1,595.00	
Total of Labour		1,595.00
Paint Work Time Base 10 WU/h		
Labour Cost 236.0 WU X 50.00 SGD/h	1,180.00	
Material Cost	483.80	
Total Paint Including Material		1,663.80
Repair Cost Excludes GST		10,211.90
GST (+7.0%)		714.83
Repair Cost Included GST		10,926.73

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



[Handwritten signature]
3/12/19

HP 90010068

12 days

P/P

27/11/19 @1620

EXCESS: TBA

REVERT

Resurvey before paint

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: SLE6073G
Repairer Reference: 022591
Date calculated: 03/01/2020 10:11 AM

Full Report
Registration: SLE6073G
Printed: 03/01/2020 10:11 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	SLE6073G	Date of Incident:	23/11/19
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	TOYOTA		
Model:	COROLLA		
Sub Model:	ALTIS CLASSIC		
Model Sheet Number:	70 EW 20		
Registration:	SLE6073G		
VIN number:			
Odometer:			
Model Specs			
SINGAPORE VERSION	AUTO AIR CON	FOG LAMPS	1.6 LTR 97KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: FRONT BUMPER, BOTH FOG LAMPS AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: RADIATOR GRILLE REMOVE AND REFIT		10.0	50.00
B030	R + R RADIATOR GRILLE		1.0	5.00
B020)	RENEW FRONT BUMPER REINFORCEMENT (BUMPER REMOVED) INCLUDES: FRONT BUMPER ABSORBER REMOVE AND REFIT		1.0	5.00
NO NUMBER	R + R FRONT BUMPER IMPACT DAMPER		1.0	5.00
B040	RENEW BOTH HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		7.0	35.00
B110	RENEW L/FRT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: L/F WHEELHOUSE COVER AND REQUIRED ATTACHED PARTS R + R.		6.0	30.00
B110	RENEW R/FRT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R/F WHEELHOUSE COVER AND REQUIRED ATTACHED PARTS R + R.		6.0	30.00
B070	RENEW BONNET INCLUDES: R + R BONNET NOT INCLUDED: INSULATION BONNET REMOVE AND REFIT.		4.0	20.00
B080	R + R BONNET HINGE/S		1.0	5.00
B060	R + R ENGINE COMPARTMENT INSULATION		1.0	5.00
B140	RENEW FRONT PANEL CPL		26.0	130.00
NO NUMBER	R + R BOOTLID TRIM		2.0	10.00
640201)	R + R BOOTLID LOCK		3.0	15.00
750171	RENEW BADGE "TOYOTA"		4.0	20.00
750171	RENEW TYPE BADGE		4.0	20.00
B420	RENEW REAR BUMPER INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R		6.0	30.00
NO NUMBER	R + R L/R BUMPER BRACKET		1.0	5.00
NO NUMBER	R + R R/R BUMPER BRACKET		1.0	5.00
B410	R + R REAR BUMPER REINFORCEMENT		1.0	5.00
M010	DRAIN AIR CONDITIONING		3.0	15.00
M010	RENEW AIR CONDITIONING CONDENSER INCLUDES: DRAIN + REFILL AIR CONDITIONING FLUID		11.0	55.00
M020	R + R RADIATOR INCLUDES: BLEED COOLING SYSTEM		5.0	25.00
2711	REAR PANEL REPAIR		20.0*	100.00
2931	BOOTLID REPAIR		10.0*	50.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	13.50	135.0	675.00
Total of Labour			675.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	23.0	
	L/F WING NEW PART PAINTING	10.0	
	R/F WING NEW PART PAINTING	10.0	
	LOCK CARRIER STRUT SURFACE PAINT	4.0	
	INNER FRT PANEL CPL SURFACE PAINT	6.0	
	FRONT BUMPER NEW PART PAINT K1G	19.0	
	REAR BUMPER NEW PART PAINT K1G	26.0	
	REAR PANEL REPAIR PAINTING >50%	19.0	
	BOOTLID REPAIR PAINTING >50%	27.0	
	L/R SIDE PANEL SURFACE PAINT	8.0	
	R/R SIDE PANEL SURFACE PAINT	8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	73.27
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
0988	LOCK CARRIER STRUT SURFACE PAINT	1.25
1009	INNER FRT PANEL CPL SURFACE PAINT	13.94
0281	FRONT BUMPER NEW PART PAINT K1G	60.10
2581	REAR BUMPER NEW PART PAINT K1G	86.18
2711	REAR PANEL REPAIR PAINTING >50%	22.12
2931	BOOTLID REPAIR PAINTING >50%	37.92
3481	L/R SIDE PANEL SURFACE PAINT	20.67
3482	R/R SIDE PANEL SURFACE PAINT	20.67

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		160.0	
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.80	8.0	40.00
Total	10 WU/h	19.30	193.0

Material Cost - Paint

	Price SGD
New Part Painting	109.39
New Part Painting - Plastic K1G	146.28
Repair Painting	60.04
Surface-/Blend Paint	56.53
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	413.54

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER	52119 02955		180.00
0317	L/F BUMPER BRACKET	52116 02270		28.00
0318	R/F BUMPER BRACKET	52115 02270		28.00
0340	FRT BUMPER REINF	52131 02190		110.00
0341	FRT BUMPER ABSORBER	52611 02310		45.00
0410	FRONT GRILLE	53100 02670		150.00
0471	BONNET	53301 02310		280.00
0475	L/BONNET HINGE	53420 02360		25.00
0476	R/BONNET HINGE	53410 02360		25.00
0481	BONNET INSULATION	53341 02290		110.00
0493	BONNET LOCK	53510 02660		50.00
0565	LEFT HEADLAMP ASSY	81170 02F50		260.00
0566	RIGHT HEADLAMP ASSY	81130 02F50		260.00
0741	L/F WING	53802 02220		200.00
0742	R/F WING	53801 02240		200.00
0813	L/F WING BADGE	75444 02A20		20.00
0814	R/F WING BADGE	75444 02700		20.00
0847	L/CLIP	90467 07215		15.00
0848	R/CLIP	90467 07215		15.00
0988	LOCK CARRIER STRUT	53208 02210		35.00
1009	INNER FRT PANEL CPL	53201 02370		200.00
2581	REAR BUMPER	52159 02904		180.00
2617	L/R UPP BUMPER BRKT	52563 02250		40.00
2618	R/R UPP BUMPER BRKT	52562 02250		40.00
2619	L/R BUMPER BRACKET	52576 02140		30.00
2620	R/R BUMPER BRACKET	52575 02140		30.00
2640	REAR BUMPER REINF	52023 02190		110.00
2977	BOOTLID LOCK	64600 02080		130.00
3015	REAR MANUFACT BADGE	75431 02090		30.00
3017	BADGE MODEL	75442 02320		25.00
3022	VERSION BADGE	75442 02340		20.00
4465	CONDENSER CPL	88450 02350		270.00
9630	UPP BATTERY BRACKET	74404 02550		15.00
1004	RR Bumper Clips (10)	RR Bumper Clips		15.00
1005	FRT BUMPER CLIPS	umper Clips(10)		15.00
1006	SPT UP GAR CLIP	p Garn Clips 10		15.00
1007	BONNET INS CLIP	t Insu Clips 10		15.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	3,236.00
Addition(+10.00%)	323.60
Total	3,559.60

Final Calculation

	SGD	SGD
Parts	3,236.00	
Addition(+10.00%)	323.60	
Total Parts		3,559.60
Labour Time Base 10 WU/h		
Total 135.0 WU X 50.00 SGD/h	675.00	
Total of Labour		675.00
Paint Work Time Base 10 WU/h		
Labour Cost 193.0 WU X 50.00 SGD/h	965.00	
Material Cost	413.54	
Total Paint Including Material		1,378.54
Repair Cost Excludes GST		5,613.14
GST (+7.0%)		392.92
Repair Cost Included GST		6,006.06

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

LS: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

ALTI5

MR HOW

NO: DL19225508

PAGE 1

DATE 09/12/2019

A/C CODE LDHC008

TERMS: CR

VEH NO: SLE6073G

Part No	Description	Location	Qty	Unit Price	Amount
68450-02350	CONDENSER / 4465	DB2C	1	270.00	270.00
TOTAL QUANTITY:			1	TOTAL	SIN 270.00
				ADD GST @ 7%	18.90
				GRAND TOTAL	<u>SIN 288.90</u>

O/R:
IR WENG

Int / LSK / 9/12/2019 12:59:04 PM

ALESMA: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E A O E

GOODS RECEIVED BY





HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

ALTS

MR HOW

NO: DLI9215485

PAGE: 1

DATE: 09/12/2019

A/C CODE: LDHC008

TERMS: /CR

VEH NO: SLE6073G

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
T53410-02360 ✓	BONNET HINGE RH / 0475	DU1AD33-2	1	25.00	25.00
T53420-02360 ✓	BONNET HINGE LH / 0476	DU1AD33-6	1	25.00	25.00
T53801-02240	FENDER FR RH / 0742	DB1D41	1	200.00	200.00
T52023-02190	BUMPER REINF REAR / 2640	DB1U6L	1	110.00	110.00
TOTAL QUANTITY:			4	TOTAL	SIN 360.00
				ADD GST @ 7%	25.20
				GRAND TOTAL	<u>SIN 385.20</u>



TO/R:
MR WENG

int / LSK / 9/11/2019 9:48:32 AM

ALESMA LSK

this document is computer generated No signature required

GOODS SOLD ARE NOT RETURNABLE

E & O E

GOODS RECEIVED BY





HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

SLE6073G

HOW

NO: DL19225275

PAGE: 1

DATE: 03/12/2019

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLE6073G

[Handwritten signature]

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
T52119-02955 ✓	BUMPER FR / 0281	OB2G	1	180.00	180.00
T52161-16010-1 ✓	CLIP,FR BUMPER / 1503	DU1AD11-3	10 ✓	1.50	15.00
T52115-02270 ✓	6317 BUMPER RETAINER FR RH /	DU1AD28-4	1 ✓	28.00	28.00
T52116-02270 ✓	0319 BUMPER RETAINER FR LH /	DU1AD44-1	1 ✓	28.00	28.00
T52131-02190 ✓	BUMPER REINE FR / 0340	OB1E33	1	110.00	110.00
T52611-02310 ✓	BUMPER SPONGE FR / 0341	OB3AA	1	45.00	45.00
T53100-02760 ✓	GRILLE / 0410	OB2H	1	150.00	150.00
T81130-02F31 ✓	H/LAMP RH / 0566	OB2G	1	260.00	260.00
T81150-02F30 ✓	ASSY HEADLAMP LH / 0565	OB2BB18	1	260.00	260.00
T53208-02210 ✓	BRACE PANEL / 0988	DU1E33-2	1 ✓	35.00	35.00
T53201-02370 ✓	1009 SUPPORT PANEL / Return	OB1F13	1	200.00	200.00
T52161-0K040 ✓	1001 CLIP,SUPPORT GARNISH /	DU1AD10-10	10 ✓	1.50	15.00
T53301-02310 ✓	BONNET / 0471	DDS	1	280.00	280.00
T53510-02670 ✓	BONNET LOCK / 0493	DU1B86	1 ✓	50.00	50.00
3341-02290 ✓	BONNET INSULATOR / 0481	OB2K2	1	110.00	110.00
T90467-09050 ✓	CLIP,INSULATOR / 1002	DD1AS3-6	10	1.50	15.00
T90467-07214 ✓	CLIP,COWLING / 0471/0448	DD1AS3-6	20	1.50	30.00
T53802-02220 ✓	FENDER FR LH / 0741	DDS	1	200.00	200.00
T75444-02700 ✓	FENDER PLATE RH (DUAL VTTI) / 0813	DD1AS2-20	1	20.00	20.00
T75444-02A20 ✓	VVTT LH / 0814	DDS	1	20.00	20.00
T74404-02550 ✓	BATTERY CLAMP / 9630	DU1D40-3	1	15.00	15.00

int / MT / 03/12/2019 1:55:35 PM

Cont'd





HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

NO: DL19225275

PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
T52159-02904 ✓	BUMPER RR / 2581	DDS	1	180.00	180.00
T52161-16010-1 ✓	CLIP,RR,BUMPER / 1004	DU1AD11-3	10 ✓	1.50	15.00
T52575-02140 ✓	2618 BUMPER RETAINER RR RH ✓	DU1AD27-1	1 ✓	40.00	40.00
T52576-02140 ✓	2617 BUMPER RETAINER RR LH ✓	DU1AD23-1	1 ✓	40.00	40.00
T52181-02190 ✓	2620 RR BUMPER BRACKET RH ✓	DU1C55-2	1 ✓	30.00	30.00
T52182-02160 ✓	2619 BKT LH ✓	DU1D55-2	1 ✓	30.00	30.00
4600-02080 ✓	2771 BOOT INNER LOCK ✓	DU1B1	1 ✓	130.00	130.00
T75431-02090 ✓	3015 BOOT LOGO ✓	DU1AS3-38	1 ✓	30.00	30.00
T75442-02330 ✓	3017 COROLLA LOGO ✓	DU1AS3-22	1 ✓	25.00	25.00
T75442-02340 ✓	3022 ALTIS LOGO ✓	DU1AS3-23	1 ✓	20.00	20.00
TOTAL QUANTITY:			86	TOTAL	SIN 2,606.00
				ADD GST @ 7%	182.42
				GRAND TOTAL	<u>SIN 2,788.42</u>

int / MT / 03/12/2019 1:55:35 PM

LES MAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2019 Sendback Est	02 Dec 2019 13:27 S\$10,211.90	28 Nov 2019 10:02 Edit Adj Rpt	S\$5,613.14 Edit Estimates	S\$5,613.14 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SLE6073G	Date of Loss:	23/11/2019 14:00 - :59 [39 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / MSC/V/19-001379	Policy/Cover Note No.:	MSD/VPCP/19-000825-00 (Comprehensive) Coverage: 01/06/2019 - 31/05/2020						
		Excess:	S\$1,500.00						
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jeannie Cheng Jin Rong - 6594 2537]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/12/2019]								
Driver/Custodian:	POO CHI-MENG (45 / Male) , NRIC: S7429243G, Tel: +6598508852 Email: NOEMAIL								
Adj Asg. Remarks:	Car in. Manual assigned to LKK via email on 27/11/19. Survey and revert. manual assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (06/01/2020): Alert - Adj Mandate Approved (S\$5613.14) - SLE6073G - Claim Handler: Jeannie Che... - MSIG_SG (03/12/2019): Alert - Adj Mandate Approved (S\$6125.40) - SLE6073G - Claim Handler: Jeannie Che...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLE6073G (MSC/V/19-001379)
 OD
 Nov 23 2019 2:00PM
 [HITACHI CAPITAL ASIA PACIFIC PTE LTD]
 Hitachi Capital Asia Pacific Pte. Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	02/12/19 13:27	Repairer Estimates		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/12/19 11:25	Adjuster Immediate Advice		Load HTM
2	03/01/20 10:35	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/12/19 11:35	General View		Load JPG ☒
2	02/12/19 11:35	General View		Load JPG ☒
3	02/12/19 11:35	General View		Load JPG ☒
4	02/12/19 11:35	General View		Load JPG ☒
5	02/12/19 11:35	General View		Load JPG ☒
6	02/12/19 11:35	General View		Load JPG ☒
7	02/12/19 11:35	General View		Load JPG ☒
8	02/12/19 11:35	General View		Load JPG ☒
9	02/12/19 11:35	General View		Load JPG ☒
10	02/12/19 11:35	General View		Load JPG ☒
11	02/12/19 11:35	General View		Load JPG ☒
12	02/12/19 11:35	General View		Load JPG ☒
13	02/12/19 11:35	General View		Load JPG ☒
14	02/12/19 11:35	General View		Load JPG ☒
15	02/12/19 11:35	General View		Load JPG ☒
16	02/12/19 11:35	General View		Load JPG ☒
17	02/12/19 11:35	General View		Load JPG ☒
18	02/12/19 11:35	General View		Load JPG ☒
19	02/12/19 11:35	General View		Load JPG ☒
20	02/12/19 11:35	General View		Load JPG ☒
21	02/12/19 11:35	General View		Load JPG ☒
22	02/12/19 11:35	General View		Load JPG ☒
23	02/12/19 11:35	General View		Load JPG ☒
24	02/12/19 11:35	General View		Load JPG ☒
25	02/12/19 11:35	General View		Load JPG ☒
26	02/12/19 11:35	General View		Load JPG ☒
27	02/12/19 11:35	General View		Load JPG ☒
28	02/12/19 11:35	General View		Load JPG ☒
29	02/12/19 11:35	General View		Load JPG ☒
30	02/12/19 11:35	General View		Load JPG ☒
31	02/12/19 11:35	General View		Load JPG ☒
32	02/12/19 11:35	General View		Load JPG ☒
33	02/12/19 11:35	General View		Load JPG ☒
34	02/12/19 11:35	General View		Load JPG ☒
35	02/12/19 11:35	General View		Load JPG ☒
36	02/12/19 11:35	General View		Load JPG ☒
37	02/12/19 11:35	General View		Load JPG ☒
38	02/12/19 11:35	General View		Load JPG ☒
39	02/12/19 11:35	General View		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
				☒
40	02/12/19 11:35	General View		☒
41	02/12/19 11:35	General View		☒
42	02/12/19 11:35	General View		☒
43	02/12/19 11:35	General View		☒
44	02/12/19 11:35	General View		☒
45	02/12/19 11:35	General View		☒
46	02/12/19 11:35	General View		☒
47	02/12/19 11:35	General View		☒
48	02/12/19 11:35	General View		☒
49	02/12/19 11:35	General View		☒
50	02/12/19 11:35	General View		☒
51	02/12/19 11:35	General View		☒
52	02/12/19 11:35	General View		☒
53	02/12/19 11:35	General View		☒
54	02/12/19 11:35	General View		☒
55	02/12/19 11:35	General View		☒
56	02/12/19 11:35	General View		☒
57	02/12/19 11:35	General View		☒
58	02/12/19 11:36	General View		☒
59	02/12/19 11:36	General View		☒
60	02/12/19 11:36	General View		☒
61	02/12/19 11:36	General View		☒
62	02/12/19 11:36	General View		☒
63	02/12/19 11:36	General View		☒
64	02/12/19 11:36	General View		☒
65	02/12/19 11:36	General View		☒
66	02/12/19 11:36	General View		☒
67	02/12/19 11:36	General View		☒
68	02/12/19 11:36	General View		☒
69	02/12/19 11:36	General View		☒
70	02/12/19 11:36	General View		☒
71	02/12/19 11:36	General View		☒
72	02/12/19 11:36	General View		☒
73	02/12/19 11:36	General View		☒
74	02/12/19 11:36	General View		☒
75	02/12/19 11:36	General View		☒
76	02/12/19 11:36	General View		☒
77	02/12/19 11:36	General View		☒
78	02/12/19 11:36	General View		☒
79	02/12/19 11:36	General View		☒
80	02/12/19 11:36	General View		☒
81	02/12/19 11:36	General View		☒
82	02/12/19 11:36	General View		☒
83	02/12/19 11:36	General View		☒
84	03/01/20 10:23	Reinspection Photo		☒
85	03/01/20 10:23	Reinspection Photo		☒
86	03/01/20 10:23	Reinspection Photo		☒
87	03/01/20 10:23	Reinspection Photo		☒
88	03/01/20 10:23	Reinspection Photo		☒
89	03/01/20 10:23	Reinspection Photo		☒
90	03/01/20 10:23	Reinspection Photo		☒
91	03/01/20 10:23	Reinspection Photo		☒
92	03/01/20 10:23	Reinspection Photo		☒
93	03/01/20 10:23	Reinspection Photo		☒
94	03/01/20 10:23	Reinspection Photo		☒

Assessment Reports				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print	
95	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
96	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
97	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
98	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
99	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
100	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
101	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
102	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
103	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
104	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
105	03/01/20 10:23	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	27/11/19 11:01	SHD1564S - TP accident Report	 Load PDF		
2	27/11/19 15:48	PARF COE	 Load PDF		
3	27/11/19 15:48	Transfer Fee Details	 Load PDF		
4	27/11/19 15:49	TP GIA Report - SJK8726K (3/3)	 Load PDF		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	28/11/19 10:01	Survey Request - Manual Assigned	 Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	02/12/19 11:28	ESTIMATE.pdf	 Load PDF		
2	03/01/20 10:32	ESTIMATE MARKED.pdf	 Load PDF		
3	03/01/20 10:32	SLE 6073G - AUDATEX.pdf	 Load PDF		

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print	
1	06/12/19 19:32	Accident Statement	 Load HTM		
2	06/12/19 19:34	Accident Statement	 Load HTM		
3	06/12/19 19:36	Accident Statement	 Load HTM		
4	06/12/19 19:39	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print	
1	25/11/19 17:21	Accident Photo	 Load JPG	☒	
2	25/11/19 17:21	Accident Photo	 Load JPG	☒	
3	25/11/19 17:21	Accident Photo	 Load JPG	☒	
4	25/11/19 17:21	Accident Photo	 Load JPG	☒	
5	25/11/19 17:21	Accident Photo	 Load JPG	☒	
6	25/11/19 17:21	Accident Photo	 Load JPG	☒	
7	25/11/19 17:21	Accident Photo	 Load JPG	☒	
8	25/11/19 17:21	Accident Photo	 Load JPG	☒	
9	25/11/19 17:21	Accident Photo	 Load JPG	☒	
10	25/11/19 17:21	Accident Photo	 Load JPG	☒	
11	25/11/19 17:21	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print	
1	25/11/19 17:27	Sketch Plan	 Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19021002/R1SD3E2

Date: 22/01/2020

REFERENCE

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD

Policy No: MSD/VPCP/19-000825-00

Date of Loss: 23/11/2019

Nature of Claim: OD

Claim No: MSC/V/19-001379

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE6073G

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZR589100

Reg. Date: 27/07/2016 (Man. Year: 2016)

Chassis No: MR053REH104555901

Colour: Grey

Odometer: 333572 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$64,000.00

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,953.10	3,559.60	3,393.50	48.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,595.00	675.00	920.00	57.68
Paintwork Labour	1,663.80	1,378.54	285.26	17.15
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,211.90	5,613.14	4,598.76	45.03
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	10,211.90	4,113.14	6,098.76	59.72
+ GST 7.00/7.00% (S\$)	714.83	287.92	426.91	59.72
Nett Amount (S\$)	10,926.73	4,401.06	6,525.67	59.72

INSPECTION

Date of Assignment: 28/11/2019 Present Location:

Hitachi Capital Asia Pacific Pte. Ltd (HQ)

Date Inspected: 27/11/2019 Inspected At:

Hitachi Capital Asia Pacific Pte. Ltd (HQ)
No 8 Fourth Lok Yang Road
Singapore 629705

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE6073G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE MODEL (WCP)	Necessary	25.00 F	*25.00 F
2	1	NA	*BATTERY HOLDER (WCP)	Serviceable	40.00 F	*- F
3	1	NA	*BONNET (WCP)	Bent	280.00 F	*280.00 F
4	1	NA	*BONNET CABLE (WCP)	Serviceable	30.00 F	*- F
5	1	NA	*Bonnet Holder (WCP)	Serviceable	10.00 F	*- F
6	1	NA	*BONNET INSULATION (WCP)	Deformed	110.00 F	*110.00 F
7	1	NA	*BONNET LOCK (WCP)	Bent	50.00 F	*50.00 F
8	1	NA	*BOOTLID (WCP)	Repair	260.00 F	*- F
9	1	NA	*BOOTLID LOCK (WCP)	Cut	130.00 F	*130.00 F
10	1	NA	*CONDENSER CPL (WCP)	Bent	270.00 F	*270.00 F
11	1	NA	*COOLING FAN (WCP)	Serviceable	55.00 F	*- F
12	1	NA	*EVAP/COMPR PIPE (WCP)	Serviceable	180.00 F	*- F
13	1	NA	*EVAPORATOR OUTL PIPE (WCP)	Serviceable	180.00 F	*- F
14	1	NA	*EXPANSION TANK (WCP)	Serviceable	55.00 F	*- F
15	1	NA	*FAN HOUSING (WCP)	Serviceable	80.00 F	*- F
16	1	NA	*FAN MOTOR (WCP)	Serviceable	150.00 F	*- F
17	1	NA	*FRONT BUMPER (WCP)	Deformed	180.00 F	*180.00 F
18	1	NA	*FRONT GRILLE (WCP)	Cracked	150.00 F	*150.00 F
19	1	NA	*FRT BUMPER ABSORBER (WCP)	Deformed	45.00 F	*45.00 F
20	1	NA	*FRT BUMPER REINF (WCP)	Bent	110.00 F	*110.00 F
21	1	NA	*INNER END PANEL TRIM (WCP)	Serviceable	90.00 F	*- F
22	1	NA	*INNER FRT PANEL CPL (WCP)	Bent	200.00 F	*200.00 F
23	1	NA	*L/BONNET HINGE (WCP)	Bent	25.00 F	*25.00 F
24	1	NA	*L/BOOTLID HINGE (WCP)	Serviceable	35.00 F	*- F
25	1	NA	*L/CLIP (WCP)	Necessary	15.00 F	*15.00 F
26	1	NA	*L/F BUMPER BRACKET (WCP)	Necessary	28.00 F	*28.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1	NA	*L/F WHEELHOUSE COVER (WCP)	Serviceable	55.00 F	*- F
28	1	NA	*L/F WING (WCP)	Bent	200.00 F	*200.00 F
29	1	NA	*L/F WING BADGE (WCP)	Necessary	20.00 F	*20.00 F
30	1	NA	*L/HEADLAMP COVER (WCP)	Serviceable	60.00 F	*- F
31	1	NA	*L/RADIATOR HOSE (WCP)	Serviceable	20.00 F	*- F
32	1	NA	*L/R BUMPER BRACKET (WCP)	Necessary	30.00 F	*30.00 F
33	1	NA	*L/R MUDFLAP FRONT (WCP)	Serviceable	25.00 F	*- F
34	1	NA	*L/R REFLECTOR (WCP)	Serviceable	25.00 F	*- F
35	1	NA	*L/R SIDE PANEL (WCP)	Serviceable	420.00 F	*- F
36	1	NA	*L/R UPP BUMPER BRKT (WCP)	Necessary	40.00 F	*40.00 F
37	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	260.00 F	*260.00 F
38	1	NA	*LOCK CARRIER STRUT (WCP)	Bent	35.00 F	*35.00 F
39	1	NA	*LWR RADIATOR GRILLE (WCP)	Serviceable	50.00 F	*- F
40	1	NA	*p Garn Clips (10) (WCP)	Necessary	15.00 F	*15.00 F
41	1	NA	*R/BONNET HINGE (WCP)	Bent	25.00 F	*25.00 F
42	1	NA	*R/BOOTLID HINGE (WCP)	Serviceable	35.00 F	*- F
43	1	NA	*R/CLIP (WCP)	Necessary	15.00 F	*15.00 F
44	1	NA	*R/F BUMPER BRACKET (WCP)	Necessary	28.00 F	*28.00 F
45	1	NA	*R/F WHEELHOUSE COVER (WCP)	Serviceable	55.00 F	*- F
46	1	NA	*R/F WING (WCP)	Bent	200.00 F	*200.00 F
47	1	NA	*R/F WING BADGE (WCP)	Necessary	20.00 F	*20.00 F
48	1	NA	*R/HEADLAMP COVER (WCP)	Serviceable	60.00 F	*- F
49	1	NA	*R/RADIATOR HOSE (WCP)	Serviceable	20.00 F	*- F
50	1	NA	*R/R BUMPER BRACKET (WCP)	Necessary	30.00 F	*30.00 F
51	1	NA	*R/R MUDFLAP FRONT (WCP)	Serviceable	25.00 F	*- F
52	1	NA	*R/R REFLECTOR (WCP)	Serviceable	25.00 F	*- F
53	1	NA	*R/R SIDE PANEL (WCP)	Serviceable	420.00 F	*- F
54	1	NA	*R/R UPP BUMPER BRKT (WCP)	Necessary	40.00 F	*40.00 F
55	1	NA	*RADIATOR (WCP)	Serviceable	350.00 F	*- F
56	1	NA	*REAR BUMPER (WCP)	Deformed	180.00 F	*180.00 F
57	1	NA	*REAR BUMPER REINF (WCP)	Bent	110.00 F	*110.00 F
58	1	NA	*REAR MANUFACT BADGE (WCP)	Necessary	30.00 F	*30.00 F
59	1	NA	*REAR PANEL (WCP)	Repair	220.00 F	*- F
60	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	260.00 F	*260.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
61	1	NA	*RR Bumper Clips (10) (WCP)	Necessary	15.00 F	*15.00 F
62	1	NA	*t Insu Clips (10) (WCP)	Necessary	15.00 F	*15.00 F
63	1	NA	*umper Clips (10) (WCP)	Necessary	15.00 F	*15.00 F
64	1	NA	*UPP BATTERY BRACKET (WCP)	Bent	15.00 F	*15.00 F
65	1	NA	*UPP RADIATOR SHROUD (WCP)	Serviceable	55.00 F	*- F
66	1	NA	*VERSION BADGE (WCP)	Necessary	20.00 F	*20.00 F

F=Franchise part.

Sub Total (\$\$)	6,321.00	3,236.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	632.10	323.60
Total Parts (\$\$)	6,953.10	3,559.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	1,180.00	965.00
2	Total Paint Materials	New	483.80	413.54
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	1,595.00	675.00
Gross Labour Cost (\$\$)			3,258.80	2,053.54

Report was unsubmitted during this print-out.

< END OF ESTIMATES >