





Reference No: 221119

Date: 22.11.2019

Tan Boon Ann Blk 74 Whampoa Drive #10-322 Singapore 320074

KIA Cerato K3

Estimated Repair Cost for Vehicle Reg. No: SJW 4477 S

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Rear Bumper Ovt		699.00
1 Pc. Rear Bumper Side Retainer SV		52.00 ×
10 Pcs. Rear Bumper Clips Nuc	@ 5.00	50.00 30 - SH
1 Pc. Rear Bumper RH Dust Garnish		95.00 ×
6 Pcs. Rear RH Garnish Clips HK	@ 6.00	36.00
1 Pc. Rear RH Sport Rim Cwd		380.00 W SH
1 Pc. Rear Tyre SIL		295.00 ×
10	12. disc	

Total (Panels / Parts):

1,607.00 (SGD)

LABOR CHARGES

To repair & refit wiring & refit parking sensor.	120.00 40
To remove & refit rear tyre & balancing.	60.00 30 -
To knocking, straightening repair & renew all accident Damage parts.	480.00 350 -
To Respray painting on all accident affected damaged area.	500.00 300 -

Total (Labor Charges):

1,160.00 (SGD)



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E Email: alfredauto@hotmail.com



TOTAL COST SUMMARY

PANELS / PARTS LABOR CHARGES

1,607.00 1,160.00

Grand Total:

2,767.00 (SGD)

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

man

ALFRED AUTO SERVICES & SUPPLIES

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

29/11/2019 @ 1400m NA Andre L/Shore 2 days

LKK And