

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9180M**AAD1911-199***Not Authenticated
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

26 NOV 2019

SHD 9180M

JTDKB3FU603079431

TOYOTA

PRIUS

25.11.19

China TP

11/3/2019

PART**LIST**

1	1	FRONT BUMPER	\$	<i>Sn</i>	516.00	✓
2	1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>Sn</i>	103.40	X
3	1	REINFORCEMENT, FRONT BUMPER	\$	<i>R</i>	716.60	} X
4	1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	<i>R</i>	246.10	
5	1	COVER, FRONT BUMPER HOLE, RH	\$	<i>Sn</i>	29.30	
6	1	COVER FRONT BUMPER HOLE, LH	\$	<i>Sn</i>	29.30	
7	1	ABSORBER, FRONT BUMPER, LOWER	\$	<i>Sn</i>	132.70	
8	1	ABSORBER, FRONT BUMPER ENERGY	\$	<i>Sn</i>	79.60	} X
9	1	FRONT BUMPER SIDE RETAINER RH	\$	<i>Sn</i>	80.10	
10	1	FRONT BUMPER SIDE RETAINER LH	\$	<i>Dis</i>	82.30	
11	1	COVER SUB-ASSY, ENGINE, NO.1	\$	<i>Sn</i>	472.40	X
12	1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	<i>Sn</i>	241.90	X
13	1	EXTENSION, FRONT BUMPER, RH	\$	<i>Sn</i>	120.10	X
14	1	EXTENSION, FRONT BUMPER, LH	\$	<i>Sn</i>	120.10	X
15	1	FRONT LED LAMP (LOWER) LH	\$		951.40	?
16	1	FRONT HEADLAMP LH	\$	<i>cm</i>	2,637.60	✓
17	1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	<i>Sn</i>	960.50	X
18	1	MOTOR, HEADLAMP LEVELING, LH	\$	<i>Sn</i>	487.50	X
19	1	FRONT FENDER LH	\$	<i>Bu</i>	977.80	✓
20	1	LINER, FRONT FENDER, LH	\$	<i>cm</i>	202.50	✓
21	1	COVER SUB ASSY, FRONT PILLAR, UPPER LH	\$	<i>Sn</i>	100.40	X
22	1	EMBLEM, SIDE PANEL	\$	<i>re</i>	54.60	✓
23	1	PROTECTOR, FRONT FENDER SIDE PANEL, LH	\$	<i>Sn</i>	93.90	X
24	1	SEAL, FENDER APRON MUDGUARD, LH	\$	<i>Sn</i>	51.90	X
25	1	APRON ASSY, FRONT FENDER, LH	\$	<i>Sn</i>	176.80	X
26	1	BRACE SUB ASSY, FENDER APRON, LH	\$	<i>R</i>	292.10	X
27	1	BRACKET, FRONT SIDE PANEL, LH	\$	<i>R</i>	58.50	X
28	1	GRILLE SUB-ASSY, RADIATOR	\$	<i>Sn</i>	346.00	X

Trans-cab Auto Services Pte Ltd**AAD1911-199**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9180M

29	1	GRILLE, RADIATOR, LOWER NO.1	\$	S	170.10
30	1	EMBLEM ASSY, RADIATOR GRILLE	\$	S	90.80
31	1	FRONT BONNET	\$	M	983.10
32	1	INSULATOR, HOOD	\$	S	410.90
33	1	HINGE ASSY, HOOD, LH	\$	M	58.90
34	1	COVER, RADIATOR SUPPORT OPENING	\$	S	235.30
35	1	SEAL, RADIATOR TO SUPPORT, NO. 3	\$	S	29.60
36	1	GUIDE, RADIATOR AIR, NO. 1 LH	\$	S	69.90
37	1	GUIDE, RADIATOR AIR, NO 2	\$	S	53.40
38	1	GUIDE, RADIATOR AIR, NO 3	\$	S	112.70
39	1	SUPPORT SUB-ASSY, RADIATOR , LH	\$	S	245.10
40	1	SUPPORT SUB ASSY, RADIATOR, UPPER	\$	S	377.10
41	1	SUPPORT SUB ASSY, RADIATOR, LOWER	\$	S	409.90
42	1	CONDENSER ASSY, COOLER	\$	S	1,783.20
43	1	SHROUD, FAN	\$	S	264.70
44	1	FAN, LH	\$	S	219.10
45	1	MOTOR, COOLING FAN, LH	\$	S	655.10
46	1	SHAFT ASSY, FRONT DRIVE, LH	\$	S	1,352.50
47	1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$	S	760.10
48	1	KNUCKLE, STEERING, LH	\$	S	663.40
49	1	LINK ASSY, FRONT STABILIZER, LH	\$	S	237.10
50	1	BAR, STABILIZER, FRONT	\$	S	367.30
51	1	FRONT SHOCK ABSORBER	\$	S	438.30
52	1	SUPPORT SUB-ASSY, FRONT SUSPENSION, LH	\$	S	236.40
53	1	GEAR ASSY, STEERING	\$	S	1,955.40
54	1	PANEL SUB ASSY, FRONT DOOR, LH	\$	M	1,287.40
55	1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	S	1,339.30
56	1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	S	594.80

TOTAL	\$	25,762.30
25%	\$	6,440.58
	\$	19,321.73

Special Nett

1	1	FRONT WHEEL RIM	\$	S	1,570.55	X
2	1	FRONT WHEEL RIM COVER	\$	S	175.80	X
3	1	FRONT TYRE 195/65/15	\$	S	350.00	X

Trans-cab Auto Services Pte Ltd**AAD1911-199**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9180M

4	1	CLIP, FRONT FENDER LINER	\$	na 22.00	✓
5	1	FRONT NUMBER PLATE WITH MOULDING	\$	ph 200.00	X
6	1	BUMPER CLIP FRT	\$	nee 66.00	✓
7	1	WINDSCREEN SEALANT	\$	na 253.80	X
8	1	FRONT WINDSCREEN MOULDING	\$	na 120.00	X
9	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na 100.00	X
10	1	FRONT LH BUMPER RETAINER CLIP	\$	na 25.00	X
11	1	FRONT DOOR STICKER "Trans-Cab"	\$	na 100.00	X
TOTAL			\$	2,983.15	

TOTAL PARTS	\$	22,304.88
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	7,500.00	400
----	----------	-----

Putty And Spray Painting Of The Affected Portion.

\$	7,500.00	440
----	----------	-----

To Rust-Proofing Of The Affected Areas.

\$	170.00	30
----	--------	----

To transfer of Fender fittings, attachments and perform water seepage test.

\$	na 170.00	X
----	-----------	---

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$	na 170.00	X
----	-----------	---

To transfer of tire, rim and on wheel balancing.

\$	na 170.00	X
----	-----------	---

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	na 380.00	X
----	-----------	---

To Check Electrical Lighting Concerned.

\$	170.00	20
----	--------	----

To transfer of Bonnet fittings, attachments and perform water seepage test.

\$	na 170.00	X
----	-----------	---

Trans-cab Auto Services Pte Ltd**AAD1911-199**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9180M

To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	nn	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn	380.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X
TOTAL	\$		18,860.00	
Over All Total	\$		41,164.88	

(PART-BY-PART) Repair Days**25 days****2 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: