

ASS. REC. BY:

REF:

CS/SMO19021010/fisd32

Special Instructions:

Survey: Tauhidich

ASSIGNMENT (Office)

Firm (Person): Yong Kong Melvin of SMO Date/Time: 27/11/19 @ 3:35pm

Estimated Cost: _____ Bill to: _____

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMM 8825L Insured: GBS 729E

at Workshop m/s Vermogen Ace Tel: 9128 8559

of 60 Jalan Lam Hwat # 03-35/36

Policy No: _____ Claim No: CMTD1906540/RUC

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 26/11/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____

Date/Time: 3:45pm @ 27/11/19 Person Contacted: pila Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>SMM 8825L - X</u>
	<u>GBS 729E - X</u>
<u>4/12 @ 4:03pm</u>	<u>Revised via email preli advise</u>

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop n/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$28K
IDAC Accident Report: _____ Consistent? Yes or No
GIA / PR Seen: _____ Consistent? Yes or No
Est. Repair: _____ days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
Minsk

Veh No: SMW 8825L Yr Regn: 2010 / Any
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: And 144 cc 1798
Colour: Black AG: Insured / Std / NI / NA
Sp Reading: 158570 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: W4Y2278KYN A071500
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/55/17
R: _____
ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. _____ D.O.I. 27/11/19
Survey held at Vernoyen
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
o/s Rear
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit \$5000.
4/5 \$5000, ~8 days email to w/s

(\$34,813.17 Red - 87%)

MV - \$28K
LTA - \$21,125.00
NET - \$6,875.00

RECEIVED 16 DEC 2019

16/12/2019

Date/Time, File Pass by?

1) 16/12/19 Typist

Date/Time, File Return to?

2)

Form 4 Format:

Mink 200 / TR 1:1 \$5,000/- 45

Days Of Repair: 8Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Wheel and (\$)

Survey Fee:

Transportation:

S + RS \$

Photo

Draw

TOTAL

AGD

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Wednesday, 27 November 2019 3:35 PM
To: Pila Ng; assignments; sur@lkkauto.com
Cc: Minoko Chan; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Baldoz Juan Paulo Bongon; Yira Rahman; Henry, Irene James; Chua, Gek Tiang Ruth
Subject: RE: Accident involving vehicle SMM8825L & GBJ729E (Your Insured) DOA : 26/11/2019 - PLEASE ARRANGE TP SURVEY Our ref : CMTD1905540/RUC

Dear LKK Auto,

Please make the arrangement to survey for SMM8825L and revert with your preliminary report upon completion of survey to my colleague, Ruth.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Pila Ng <pila@vermogen-group.com>

Sent: Wednesday, 27 November, 2019 3:19 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Minoko Chan <minoko@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>; Yira Rahman <yira@vermogen-group.com>; Henry, Irene James <irene.henry@sompo.com.sg>; Chua, Gek Tiang Ruth <ruth.chua@sompo.com.sg>

Subject: Re: Accident involving vehicle SMM8825L & GBJ729E (Your Insured) DOA : 26/11/2019 - PLEASE ARRANGE TP SURVEY Our ref : CMTD1905540/RUC

Without Prejudice

Dear officer in-charge,

We would like to choose **LKK Auto Consultants** to conduct the PRS matter.

Thanks & regards,
Pila
Vermogen Ace Pte Ltd
Tel : 9128 8559

On Wed, Nov 27, 2019 at 3:15 PM Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Reference : CMTD1905540/RUC

Your Reference: SMM8825L

Without Prejudice

Date: 27/11/2019

Attention:

VERMOGEN ACE PTE LTD

Dear Pila,

ACCIDENT INVOLVING SMM8825L & GBJ729E ON 26.11.2019

We refer to your Notice of Accident dated 27/11/2019.

Please be informed that Ms Ruth Chua is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Aside to Ruth,

Please advise on the liability request from Vermogen Ace Pte Ltd.

Best Regards

Melvin Ye

Claims Division



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Pila Ng <pila@vermogen-group.com>

Sent: Wednesday, 27 November, 2019 12:33 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Minoko Chan <minoko@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>; Yira Rahman <yira@vermogen-group.com>

Subject: Accident involving vehicle SMM8825L & GBJ729E (Your Insured) DOA : 26/11/2019 - PLEASE ARRANGE TP SURVEY

Dear officer in-charge,

Refer to above attachment kindly arrange our client's vehicle for pre-repair survey at **Vermogen Ace Pte Ltd** here at **60 Jalan Lam Huat #03-35/36 Singapore 737869**.

Beside, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thanks & regards,

Pila

Vermogen Ace Pte Ltd

60 Jalan Lam Huat

#03-35/36

Singapore 737869

Tel: 9128 8559

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 715B

Vehicle Details

Vehicle No.: SMM8825L
Vehicle to be Exported: Yes
Intended Deregistration Date: 27 Nov 2019
Vehicle Make: AUDI
Vehicle Model: A4 1.8 TFSI MU
Primary Colour: Blue
Manufacturing Year: 2009
Engine No.: CDH071802
Chassis No.: WAUZZZ8KXAA071500
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$35,760.00
Original Registration Date: 31 Aug 2010
First Registration Date: 31 Aug 2010
Transfer Count: 4
Actual ARF Paid: \$35,760.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Aug 2020
PARF Rebate Amount: \$17,880.00

Intended COE Rebate Details

COE Expiry Date: 30 Aug 2020
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$43,501.00
COE Rebate Amount: \$3,245.00
Total Rebate Amount: \$21,125.00

The information contained herein is correct as at 27 Nov 2019

OK

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto)
Sent: Monday, 16 December 2019 12:16 pm
To: ezel.t@vermogen-group.com
Cc: Shirley Hiew (LKK Auto)
Subject: RE: TP FINALISE SMM8825L DOA: 26/11/2019

Hi Ezel,

COR l/s \$5000 , 8 days.

Regards
Taufikh
Lkk Auto

-----Original Message-----

From: ezel.t@vermogen-group.com [mailto:ezel.t@vermogen-group.com]
Sent: Monday, 9 December 2019 2:03 PM
To: 'Taufikh (LKKAuto)'; 'Admin A'
Cc: 'Pila Ng'; 'Glorioso Eric Paul Patambang'; 'Baldoz Juan Paulo Bongon'; 'Vermogen Ace'; 'Yira Rahman'; 'Minoko Chan'; 'Luis Tan'; 'Vmg admin'; paul@vermogen-group.com
Subject: TP FINALISE SMM8825L DOA: 26/11/2019

Dear Taufikh,

Please refer to attachments, the finalize COR L/S is \$12,200.00 (before GST) & 8 repair days, but we agreed to accept the maximum repair limit of this car @ \$5000.00 (before GST) & 8 repair days. (excluding PRS/RS/WEEKEND/PH).

Thank you.

Best Regards,

Ezel Tejano
Vermogen Ace Pte Ltd
Operation Address:
60 Jalan Lam Huat # 03-35/36
Carros Centre Singapore 737869
Tel: 6904 4596
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Wcega Plaza Singapore 658064

This email has been checked for viruses by AVG.

Veron Chen (LKKAUTO)

From: ezel.t@vermogen-group.com
Sent: Monday, 9 December 2019 2:03 PM
To: Taufikh (LKKAUTO); Admin A
Cc: 'Pila Ng'; 'Glorioso Eric Paul Patambang'; 'Baldoz Juan Paulo Bongon'; 'Vermogen Ace'; 'Yira Rahman'; 'Minoko Chan'; 'Luis Tan'; 'Vmg admin'; paul@vermogen-group.com
Subject: TP FINALISE SMM8825L DOA: 26/11/2019
Attachments: doc06076620191209122225.pdf; WhatsApp Image 2019-12-06 at 1.20.42 PM.jpeg; WhatsApp Image 2019-12-06 at 1.20.41 PM.jpeg; WhatsApp Image 2019-12-06 at 1.20.40 PM.jpeg; WhatsApp Image 2019-12-06 at 1.20.39 PM.jpeg; WhatsApp Image 2019-12-06 at 1.20.38 PM.jpeg; WhatsApp Image 2019-12-06 at 1.20.37 PM.jpeg; WhatsApp Image 2019-12-06 at 1.20.36 PM (1).jpeg; WhatsApp Image 2019-12-06 at 1.20.36 PM.jpeg; WhatsApp Image 2019-12-06 at 1.20.35 PM.jpeg

Dear Taufikh,

Please refer to attachments, the finalize COR L/S is \$12,200.00 (before GST) & 8 repair days, but we agreed to accept the maximum repair limit of this car @ \$5000.00 (before GST) & 8 repair days. (excluding PRS/RS/WEEKEND/PH).

Thank you.

Best Regards,

Ezel Tezano
Vermogen Ace Pte Ltd
Operation Address:
60 Jalan Lam Huat # 03-35/36
Carros Centre Singapore 737869
Tel: 6904 4596
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Wcega Plaza Singapore 658064

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 4 December 2019 4:03 PM
To: Admin-D (LKKAuto); 'Ye, Yong Kang Melvin'; assignments; SUR
Cc: 'Henry, Irene James'; 'Chua, Gek Tiang Ruth'
Subject: RE: Accident involving vehicle SMM8825L & GBJ729E (Your Insured) DOA : 26/11/2019 - PLEASE ARRANGE TP SURVEY Our ref : CMTD1905540/RUC
Attachments: PRELI ADVISED OF SMM 8825L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **MM 8825L**
Number of days (estimated) : 8 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 27 November 2019 3:47 PM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Chua, Gek Tiang Ruth' <ruth.chua@sompo.com.sg>
Subject: RE: Accident involving vehicle SMM8825L & GBJ729E (Your Insured) DOA : 26/11/2019 - PLEASE ARRANGE TP SURVEY Our ref : CMTD1905540/RUC

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Wednesday, 27 November 2019 3:35 PM
To: Pila Ng <pila@vermogen-group.com>; assignments <assignments@lkkauto.com>; sur@lkkauto.com
Cc: Minoko Chan <minoko@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Baldoz Juan Paulo Bongon <paulo.b@vermogen-



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: CMTD1905540/RUC

Date: 04/12/2019

Our Ref: CS/SMO19021010/T1sd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SMM 8825L.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 27/11/2019 at the premises of M/s Vermogan Ace and have the following to report: -

Workshop Estimate Amount	: S\$ 39,813.15
Revised Estimate Amount	: S\$ 15,307.34
"Check" Items Amount	: S\$ 350.00
Market Value	: S\$
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Repair days: 8

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2019 12:06
Date Of Accident	26/11/2019 15:50
Exact Location Of Accident	IN THE PREMISES OF GLOBAL FOUNDRIES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM8825L
Insured/Policyholder	
Name Of Registered Owner	GAN CHEE LEE
NRIC No	S8317715B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87972000
Alternative Phone No	OFFICE-87972000

Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.8 TFSI MU
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	GA493662/1
Cover Note Number	

Driver

Name of Driver	GOH BENG HOE
NRIC No	S7826236B
Date Of Birth	25/09/1978
Occupation	INDOOR
Date Of Driving Pass	29/10/2010
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97666659
Fax Number	
Contact Number	
Email Address	MINGHUADONALD@HOTMAIL.COM

Address	BLK 483 CHOA CHU KANG AVENUE 5 #09-168
Postcode	680483
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS AS ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ729E
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

I Lee Choon Heng acknowledged that
I had this vehicle SMM 8825L at Global Furniture
Premises at 3:50 pm.



Lee Choon Heng
S1610932J



Garry Lee
S8262368

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: YIRA RAHMAN
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the said time & date I was travelling straight along Global Foundries premises when suddenly I felt an impact coming from the right of my car. I realised vehicle B has collided into my right portion and cause my rear bumper falls off. Vehicle B came out of stop Rd with stop line but did not stop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: YIRA RAHMAN
NRIC/FIN No.:



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4360
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

Account Number
 15423

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks and Compensation) Rules, 1990; Road Transport Act, 1987 (Malaysia);
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1990 (Malaysia)

Policy details

Policyholder name	GAN CHIE LEE	Certificate number	GA453462 / 1
Cover	Comprehensive	Chassis number	WUZZ28KAA071900
Plan name	Essential	Engine number	CDH071802
NCD applicable	10%		
Vehicle registration number	SMMA82SL		
Period of Insurance	from 01/09/2019 to 31/08/2020 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws, or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover: use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 500.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

- \$5500 for unnamed Authorized Driver
- \$5500 for declared Young and Inexperienced Driver
- \$55,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to \$12,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurer's company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Rebate Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.



SMM8825L

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO
OWN INSURER : AXA
CLAIM TYPE : TP
Date of Accident : 26/11/2019

Vehicle Reg. No. : SMM8825L
Vehicle Reg. Date: 31-Aug-2010
Make / Model : AUDI A4 1.8 TFSI MU
Engine No. : CDH071802
Chassis No. : WAUZZZ8KXAA071500

COST OF CLAIMS

Parts Cost / List Items : \$ -
Plus/Less 5% \$ -
Total Cost / List : \$ -
Special Nett Items : \$ 1,370.00
Total Parts Amount : \$ 1,370.00
Total Labour Amount : \$ 7,130.00
Gross Total : \$ 8,500.00
GST % : 7% \$ 595.00
Nett Amount : \$ 9,095.00

[Signature]
6/12/19

Surveyor Name and Company :

Tanfah 97445749/67418434

Date of survey : 27/4/19 @ 5pm

Part by Part / Lump Sum : 8 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@lkkauto.com
tanfah@lkkauto.com

Fax No : _____

HP No : _____

To check repair limit

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**

Vehicle Reg. Date: **31/8/2010**

Make / Model : **AUDI A4 1.8 TFSI MU**

Engine No. : **CDH071802**

Chassis No. : **WAUZZZ8KXAA071500**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	dis✓	21,600.70		
2	2	REAR BUMPER SIDE RETIANER	LH-x, RH-ds✓	161.93	80.99	
3	2	REAR BUMPER SIDE BRACEKT	LH-x, RH-ds✓	159.54	79.77	
4	1	REAR BUMPER LOWER SKIRT	ds✓	395.70		
5	1	REAR BUMPER REINFORCEMENT	X			
6	1	REAR BUMPER REINFORCEMENT CENTER BRACKET	ds✓			
7	1SET	REAR BUMPER CLIPS	ds✓			
8	1	REAR BOOT	Rx			
9	2	REAR BOOT LAMP	LH-x, RH-int✓			
10	1	REAR BOOT EMBLEM - LOGO	ds✓			
11	1	REAR BOOT EMBLEM - A4	ds✓			
12	1	REAR BOOT EMBLEM - 1.8T	ds✓			
13	1	REAR BOOT WEATHERSTRIP	X			
14	1	REAR END PANEL	X			
15	1	REAR END PANEL TOP GARNISH	X			
16	1SET	REAR END PANEL TOP GARNISH CLIPS	X			
17	2	TAILLAMP	LH-x, RH-?			
18	2	TAILLAMP BRACKET	LH-x, RH-?			
19	2	TAILLAMP CLIPS	LH-x, RH-?			
20	2	TAILLAMP PANEL	X			
21	2	REAR FENDER	LH-x, RH-bt✓			
22	2	REAR FENDER INNERSHIELD	LH-x, RH-int✓			
23	2SET	REAR FENDER INNERSHIELD CLIPS	LH-x, RH-int✓			
24	1	REAR FENDER INNER TRIMBOARD RH	X			
25	1	REAR FENDER INNER TRIMBOARD CLIPS RH	X			
26	1	REAR FENDER OUTER MOULDING RH	ds✓			
27	1	REAR FENDER GLASS RH	X			
28	1	REAR FENDER GLASS MOULDING RH	ds✓			
29	1	REAR FENDER AIR DUCT RH	ds✓			
30	1	REAR WHEEL HOUSE RH OUTER	X			
31	1	REAR WHEEL HOUSE RH INNER	X			
32	1	PETROL TANK COVER	bt✓			
33	1	PETROL TANK COVERT RIVERT	ds✓			
34	1	SPARE TYRE PANEL	X			
35	1	SPARE TYRE LOWER COVER	X			
36	1	REAR DOOR RH	Rx			
37	1	REAR DOOR LOCK RH	X			
38	1	REAR DOOR LOCK CATCH RH	X			
39	1	REAR DOOR STICKER RH	X			
40	1	REAR DOOR WEATHERSTRIP RH	ds✓			

5

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
 60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
 Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**
 Vehicle Reg. Date: **31/8/2010**
 Make / Model : **AUDI A4 1.8 TFSI MU**
 Engine No. : **CDH071802**
 Chassis No. : **WAUZZZ8KXAA071500**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR DOOR OUTER HANDLE RH	X			
42	1	REAR DOOR OUTER HANDLE CAP RH	X			
43	1	REAR RIM RH	Ref		\$ 450.00	
44	1	REAR TYRE RH	X		\$ 280.00	
45	1	REAR SHOCK ABSORBER RH	?			
46	1	REAR WHEEL HUB & BEARING	?			
47	1	REAR AXLE BEAM	X			
48	1	REVERSE SENSOR	?			
49	1	REAR WINDSCREEN GLASS	X			
50	1	REAR WINDSCREEN GLASS MOULDING	Ref			
51	1	REAR FENDER SEALANT	Ref		\$ 80.00	30 Δ
52	1	REAR FENDER GLASS SEALANT	Ref		\$ 80.00	30 Δ
53	1	SPARE TYRE PANEL SEALANT	X		\$ 80.00	
54	1	TAILLAMP PAD	X		\$ 80.00	
55	1	TAILLAMP PANEL SEALANT	Ref X		\$ 80.00	
56	1	REAR WINDSCREEN GLASS SEALANT	Ref		\$ 80.00	30 Δ
57	1	REAR WINDSCREEN GLASS INNER SEAL	Ref		\$ 80.00	30 Δ
58	1	REAR WINDSCREEN GLASS PRIMER & CLENER	Ref		\$ 80.00	X Δ
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
 60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
 Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**
 Vehicle Reg. Date: **31/8/2010**
 Make / Model : **AUDI A4 1.8 TFSI MU**
 Engine No. : **CDH071802**
 Chassis No. : **WAUZZZ8KXAA071500**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	TO CUT WELD FRT PANEL,JACK ,STRAIGHTEN CHASSIS,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	\$ 2,400.00	900
2	To putty,respray painting and polish rear affected areas. Rear Portion.	\$ 2,400.00	900
3	To remove and transfer bootlid components.	\$ 180.00	X
4	To check and rectify wiring system.	\$ 150.00	30
5	To remove and replace reverse sensor.	\$ 150.00	30
6	To remove and replace rear windscreen glass	\$ 180.00	120
7	To remove and refit interior parts and upholstery.	\$ 180.00	60
8	To rust proof affected areas.	\$ 200.00	50
9	To remove and replace rear fender glass	\$ 150.00	860
10	To remove & transfer rear door rh component	\$ 180.00	X
11	To do wheel alignment	\$ 180.00	80
12	To do tyre balancing	\$ 150.00	30
13	To remove & install rear undercarriage	\$ 280.00	150? plus
14	To remove & refit petrol tank to assist work load.	\$ 350.00	100? plus

\$ -



SMM8825L

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO

Vehicle Reg. No. : SMM8825L

OWN INSURER : AXA

Vehicle Reg. Date: 31-Aug-2010

CLAIM TYPE : TP

Make / Model : AUDI A4 1.8 TFSI MU

Date of Accident : 26/11/2019

Engine No. : CDH071802

Chassis No. : WAUZZZ8KXAA071500

COST OF CLAIMS

Parts Cost / List Items : \$ -

Plus/Less 5% \$ -

Total Cost / List : \$ -

Special Nett Items : \$ 1,370.00

Total Parts Amount : \$ 1,370.00

Total Labour Amount : \$ 7,130.00

Gross Total : \$ 8,500.00

GST % : 7% \$ 595.00

Nett Amount : \$ 9,095.00

Surveyor Name and Company :

Tanjiliah 97445749/6741843

Date of survey : 27/11/19 @ 5pm

Part by Part / Lump Sum : 8 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sure@hkauto.com

Fax No : tanjiliah@hkauto.com

HP No :

This claim is handled by : MINOKO

To check repair limit
Repair limit \$5000

60942-794

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**

Vehicle Reg. Date: **31/8/2010**

Make / Model : **AUDI A4 1.8 TFSI MU**

Engine No. : **CDH071802**

Chassis No. : **WAUZZZ8KXAA071500**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	actis	1600.70		
2	2	REAR BUMPER SIDE RETIANER	LH-X, RH-ds	161.98	80.99	
3	2	REAR BUMPER SIDE BRACKET	LH-xm, RH-ds	154.54	30.37	
4	1	REAR BUMPER LOWER SKIRT	fu	399.70		
5	1	REAR BUMPER REINFORCEMENT	X	600.35		
6	1	REAR BUMPER REINFORCEMENT CENTER BRACKET	CR	401.50		
7	1SET	REAR BUMPER CLIPS	actis	30.00		
8	1	REAR BOOT	Rx	239.60		
9	2	REAR BOOT LAMP	LH-X, RH-ml	399.20	309.60	
10	1	REAR BOOT EMBLEM - LOGO	actis	130.71		
11	1	REAR BOOT EMBLEM - A4	actis	99.39		
12	1	REAR BOOT EMBLEM - 1.8T	actis	99.39		
13	1	REAR BOOT WEATHERSTRIP	X	80.37		
14	1	REAR END PANEL	X	1004.60		
15	1	REAR END PANEL TOP GARNISH	X	288.96		
16	1SET	REAR END PANEL TOP GARNISH CLIPS	X	30.00		
17	2	TAILLAMP	LH-X, RH-ml	1001.94	500.97	
18	2	TAILLAMP BRACKET	LH-X, RH-ml	81.54		
19	2	TAILLAMP CLIPS	LH-X, RH-ml	15.00	3.50	
20	2	TAILLAMP PANEL	X	901.58		
21	2	REAR FENDER	LH-X, RH-bt	3549.40	1774.70	
22	2	REAR FENDER INNERSHIELD	LH-X, RH-ml	401.94	200.97	
23	2SET	REAR FENDER INNERSHIELD CLIPS	LH-X, RH-ml	144.00	72.00	
24	1	REAR FENDER INNER TRIMBOARD RH	X	499.91		
25	1	REAR FENDER INNER TRIMBOARD CLIPS RH	X	30.00		
26	1	REAR FENDER OUTER MOULDING RH	actis	300.71		
27	1	REAR FENDER GLASS RH	X	300.60		
28	1	REAR FENDER GLASS MOULDING RH	actis	with Holes	399.60	
29	1	REAR FENDER AIR DUCT RH	actis	100.71		
30	1	REAR WHEEL HOUSE RH OUTER	X	1300.71		
31	1	REAR WHEEL HOUSE RH INNER	X	300.97		
32	1	PETROL TANK COVER	bt	288.96		
33	1	PETROL TANK COVERT RIVERT	actis	15.00		
34	1	SPARE TYRE PANEL	X	1300.71		
35	1	SPARE TYRE LOWER COVER	X	288.96		
36	1	REAR DOOR RH	Rx	1800.70		
37	1	REAR DOOR LOCK RH	X	500.71		
38	1	REAR DOOR LOCK CATCH RH	X	100.97		
39	1	REAR DOOR STICKER RH	X	80.99		
40	1	REAR DOOR WEATHERSTRIP RH	X	200.97		

5

23091.79

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**

Vehicle Reg. Date: **31/8/2010**

Make / Model : **AUDI A4 1.8 TFSI MU**

Engine No. : **CDH071802**

Chassis No. : **WAUZZZ8KXAA071500**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR DOOR OUTER HANDLE RH	X UN	500.47		
42	1	REAR DOOR OUTER HANDLE CAP RH	X UN	80.47		
43	1	REAR RIM RH	Ref	1100.47	880	
44	1	REAR TYRE RH	X UN		\$ 280.00	
45	1	REAR SHOCK ABSORBER RH	? bt	1307.71	780	
46	1	REAR WHEEL HUB & BEARING	? bt	1004.76		
47	1	REAR AXLE BEAM	X UN	2077.60		
48	2	REVERSE SENSOR @ 212.11 each.	? UN	848.44	42422	
49	1	REAR WINDSCREEN GLASS	X UN	1674.60		
50	1	REAR WINDSCREEN GLASS MOULDING	new X UN	with glass		
51	1	REAR FENDER SEALANT	new		\$ 80.00	
52	1	REAR FENDER GLASS SEALANT	new		\$ 80.00	
53	1	SPARE TYRE PANEL SEALANT	X UN		\$ 80.00	
54	1	TAILLAMP PAD	X UN		\$ 80.00	
55	1	TAILLAMP PANEL SEALANT	new X UN		\$ 80.00	
56	1	REAR WINDSCREEN GLASS SEALANT	new		\$ 80.00	
57	1	REAR WINDSCREEN GLASS INNER SEAL	new		\$ 80.00	
58	1	REAR WINDSCREEN GLASS PRIMER & CLENER	new		\$ 80.00	
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

8806.02

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
 60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
 Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**
 Vehicle Reg. Date: **31/8/2010**
 Make / Model : **AUDI A4 1.8 TFSI MU**
 Engine No. : **CDH071802**
 Chassis No. : **WAUZZZ8KXAA071500**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	TO CUT WELD FRT PANEL,JACK ,STRAIGHTEN CHASSIS,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	\$ 2,400.00	900
2	To putty,respray painting and polish rear affected areas. Rear Portion.	\$ 2,400.00	900
3	To remove and transfer bootlid components.	\$ 180.00	X NM
4	To check and rectify wiring system.	\$ 150.00	30
5	To remove and replace reverse sensor.	\$ 150.00	30
6	To remove and replace rear windscreen glass	\$ 180.00	120
7	To remove and refit interior parts and upholstery.	\$ 180.00	60
8	To rust proof affected areas.	\$ 200.00	50
9	To remove and replace rear fender glass	\$ 150.00	860
10	To remove & transfer rear door rh component	\$ 180.00	X NM
11	To do wheel alignment	\$ 180.00	80
12	To do tyre balancing	\$ 150.00	30
13	To remove & install rear undercarriage	\$ 280.00	150? plus ✓
14	To remove & refit petrol tank to assist work load.	\$ 350.00	100? plus ✓

\$ -

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**
Vehicle Reg. Date: **31/8/2010**
Make / Model : **AUDI A4 1.8 TFSI MU**
Engine No. : **CDH071802**
Chassis No. : **WAUZZZ8KXAA071500**

ATTN: AH HAN
PLEASE QUOTE COST/LIST PRICE
FAX: 6745 4442

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR SHOCK ABSORVER STOPPER RH	NE ✓	\$ 90.77		
2	1	REAR SHOCK ABSORVER TOP MOUNT RH	NE ✓	\$ 189.85		
3	1	REAR LOWER ARM RH	bb ✓	\$ 600.33	325	} supp
4	1	REAR UPPER ARM RH	bb ✓	\$ 488.96		
5	1	REAR CONTROL ARM RH	bb ✓	\$ 477.20	307	
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

1242.11

Customer:		Date:	28-Nov-19 2:35 PM
Company:	VERMOGEN ACE	VIN	
License No:	SMM8825L	Technician:	IVAN
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT
AUDI, A4 [8K], 2009-2015, (1BA) Normal Suspension Right Hand Drive

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	----	----	----
		Right	----	----	----	----
	Camber	Left	-1.4°	----	----	-1.4°
		Right	-1.3°	----	----	-1.3°
	Toe	Left	-0.30°	0.10°	0.25°	-0.30°
		Right	0.25°	0.10°	0.25°	0.30°
Total		-0.05°	0.15°	0.50°	0.00°	
Rear	Camber	Left	-1.9°	-1.8°	-0.9°	-1.9°
		Right	-1.9°	-1.8°	-0.9°	-1.9°
	Toe	Left	0.45°	0.10°	0.25°	0.45°
		Right	-0.60°	0.10°	0.25°	-0.60°
		Total	-0.15°	0.15°	0.50°	-0.15°
	Thrust Angle		-0.5°	-0.2°	0.2°	-0.5°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	----	----	----
	Right		----	----	----	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	1.3°	2.3°	----
	Right		----	1.3°	2.3°	----
Maximum Turns	Left		----	37.6°	41.1°	----
	Right		----	37.6°	41.1°	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		3mm	----	----	3mm
	Rear		3mm	----	----	3mm
Track Width Diff.			15mm			16mm
Wheel Base Diff.			1mm			1mm
Front Ride Height	Left		----	381mm	401mm	----
	Right		----	381mm	401mm	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO: VAC-FOCK
Surveyor Name and Company

Date of Accident : 26-Nov-2019

BILL TO: MS FC
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SMM8825L

Make / Model : AUDI A4 1.8 TFSI MU

COST OF REPAIR

Parts Cost / List : \$ 11,283.13

Supp. Parts : \$ 1,847.11

Special Nett : \$ 400.00

Total Parts : \$ 12,873.73

Total Labour : \$ 2,410.00

TOTAL REPAIR COST : \$ 15,283.73

Total Parts Cost/List :	\$	13,130.24
Plus / Less : 5%	\$	656.51
Total :	\$	12,473.73

Lump Sum Discount : 20%	\$	3,056.75
Lump Sum Amount:	\$	12,226.98

Final Lump Sum Amount : \$ 12,200.00

No. of Repair Days: 8

Submitted by / Date : MINOKO

Confirmed by / Date : _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**
Vehicle Reg. Date: **8/31/2010**
Make / Model : **AUDI A4 1.8 TFSI MU**
Engine No. : **CDH071802**
Chassis No. : **WAUZZZ8KXAA071500**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER		\$ 1,600.70		\$ 1,600.70
2	2	REAR BUMPER SIDE RETIANER		\$ 161.98		\$ 80.99
3	2	REAR BUMPER SIDE BRACEKT		\$ 159.54		\$ 79.77
4	1	REAR BUMPER LOWER SKIRT		\$ 399.70		\$ 399.70
5	1	REAR BUMPER REINFORCEMENT		\$ 600.33		
6	1	REAR BUMPER REINFORCEMENT CENTER BRACKET		\$ 401.50		\$ 401.50
7	1SET	REAR BUMPER CLIPS		\$ 72.00		\$ 72.00
8	1	REAR BOOT		\$ 2,397.60		
9	2	REAR BOOT LAMP		\$ 799.20		\$ 399.60
10	1	REAR BOOT EMBLEM - LOGO		\$ 130.71		\$ 130.71
11	1	REAR BOOT EMBLEM - A4		\$ 99.79		\$ 99.79
12	1	REAR BOOT EMBLEM - 1.8T		\$ 99.79		\$ 99.79
13	1	REAR BOOT WEATHERSTRIP		\$ 80.37		
14	1	REAR END PANEL		\$ 1,009.60		
15	1	REAR END PANEL TOP GARNISH		\$ 288.96		
16	1SET	REAR END PANEL TOP GARNISH CLIPS		\$ 72.00		
17	2	TAILLAMP		\$ 1,001.94		\$ 500.97
18	2	TAILLAMP BRACKET		\$ 181.54		
19	2	TAILLAMP CLIPS		\$ 15.00		\$ 7.50
20	2	TAILLAMP PANEL		\$ 921.58		
21	2	REAR FENDER		\$ 3,599.40		\$ 1,799.70
22	2	REAR FENDER INNERSHIELD		\$ 401.94		\$ 200.97
23	2SET	REAR FENDER INNERSHIELD CLIPS		\$ 144.00		\$ 72.00
24	1	REAR FENDER INNER TRIMBOARD RH		\$ 499.91		
25	1	REAR FENDER INNER TRIMBOARD CLIPS RH		\$ 72.00		
26	1	REAR FENDER OUTER MOULDING RH		\$ 300.77		\$ 300.77
27	1	REAR FENDER GLASS RH		\$ 399.60		\$ 399.60
28	1	REAR FENDER GLASS MOULDING RH		with glass		
29	1	REAR FENDER AIR DUCT RH		\$ 100.71		\$ 100.71
30	1	REAR WHEEL HOUSE RH OUTER		\$ 1,300.71		
31	1	REAR WHEEL HOUSE RH INNER		\$ 700.97		
32	1	PETROL TANK COVER		\$ 288.96		\$ 288.96
33	1	PETROL TANK COVERT RIVERT		\$ 15.00		\$ 15.00
34	1	SPARE TYRE PANEL		\$ 1,300.71		
35	1	SPARE TYRE LOWER COVER		\$ 388.96		
36	1	REAR DOOR RH		\$ 1,800.70		
37	1	REAR DOOR LOCK RH		\$ 500.71		
38	1	REAR DOOR LOCK CATCH RH		\$ 100.97		
39	1	REAR DOOR STICKER RH		\$ 80.97		
40	1	REAR DOOR WEATHERSTRIP RH		\$ 200.97		

\$ 7,050.73

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**
 Vehicle Reg. Date: **8/31/2010**
 Make / Model : **AUDI A4 1.8 TFSI MU**
 Engine No. : **CDH071802**
 Chassis No. : **WAUZZZ8KXAA071500**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR DOOR OUTER HANDLE RH		\$ 200.97		
42	1	REAR DOOR OUTER HANDLE CAP RH		\$ 80.97		
43	1	REAR RIM RH		\$ 1,400.71		\$ 1,400.71
44	1	REAR TYRE RH			\$ -	
45	1	REAR SHOCK ABSORBER RH		\$ 1,397.71		\$ 1,397.71
46	1	REAR WHEEL HUB & BEARING		\$ 1,009.76		\$ 1,009.76
47	1	REAR AXLE BEAM		\$ 2,477.60		
48	4	REVERSE SENSOR		\$ 848.44		\$ 424.22
49	1	REAR WINDSCREEN GLASS		\$ 1,479.60		
50	1	REAR WINDSCREEN GLASS MOULDING		with glass		
51	1	REAR FENDER SEALANT			\$ 80.00	
52	1	REAR FENDER GLASS SEALANT			\$ 80.00	
53	1	SPARE TYRE PANEL SEALANT			\$ -	
54	1	TAILLAMP PAD			\$ -	
55	1	TAILLAMP PANEL SEALANT			\$ -	
56	1	REAR WINDSCREEN GLASS SEALANT			\$ 80.00	
57	1	REAR WINDSCREEN GLASS INNER SEAL			\$ 80.00	
58	1	REAR WINDSCREEN GLASS PRIMER & CLENER			\$ 80.00	
59	0					
60	0					
61	0					
62	0					
63	0					
64	0					
65	0					
66	0					
67	0					
68	0					
69	0					
70	0					
71	0					
72	0					
73	0					
74	0					
75	0					
76	0					
77	0					
78	0					
79	0					
80	0					

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SMM8825L
Vehicle Reg. Date: 8/31/2010
Make / Model : AUDI A4 1.8 TFSI MU
Engine No. : CDH071802
Chassis No. : WAUZZZ8KXAA071500

ATTN: AH HAN
PLEASE QUOTE COST/LIST PRICE
FAX: 6745 4442

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR SHOCK ABSORVER STOPPER RH		\$ 90.77		\$ 90.77
2	1	REAR SHOCK ABSORVER TOP MOUNT RH		\$ 189.85		\$ 189.85
3	1	REAR LOWER ARM RH		\$ 600.33		\$ 600.33
4	1	REAR UPPER ARM RH		\$ 488.96		\$ 488.96
5	1	REAR CONTROL ARM RH		\$ 477.20		\$ 477.20
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SMM8825L**
Vehicle Reg. Date: **8/31/2010**
Make / Model : **AUDI A4 1.8 TFSI MU**
Engine No. : **CDH071802**
Chassis No. : **WAUZZZ8KXAA071500**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	TO CUT WELD FRT PANEL,JACK ,STRAIGHTEN CHASSIS,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	\$ 2,400.00	\$ 900.00
2	To putty,respray painting and polish rear affected areas. Rear Portion.	\$ 2,400.00	\$ 900.00
3	To remove and transfer bootlid components.	\$ 180.00	\$ -
4	To check and rectify wiring system.	\$ 150.00	\$ 30.00
5	To remove and replace reverse sensor.	\$ 150.00	\$ 30.00
6	To remove and replace rear windscreen glass	\$ 180.00	\$ 120.00
7	To remove and refit interior parts and upholstery.	\$ 180.00	\$ 60.00
8	To rust proof affected areas.	\$ 200.00	\$ 50.00
9	To remove and replace rear fender glass	\$ 150.00	\$ 60.00
10	To remove & transfer rear door rh component	\$ 180.00	
11	To do wheel alignment	\$ 180.00	\$ 80.00
12	To do tyre balancing	\$ 150.00	\$ 30.00
13	To remove & install rear undercarriage	\$ 280.00	\$ 150.00
14	To remove & refit petrol tank to assist work load.	\$ 350.00	

\$ 2,410.00



SMM8825L

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO
OWN INSURER : AXA
CLAIM TYPE : TP
Date of Accident : 26/11/2019

Vehicle Reg. No. : SMM8825L
Vehicle Reg. Date: 31-Aug-2010
Make / Model : AUDI A4 1.8 TFSI MU
Engine No. : CDH071802
Chassis No. : WAUZZZ8KXAA071500

COST OF CLAIMS

Parts Cost / List Items : \$ -
Plus/Less 5% \$ -
Total Cost / List : \$ -
Special Nett Items : \$ 1,370.00
Total Parts Amount : \$ 1,370.00
Total Labour Amount : \$ 7,130.00
Gross Total : \$ 8,500.00
GST % : 7% \$ 595.00
Nett Amount : \$ 9,095.00

Surveyor Name and Company :

Tanjik 97495749/6741843
Date of survey : 27/4/19 @ 5pm
Part by Part / Lump Sum : 8 days
Resurvey Before Paint / After Paint After Paint
Authorize/Not Authorize/Without Prejudice Without Prejudice
Email : sure@hkant.com
tanjik@hkant.com
Fax No : _____
HP No : _____

To check repair limit

This claim is handled by : MINOKO

Vehicle Reg. No. : **SMM8825L**
Vehicle Reg. Date: **31/8/2010**
Make / Model : **AUDI A4 1.8 TFSI MU**
Engine No. : **CDH071802**
Chassis No. : **WAUZZZ8KXAA071500**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	dis✓	1600.70		
2	2	REAR BUMPER SIDE RETIANER	LH-x, RH-dis✓	161.98	80.99	
3	2	REAR BUMPER SIDE BRACEKT	LH-x, RH-dis✓	154.54	77.77	
4	1	REAR BUMPER LOWER SKIRT	dis✓	399.70		
5	1	REAR BUMPER REINFORCEMENT	X	600.33		
6	1	REAR BUMPER REINFORCEMENT CENTER BRACKET	dis✓	401.50		
7	1SET	REAR BUMPER CLIPS	dis✓	72.00		
8	1	REAR BOOT	Rx	297.60		
9	2	REAR BOOT LAMP	LH-x, RH-dis✓	799.20	399.60	
10	1	REAR BOOT EMBLEM - LOGO	dis✓	130.71		
11	1	REAR BOOT EMBLEM - A4	dis✓	99.79		
12	1	REAR BOOT EMBLEM - 1.8T	dis✓	99.79		
13	1	REAR BOOT WEATHERSTRIP	X	80.37		
14	1	REAR END PANEL	X	1009.60		
15	1	REAR END PANEL TOP GARNISH	X	288.96		
16	1SET	REAR END PANEL TOP GARNISH CLIPS	X	72.00		
17	2	TAILLAMP	LH-x, RH-dis✓	1001.94	500.97	
18	2	TAILLAMP BRACKET	LH-x, RH-dis✓	181.54		
19	2	TAILLAMP CLIPS	LH-x, RH-dis✓	15.00	7.50	
20	2	TAILLAMP PANEL	X	921.58		
21	2	REAR FENDER	LH-x, RH-dis✓	3599.10		
22	2	REAR FENDER INNERSHIELD	LH-x, RH-dis✓	401.94		
23	2SET	REAR FENDER INNERSHIELD CLIPS	LH-x, RH-dis✓	144.00		
24	1	REAR FENDER INNER TRIMBOARD RH	X	499.91		
25	1	REAR FENDER INNER TRIMBOARD CLIPS RH	X	72.00		
26	1	REAR FENDER OUTER MOULDING RH	dis✓	300.77		
27	1	REAR FENDER GLASS RH	X	300.60		
28	1	REAR FENDER GLASS MOULDING RH	dis✓	with glass		
29	1	REAR FENDER AIR DUCT RH	dis✓	100.71		
30	1	REAR WHEEL HOUSE RH OUTER	X	1300.71		
31	1	REAR WHEEL HOUSE RH INNER	X	700.97		
32	1	PETROL TANK COVER	dis✓	288.96		
33	1	PETROL TANK COVERT RIVERT	dis✓	15.00		
34	1	SPARE TYRE PANEL	X	1300.71		
35	1	SPARE TYRE LOWER COVER	X	288.96		
36	1	REAR DOOR RH	Rx	1800.70		
37	1	REAR DOOR LOCK RH	X	500.71		
38	1	REAR DOOR LOCK CATCH RH	X	100.97		
39	1	REAR DOOR STICKER RH	X	80.97		
40	1	REAR DOOR WEATHERSTRIP RH	X	200.97		

Vehicle Reg. No. : SMM8825L
Vehicle Reg. Date: 31/8/2010
Make / Model : AUDI A4 1.8 TFSI MU
Engine No. : CDH071802
Chassis No. : WAUZZZ8KXAA071500

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR DOOR OUTER HANDLE RH	X	200.97		
42	1	REAR DOOR OUTER HANDLE CAP RH	X	80.47		
43	1	REAR RIM RH	ref	1100.00		
44	1	REAR TYRE RH	X		\$ 280.00	
45	1	REAR SHOCK ABSORBER RH	? bt	1307.71		
46	1	REAR WHEEL HUB & BEARING	? bt	1004.76		
47	1	REAR AXLE BEAM	X	2077.60		
48	1	REVERSE SENSOR	? new	848.44	4524.22	
49	1	REAR WINDSCREEN GLASS	X	1674.60		
50	1	REAR WINDSCREEN GLASS MOULDING	new	with glass		
51	1	REAR FENDER SEALANT	new		\$ 80.00	
52	1	REAR FENDER GLASS SEALANT	new		\$ 80.00	
53	1	SPARE TYRE PANEL SEALANT	X		\$ 80.00	
54	1	TAILLAMP PAD	X		\$ 80.00	
55	1	TAILLAMP PANEL SEALANT	new		\$ 80.00	
56	1	REAR WINDSCREEN GLASS SEALANT	new		\$ 80.00	
57	1	REAR WINDSCREEN GLASS INNER SEAL	new		\$ 80.00	
58	1	REAR WINDSCREEN GLASS PRIMER & CLENER	new		\$ 80.00	
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vehicle Reg. No. : SMM8825L
Vehicle Reg. Date: 31/8/2010
Make / Model : AUDI A4 1.8 TFSI MU
Engine No. : CDH071802
Chassis No. : WAUZZZ8KXAA071500

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	TO CUT WELD FRT PANEL,JACK ,STRAIGHTEN CHASSIS,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	\$ 2,400.00	900
2	To putty,respray painting and polish rear affected areas. Rear Portion.	\$ 2,400.00	900
3	To remove and transfer bootlid components.	\$ 180.00	X
4	To check and rectify wiring system.	\$ 150.00	30
5	To remove and replace reverse sensor.	\$ 150.00	30
6	To remove and replace rear windscreen glass	\$ 180.00	120
7	To remove and refit interior parts and upholstery.	\$ 180.00	60
8	To rust proof affected areas.	\$ 200.00	50
9	To remove and replace rear fender glass	\$ 150.00	860
10	To remove & transfer rear door rh component	\$ 180.00	X
11	To do wheel alignment	\$ 180.00	90
12	To do tyre balancing	\$ 150.00	30
13	To remove & install rear undercarriage	\$ 280.00	150? photo
14	To remove & refit petrol tank to assist work load.	\$ 350.00	100? photo

\$ -

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
 60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
 Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SMM8825L
 Vehicle Reg. Date: 31/8/2010
 Make / Model : AUDI A4 1.8 TFSI MU
 Engine No. : CDH071802
 Chassis No. : WAUZZZ8KXAA071500

ATTN: AH HAN
 PLEASE QUOTE COST/LIST PRICE
 FAX: 6745 4442

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR SHOCK ABSORVER STOPPER RH	REC ✓	\$ 90.77		
2	1	REAR SHOCK ABSORVER TOP MOUNT RH	REC ✓	\$ 189.85		
3	1	REAR LOWER ARM RH	bt ✓	\$ 600.33		
4	1	REAR UPPER ARM RH	bt ✓	\$ 488.96		
5	1	REAR CONTROL ARM RH	bt ✓	\$ 477.20		
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Handwritten signature
 29/11

Customer:		Date:	28-Nov-19 2:35 PM
Company:	VERMOGEN ACE	VIN	
License No:	SMM8825L	Technician:	IVAN
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

AUDI, A4 [8K], 2009-2015, (1BA) Normal Suspension Right Hand Drive

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	---	---	---
		Right	---	---	---	---
	Camber	Left	-1.4°	---	---	-1.4°
		Right	-1.3°	---	---	-1.3°
	Toe	Left	-0.30°	0.10°	0.25°	-0.30°
		Right	0.25°	0.10°	0.25°	0.30°
Total		-0.05°	0.15°	0.50°	0.00°	
Rear	Camber	Left	-1.9°	-1.8°	-0.9°	-1.9°
		Right	-1.9°	-1.8°	-0.9°	-1.9°
	Toe	Left	0.45°	0.10°	0.25°	0.45°
		Right	-0.60°	0.10°	0.25°	-0.60°
		Total	-0.15°	0.15°	0.50°	-0.15°
	Thrust Angle		-0.5°	-0.2°	0.2°	-0.5°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		---	---	---	---
	Right		---	---	---	---
Included Angle	Left		---	---	---	---
	Right		---	---	---	---
Toe Out On Turns	Left		---	1.3°	2.3°	---
	Right		---	1.3°	2.3°	---
Maximum Turns	Left		---	37.6°	41.1°	---
	Right		---	37.6°	41.1°	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		3mm	---	---	3mm
	Rear		3mm	---	---	3mm
Track Width Diff.			15mm			16mm
Wheel Base Diff.			1mm			1mm
Front Ride Height	Left		---	381mm	401mm	---
	Right		---	381mm	401mm	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						---

Customer:		Date:	06-Dec-19 11:55 AM
Company:		VIN	
License No:	SMM8825L	Technician:	IVAN
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT
AUDI, A4 [8K], 2009-2015, (1BA) Normal Suspension Right Hand Drive

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	---	---	---
		Right	---	---	---	---
	Camber	Left	-1.3°	---	---	-1.2°
		Right	-1.3°	---	---	-1.2°
	Toe	Left	0.10°	0.10°	0.25°	0.25°
		Right	-0.10°	0.10°	0.25°	-0.20°
Total		0.00°	0.15°	0.50°	0.05°	
Rear	Camber	Left	-1.5°	-1.8°	-0.9°	-1.5°
		Right	-0.8°	-1.8°	-0.9°	-0.7°
	Toe	Left	0.20°	0.10°	0.25°	0.20°
		Right	-0.05°	0.10°	0.25°	0.20°
		Total	0.15°	0.15°	0.50°	0.40°
	Thrust Angle		-0.1°	-0.2°	0.2°	0.0°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		---	---	---	---
	Right		---	---	---	---
Included Angle	Left		---	---	---	---
	Right		---	---	---	---
Toe Out On Turns	Left		---	1.3°	2.3°	---
	Right		---	1.3°	2.3°	---
Maximum Turns	Left		---	37.6°	41.1°	---
	Right		---	37.6°	41.1°	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		4mm	---	---	1mm
	Rear		2mm	---	---	-2mm
Track Width Diff.			14mm			14mm
Wheel Base Diff.			1mm			3mm
Front Ride Height	Left		---	381mm	401mm	---
	Right		---	381mm	401mm	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						---



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19021010/T1sd3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 27-12-2019		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 729E	Veh. Inspected	SMM 8825L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905540/RUC	Excess (\$)	0.00	
Assign From	YONG KANG MELVIN	Assign Date	27/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8KXAA071500	Colour	BLACK	
Odometer	158570	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2019	Inspection Date	27/11/2019	
Survey held at	60 JALAN LAM HUAT#03-35/36			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 8825L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	1,600.70	1,600.70
2	REAR BUMPER SIDE RETAINER	N/S NOT NECESSARY / O/S DEFORMED	161.98	80.99
2	REAR BUMPER SIDE BRACKET	N/S NOT NECESSARY / O/S DEFORMED	159.54	79.77
1	REAR BUMPER LOWER SKIRT	TORN	399.70	399.70
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	600.33	-
1	REAR BUMPER REINFORCEMENT CENTER BRACKET	CRACKED	401.50	401.50
1	SET REAR BUMPER CLIPS	NECESSARY	72.00	72.00
1	REAR BOOT	TO REPAIR SEE LABOUR	2,397.60	-
2	REAR BOOT LAMP	N/S NOT NECESSARY / O/S CUT	799.20	399.60
1	REAR BOOT EMBLEM - LOGO	NECESSARY	130.71	130.71
1	REAR BOOT EMBLEM - A4	NECESSARY	99.79	99.79
1	REAR BOOT EMBLEM - 1.8T	NECESSARY	99.79	99.79
1	REAR BOOT WEATHERSTRIP	NOT NECESSARY	80.37	-
1	REAR END PANEL	NOT NECESSARY	1,009.60	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	288.96	-
1	SET REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	72.00	-
2	TAILLAMP	N/S NOT NECESSARY / O/S CRACKED	1,001.94	500.97
2	TAILLAMP BRACKET	NOT NECESSARY	181.54	-
2	TAILLAMP CLIPS	N/S NOT NECESSARY / O/S NECESSARY	15.00	7.50
2	TAILLAMP PANEL	NOT NECESSARY	921.58	-
2	REAR FENDER	N/S NOT NECESSARY / O/S BENT	3,599.40	1,799.70

Report Ref No. CS/SMO19021010/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNERSHIELD	N/S NOT NECESSARY / O/S CUT	401.94	200.97
2	SET REAR FENDER INNERSHIELD CLIPS	N/S NOT NECESSARY / O/S NECESSARY	144.00	72.00
1	REAR FENDER INNER TRIMBOARD RH	NOT NECESSARY	499.91	-
1	REAR FENDER INNER TRIMBOARD CLIPS RH	NOT NECESSARY	72.00	-
1	REAR FENDER OUTER MOULDING RH	NECESSARY	300.77	300.77
1	REAR FENDER GLASS RH	NOT NECESSARY	399.60	-
1	REAR FENDER GLASS MOULDING RH	NECESSARY	399.60	399.60
1	REAR FENDER AIR DUCT RH	CRACKED	100.71	100.71
1	REAR WHEEL HOUSE RH OUTER	NOT NECESSARY	1,300.71	-
1	REAR WHEEL HOUSE RH INNER	NOT NECESSARY	700.97	-
1	PETROL TANK COVER	BENT	288.96	288.96
1	PETROL TANK COVERT RIVERT	NECESSARY	15.00	15.00
1	SPARE TYRE PANEL	NOT NECESSARY	1,300.71	-
1	SPARE TYRE LOWER COVER	NOT NECESSARY	388.96	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,800.70	-
1	REAR DOOR LOCK RH	NOT NECESSARY	500.71	-
1	REAR DOOR LOCK CATCH RH	NOT NECESSARY	100.97	-
1	REAR DOOR STICKER RH	NOT NECESSARY	80.97	-
1	REAR DOOR WEATHERSTRIP RH	NOT NECESSARY	200.97	-
1	REAR DOOR OUTER HANDLE RH	NOT NECESSARY	200.97	-
1	REAR DOOR OUTER HANDLE CAP RH	NOT NECESSARY	80.97	-
1	REAR RIM RH	CUT	1,400.97	880.00
1	REAR SHOCK ABSORBER RH	BENT	1,397.71	780.00
1	REAR WHEEL HUB & BEARING	BENT	1,009.76	1,009.76
1	REAR AXLE BEAM	NOT NECESSARY	2,477.60	-
4	REVERSE SENSOR	NOT WORKING (2PCS ONLY)	848.44	424.22
1	REAR WINDSCREEN GLASS	NOT NECESSARY	1,479.60	-
1	REAR WINDSCREEN GLASS MOULDING (NPA)	NOT NECESSARY	-	-
1	REAR SHOCK ABSORBER STOPPER RH (ADDITIONAL)	NECESSARY	90.77	90.77

Report Ref No. CS/SMO19021010/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SHOCK ABSORBER TOP MOUNT RH (ADDITIONAL)	NECESSARY	189.85	189.85
1	REAR LOWER ARM RH (ADDITIONAL)	BENT	600.33	325.00
1	REAR UPPER ARM RH (ADDITIONAL)	BENT	488.96	488.96
1	REAR CONTROL ARM RH (ADDITIONAL)	BENT	477.20	307.00
	LESS 5% DISCOUNT		-1,691.73	-577.31
			32,142.79	10,968.98
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TYRE RH (SN)	NOT NECESSARY	280.00	-
1	REAR FENDER SEALANT (SN)	NECESSARY	80.00	80.00
1	REAR FENDER GLASS SEALANT (SN)	NECESSARY	80.00	80.00
1	SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	TAILLAMP PAD (SN)	NOT NECESSARY	80.00	-
1	TAILLAMP PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	80.00
1	REAR WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	80.00	80.00
1	REAR WINDSCREEN GLASS PRIMER & CLEANER (SN)	NECESSARY	80.00	80.00
			920.00	400.00
	<u>LABOUR</u>			
	TO CUT WELD FRT PANEL, JACK, STRAIGHTEN CHASSIS, REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR DOOR RH.		2,400.00	900.00
	TO PUTTY, RESPRAY PAINTING AND POLISH REAR AFFECTED AREAS. REAR PORTION.		2,400.00	900.00
	TO REMOVE AND TRANSFER BOOTLID COMPONENTS.	NOT NECESSARY	180.00	-
	TO CHECK AND RECTIFY WIRING SYSTEM.		150.00	30.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		150.00	30.00
	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE AND REFIT INTERIOR PARTS AND UPHOLSTERY.		180.00	60.00
	TO RUST PROOF AFFECTED AREAS.		200.00	50.00
	TO REMOVE AND REPLACE REAR FENDER GLASS.		150.00	60.00
	TO REMOVE & TRANSFER REAR DOOR RH COMPONENT.	NOT NECESSARY	180.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DO WHEEL ALIGNMENT.	NOT NECESSARY	180.00	80.00
	TO DO TYRE BALANCING.		150.00	30.00
	TO REMOVE & INSTALL REAR UNDERCARRIAGE.		280.00	150.00
	TO REMOVE & REFIT PETROL TANK TO ASSIST WORK LOAD.		350.00	-
			7,130.00	2,410.00
GRAND TOTAL			40,192.79	13,778.98
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS/SMO19021010/T1sd3e2

MARKET VALUE: \$28,000.00(EST)-LTA REIMBURSEMENT VALUE: \$21,125.00=NETT VALUE: \$6,875.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.