

ASS. REC. BY:

REF:

CS/FC19021011/KQF3M2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Meng Chua San San

of FCI

Date/Time: 27.11.19 4.16p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFG 4176C

Insured:

SHC 1931C

at Workshop m/s

VB motor works

Tel:

9750880

of

BIC 7 101-92 sm ming Industrial Estate Subor C

Policy No:

Claim No:

D19007488MFS4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22.11.2019

CA / REV / REP. / REV 24 HRS

11/2p

28.11.2019

H.O.D. Endorsement:

Date/Time:

27.11.19 4.23p.m

Person Contacted:

Mr Chang

Vehicle IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate Inspection: 9 sm ming Industrial Est setro (101-4K)
	SFG 4176C - X
	SHC 1931C - X

25/11/19 @ 10.59am informed Meng Chua, we are pending estimate from repairer.

11/12/19 @ 11.42am checked with Mr Chang, the status of estimate.

03/01/20 @ 12pm we send email to Mr Chang to check status of estimate.

10/3/20 @ 5.12pm revised to Meng Chua by email.

REF: fcl

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: _____ Date: 28.11.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SPE 4176 C

at Workshop m/s VB motor workz

of 9 sin ming Industrial Estate sector CA 01-144

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 84810

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 10/12/19 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SPE 4176 C

Yr Regn: 03 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta c.c. 1390

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 180084

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW 888 1K 8 AM 090028

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: _____

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 22/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 151

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 28/11/19

Date / Time Action / Instruction

28/11 Est not ready

RECEIVED 11 MAR 2020

5/3 L1R 8 2550h

10/3/20 @ 2.28pm confirmed with Mr Chang LS \$ 2550 (Red \$ 22343.74, 90%.)

MV: \$48,000.00 (EST)

LTA: \$25,336.00

NV: \$22,664.00

Date/Time, File Pass to?

☐

Preli. Report

10/3 train

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Meal and (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

14x15= 210

170+ 210

50

13

443

Rep. Form:

Lump Sum / Fee:

TP

2550



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007488MFSH

Date: 10th March 2020

Our Ref: CS/FCI19021011/Kqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFE 4176C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/11/2019 at the premises of M/s V8 MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>24,893.74</u> .
Revised Estimate Amount	: S\$ <u>2,550.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-11-2019	Our Ref No. D19007488MFSH
Accident Date	22-11-2019	Claim Type. Third Party
Insured Vehicle	SHC0931C	Third Party Vehicle. SFE4176C
Survey Location	BLOCK 7 #01-92SIN MING INDUSTRIAL ESTATE SECTOR C	
Contact Person.	MR CHANG	
Contact No.	0/ 97250880	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	V8 MOTOR WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 March 2020 5:12 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19007488MFSH/1
Attachments: CSFCI19021011Kqf3.pdf

Dear Merina,

Enclosed herewith preliminary advice of SFE 4176C.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 29 November 2019 10:59 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007488MFSH/1

Dear Merina,

Please be informed that we have inspected the vehicle SFE 4176C on 28/11/2019.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 27 November 2019 4:27 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007488MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 November 2019 10:59 AM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19007488MFSH/1

Dear Merina,

Please be informed that we have inspected the vehicle SFE 4176C on 28/11/2019.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 27 November 2019 4:27 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007488MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 27 November, 2019 4:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007488MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	168F
Vehicle Details	
Vehicle No.:	SFE4176C
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1K23G5 MX
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	CAX437929
Chassis No.:	WVWZZZ1KZAM090026
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,576.00
Original Registration Date:	31 Mar 2010
First Registration Date:	31 Mar 2010
Transfer Count:	2
Actual ARF Paid:	\$20,576.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2020
PARF Rebate Amount:	\$10,288.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,287.00
COE Rebate Amount:	\$15,048.00
Total Rebate Amount:	\$25,336.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Nov 2019

OK

V8 MOTOR WERKZ PRIVATE LIMITED

7 #01-92 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644

TEL NO : 91442977

EMAIL : V8MOTORWERKZ@GMAIL.COM

ROC NO. : 201622378N

*Not Notified
11 Sep @ 2550h
Resurvey After Pain
4 days*

DATE :13/12/19

MAKE / MODEL : VW JETTA

VEHICLE PLATE NUM : SFE4176C

ESTIMATED COST :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Description	QTY	Amount
1	FRONT BUMPER <i>1213-62 Bull m</i>	1PCS	\$1382.45
2	FRONT BUMPER BRACKET <i>1m</i>	1PCS	\$155.15
3	FRONT BUMPER REINFORCEMENT <i>1m</i>	1PCS	\$731.40
4	FRONT BUMPER LOWER GRILLE <i>1m</i>	1PCS	\$773.75
5	FRONT RH HEADLAMP <i>1m</i>	1PCS	\$1753.65
6	FRONT RH FENDER <i>B1</i>	1PCS	\$754.45
7	FRONT RH FENDER INNER SHIELD <i>1m</i>	1PCS	\$289.95
8	FRONT RH SHOCK ABSORBER <i>1m</i>	1PCS	\$1582.40
9	FRONT RH KNUCKLE ARM <i>1m</i>	1PCS	\$731.60
10	FRONT RH KNUCKLE BEARING <i>1m</i>	1PCS	\$491.60
11	FRONT RH LOWER ARM <i>1m</i>	1PCS	\$457.39
12	FRONT RH DRIVE SHAFT <i>1m</i>	1PCS	\$2665.15
13	STEERING RACK AND PINION <i>1m</i>	1PCS	\$5875.15
14	FRONT RH TIE ROD <i>1m</i>	1PCS	\$101.95
15	FRONT RH ABS SENSOR <i>1m</i>	1PCS	\$283.85
16	FRONT CROSS MEMBER <i>1m</i>	1PCS	\$1523.85
17	FRONT BUMPER CLIP <i>1m</i>	1PCS	\$50.00
18	FRONT FENDDER INNER TRIM CLIP <i>1m</i>	1PCS	\$50.00

101633.74

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19021011/Kqf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-03-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 931C	Veh. Inspected	SFE 4176C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007488MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA SAN SAN	Assign Date	27/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA (A)	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WVWZZZ1KZAM090026	Colour	GREY	
Odometer	180084	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	2 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	2 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	3 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2019	Inspection Date	28/11/2019	
Survey held at	V8 MOTOR WERKZ PTE LTD 9 SIN MING INDUSTRIAL EST SECTOR C #01-44 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 4176C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED / DENTED	1,382.45	1,213.62
1	FRONT BUMPER BRACKET	SERVICEABLE	155.15	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	731.40	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	773.75	-
1	FRONT RH HEADLAMP	SERVICEABLE	1,753.65	-
1	FRONT RH FENDER	BENT	754.45	754.45
1	FRONT RH FENDER INNER SHIELD	SERVICEABLE	289.95	-
1	FRONT RH SHOCK ABSORBER	SERVICEABLE	1,582.40	-
1	FRONT RH KNUCKLE ARM	SERVICEABLE	731.60	-
1	FRONT RH KNUCKLE BEARING	SERVICEABLE	491.60	-
1	FRONT RH LOWER ARM	SERVICEABLE	457.39	-
1	FRONT RH DRIVE SHAFT	TO REPAIR SEE LABOUR	2,665.15	-
1	STEERING RACK AND PINION	SERVICEABLE	5,875.15	-
1	FRONT RH TIE ROD	SERVICEABLE	101.95	-
1	FRONT RH ABS SENSOR	SERVICEABLE	283.85	-
1	FRONT CROSS MEMBER	SERVICEABLE	1,523.85	-
1	FRONT BUMPER CLIP	NECESSARY	50.00	50.00
1	FRONT FENDER INNER TRIM CLIP	NOT NECESSARY	50.00	-
1	BRAKE FLUID	NOT NECESSARY	80.00	-
1	TYRE	SERVICEABLE	450.00	-
	LESS 10% DISCOUNT		-	-201.81
			20,183.74	1,816.26
SPECIAL NETT ITEMS				
1	RIM (SN)	DENTED	1,200.00	480.00
1	FRONT BUMPER SPLITTER (SN)	SERVICEABLE	350.00	-
			1,550.00	480.00
LABOUR				
	CHECK WIRING AND LIGHTING SYSTEM.		60.00	20.00

Report Ref No. CS/FCI19021011/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DIAGNOSIS CHECK AND CLEAR FAULT CODE.	NOT NECESSARY	500.00	-
	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT.		200.00	60.00
	REMOVE AND RENEW FRONT CROSS MEMBER.	NOT NECESSARY	200.00	-
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.	NOT NECESSARY	350.00	-
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT RH DRIVE SHAFT.		900.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	30.00
			3,160.00	910.00
GRAND TOTAL			24,893.74	3,206.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CS/FCI19021011/Kqf3n2

MARKET VALUE: \$48,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$25,336.00=NETT VALUE: \$22,664.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.