

03/TP1902/017/Ar3n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____ 87827171

of _____

Insured: _____

Policy No _____

Claim No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMJ9858B. Yr Regn: 2019 March.

Type ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Avante. C.C. 1591

Colour: Silver. A/C: Insured / Std / NI / NA

Sp. Reading: 8779 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH D841CMK4878889.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Mod: Nil / ☒ R / STD A/Rim or _____

Tyre Size: F: 205/55R16-

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 22/11/19 D.O.I. 26/11/19.

Survey held at CAS.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| | TP Direct Asia Independent. |
| | SMJ9858B - X |
| | Open forward cage etc. into defunct. |
| | MV: RECEIVED 10 MAR 2020 |
| | PV: |
| | Nett. |
| 9/3/20 | Adrian confirmed LS \$11,800 (Real 12,995.60, 57%) |

Date/Time, File Path to?

☐ : Prel. Report

If _____

☐ : Final Report

Date/Time, File Path to?

03 - typist

Report Format: TP

Lump Sum / L.B. 11,800

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp 1\$☐ : Interview 1\$☐ : Tech. Insp 1\$☐ : WASH 1\$

Survey Fee

Transportation

S - P.S. 34

Phone

Other

Total

14x15 = 210

170 + 210

50

50

123

80

683

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 22/11/2019 12:49 |
| Date Of Accident | 22/11/2019 09:20 |
| Exact Location Of Accident | ALONG WHAMPOA EAST TOWARDS SERANGOON ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SMJ9858B |
| Insured/Policyholder | |
| Name Of Registered Owner | WONG AH SING |
| NRIC No | S2646686E |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-94561392 |
| Alternative Phone No | OFFICE-94561392 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | HYUNDAI |
| Model | AVANTE |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | CN039179 |
| Cover Note Number | CN039179 |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | WONG AH SING |
| NRIC No | S2646686E |
| Date Of Birth | 18/10/1957 |
| Occupation | INDOOR |
| Date Of Driving Pass | 11/07/1977 |
| Driving Experience | 42 YEARS AND 4 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-94561392 |
| Fax Number | |
| Contact Number | OFFICE-94561392 |
| Email Address | NOEMAIL |

| | |
|---|-------------------------------|
| Address | 38A BENDEMEER ROAD #05-820 |
| Postcode | S331038 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

ON 22/11/2019 AT ABOUT 0920, I WAS TRAVELLING ON THE SECOND LANE ALONG WHAMPOA EAST TOWARDS SERANGOON ROAD. DUE TO THE RED TRAFFIC LIGHT AHEAD, THE FRONT CAR STOPPED AND I FOLLOW SUIT. SUDDENLY I HEARD A LOUD BANG FROM THE REAR OF MY VEHICLE A AND A GREAT IMPACT. WHEN I ALIGHTED, I REALIZED IT WAS VEHICLE B FAILED TO STOP ON TIME, CAUSING THE COLLISION AND DAMAGES TO MY VEHICLE A.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SGU1696S |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

Name

WONG AH SING

Approximate Age

Injuries Sustain

Injured person in which vehicle?


Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

SKETCH PLAN



A - SMJ 9858 B
B - SKM 1696 S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22.11.2014, at about 0920, I was travelling on the second lane along Whampoa East towards Serangoon Road. Due to the red traffic light ahead, the front car stopped and I follow suit. Suddenly, I heard a loud bang from the rear of my vehicle A and a great impact. When I alighted, I realised it was vehicle B failed to stop in time, causing the collision and damages to my vehicle A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Reported at No. 100, 101, 102

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: DIRECT ASIA INSURANCE

Address: NO 20, ANSON ROAD, #08-01
S(079912)

Telephone: 65321818

Fax: 64231197

Email: claim@directasia.com

Make/ Model : HYUNDAI AVANTE

Date: 25.11.2019

Chassis No : KMHD841CMKU878889

Vehicle No: SMJ9858B

Date/Time of Accide: 22.11.2019/ 09 20

Date of Reg: 27.03.2019

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

| ITEMS | PARTS DESCRIPTION | QTY | LIST PRICE \$ | | FINAL PRICE \$ |
|-------|---|-----|---------------|--|----------------|
| 1 | REAR BOOTLID <i>Dented.</i> | 1 | \$ 1,853.60 | | \$ 1,853.60 |
| 2 | REAR BOOTLID HINGES <i>Not in</i> | 2 | \$ 128.50 | | \$ 257.00 |
| 3 | REAR BOOTLID INNER LOCK <i>Not in</i> | 1 | \$ 185.70 | | \$ 185.70 |
| 4 | REAR BOOTLID OUTER LOCK ASSY <i>Not in</i> | 1 | \$ 236.50 | | \$ 236.50 |
| 5 | REAR BOOTLID SMARTKEY ANTENNA <i>Not in</i> | 1 | \$ 189.70 | | \$ 189.70 |
| 6 | REAR BOOTLID INNER TRIM <i>Not in</i> | 1 | \$ 195.80 | | \$ 195.80 |
| 7 | REAR BOOTLID LATCH <i>Not in</i> | 1 | \$ 38.50 | | \$ 38.50 |
| 8 | REAR BOOTLID LAMP <i>Not in</i> | 2 | \$ 664.20 | | \$ 1,328.40 |
| 9 | BOOTLID HINGE TORSION BAR LH/RH <i>Not in</i> | 2 | \$ 68.70 | | \$ 68.70 |
| 10 | REAR BOOTLID LOGO <i>Not in</i> | 1 | \$ 79.60 | | \$ 79.60 |
| 11 | REAR BOOTLID " AVANTE " EMBLEM <i>Not in</i> | 1 | \$ 98.70 | | \$ 98.70 |
| 12 | REAR BOOTLID " ELITE " EMBLEM <i>Not in</i> | 1 | \$ 76.80 | | \$ 76.80 |
| 13 | REAR BOOTLID WEATHERSTRIP <i>Not in</i> | 1 | \$ 145.60 | | \$ 145.60 |
| 14 | SPARE TYRE FLOOR PANEL <i>Not in</i> | 1 | \$ 685.20 | | \$ 685.20 |
| 15 | SPARE TYRE TOP BOARD <i>Not in</i> | 1 | \$ 305.60 | | \$ 305.60 |
| 16 | SPARE TYRE WHEEL COVER CAP <i>Not in</i> | 1 | \$ 68.90 | | \$ 68.90 |
| 17 | REAR SILENCER BOX <i>Not in</i> | 1 | \$ 68.90 | | \$ 68.90 |
| 18 | REAR SILENCER BOX MOUNTING <i>Not in</i> | 1 | \$ 702.50 | | \$ 702.50 |
| 19 | END PANEL <i>Dented</i> | 1 | \$ 657.80 | | \$ 657.80 |
| 20 | END PANEL SMART KEY RELEASE <i>Not in</i> | 1 | \$ 187.50 | | \$ 187.50 |
| 21 | END PANEL TOP GARNISH <i>Not in</i> | 1 | \$ 175.90 | | \$ 175.90 |
| 22 | END PANEL BOOT RELEASE ANTENNA <i>Not in</i> | 1 | \$ 265.70 | | \$ 265.70 |
| 23 | TAILAMPS <i>Not in</i> | 2 | \$ 897.50 | | \$ 1,795.00 |
| 24 | TAILAMPS PANEL <i>Not in</i> | 2 | \$ 245.60 | | \$ 491.20 |
| 25 | REAR CORNER BLIND SPOT DETECTOR <i>Not in</i> | 2 | \$ 1,177.80 | | \$ 2,355.60 |
| 26 | REAR BUMPER <i>Dented</i> | 1 | \$ 598.70 | | \$ 598.70 |
| 27 | REAR BUMPER GUARD RH <i>Not in</i> | 1 | \$ 75.60 | | \$ 75.60 |
| 28 | REAR BUMPER NUMBER PLATE LAMPS <i>Not in</i> | 2 | \$ 68.50 | | \$ 137.00 |
| 29 | REAR BUMPER LOWER <i>Not in</i> | 1 | \$ 398.20 | | \$ 398.20 |
| 30 | REAR BUMPER LOWER COVER LH <i>Not in</i> | 1 | \$ 185.70 | | \$ 185.70 |
| 31 | REAR BUMPER RETAINERS <i>Not in</i> | 2 | \$ 85.90 | | \$ 171.80 |

| | | | | | | |
|------------------------------|---|---|-------------|--------------------|---------------------|---|
| 32 | REAR BUMPER REFLECTOR <i>could</i> | 2 | \$ 289.50 | | \$ 579.00 | ✓ |
| 33 | REAR BUMPER REINFORCEMENT <i>could</i> | 1 | \$ 398.70 | | \$ 398.70 | ✓ |
| 34 | REINFORCEMENT BRACKETS(BOTTOM) <i>new</i> | 3 | \$ 76.80 | | \$ 230.40 | ✓ |
| 35 | REINFORCEMENT BRACKETS(TOP) <i>new</i> | 2 | \$ 76.80 | | \$ 153.60 | ✓ |
| 36 | REINFORCEMENT BRACKETS METAL <i>Best</i> | 2 | \$ 198.80 | | \$ 397.60 | ✓ |
| 37 | REAR FENDER INNER TRIM <i>new</i> | 2 | \$ 279.90 | | \$ 559.80 | ✓ |
| 38 | REAR FENDER <i>Repr</i> | 2 | \$ 1,768.60 | | \$ 3,537.20 | ✓ |
| 39 | REAR FENDER INNER COWLING <i>new</i> | 2 | \$ 165.90 | | \$ 331.80 | ✓ |
| Total List Price Cost | | | | | \$ 20,269.50 | |
| | | | | PARTS DISCOUNT 20% | \$ 16,215.60 | |

1326870

1061496

| SPECIAL NETT | PARTS DESCRIPTION | QTY | PRICE \$ | | FINAL PRICE \$ | |
|---------------------------------|--|-------|-----------|--|------------------|---|
| 1 | REVERSE SENSORS <i>Dargd</i> | 1 SET | \$ 250.00 | | \$ 250.00 | ✓ |
| 2 | REAR NUMBER PLATE WITH CASING <i>Best</i> | 1 SET | \$ 50.00 | | \$ 50.00 | ✓ |
| 3 | REAR BUMPER CLIPS <i>new</i> | 1 SET | \$ 30.00 | | \$ 30.00 | ✓ |
| 4 | END PANEL TOP GARNISH CLIPS <i>Ne</i> | 1 SET | \$ 30.00 | | \$ 30.00 | ✓ |
| 5 | REAR BOOTLID INNER TRIM CLIPS <i>new</i> | 1 SET | \$ 30.00 | | \$ 30.00 | ✓ |
| 6 | END PANEL SEALANT <i>Ne</i> | 2 | \$ 80.00 | | \$ 80.00 | ✓ |
| 7 | FLOOR PANEL INSULATOR PADS <i>new</i> | 1 SET | \$ 200.00 | | \$ 200.00 | ✓ |
| 8 | REAR FENDER INNER TRIM CLIPS <i>new</i> | 2 SET | \$ 60.00 | | \$ 60.00 | ✓ |
| 9 | REAR FENDER INNER COWLING CLIPS <i>new</i> | 2 SET | \$ 60.00 | | \$ 60.00 | ✓ |
| 10 | REAR BUMPER LOWER COVER CLIPS <i>Ne</i> | 1 SET | \$ 30.00 | | \$ 30.00 | ✓ |
| Total Special Nett Items | | | | | \$ 820.00 | |

640

| Labour Works/ Panel Beating Related Works | |
|---|---------------------|
| Job Scope | Quotation |
| TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS | \$ 3,600.00 |
| | 1500. |
| Spray Painting | |
| Job Scope | Quotation |
| TO RESPRAY AFFECTED AREAS | \$ 2,800.00 |
| | 1400. |
| Others Cost (Accident Repair Related Expenses) | |
| Job Scope | Quotation |
| TO TUFFCOAT AFFECTED AREA | \$ 200.00 |
| TO CONDUCT WIRING CHECK ON THE REAR TAILAMPS | \$ 150.00 |
| TO REMOVE/ REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING | \$ 180.00 |
| TO REMOVE/ REFIT & REPLACE REAR SILENCER BOX | \$ 180.00 |
| TO REMOVE/ REFIT REAR INTERIOR UPHOLSTERY | \$ 180.00 |
| TO CONDUCT WATER LEAKAGE TEST | \$ 120.00 |
| TO APPLY UNDERCOATING TO THE AFFECTED AREAS | \$ 200.00 |
| TO REMOVE AND REPLACE BOOTLID MECHANISM | \$ 150.00 |
| Total Others Cost | \$ 1,360.00 |
| GRAND TOTAL | \$ 24,795.60 |

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax: +65 6509 9501

3490

Adrian Lim
L/s 26/11/19.

10 Days.

total: 14744.96

L/s: 11.8K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|--|----------------------------|
| CAS GARAGE PTE LTD | | Ref : CS/TP19021017/Avd3n2 | |
| 1 KAKI BUKIT AVENUE 6 #02-22 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | Date : 10-03-2020 | |
| ON BEHALF OF WONG AH SING | | Code : TP516 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| | Insured Veh. | Veh. Inspected | SMJ 9858B |
| | Policy No. | Coverage (\$) | 0.00 |
| | Claim No. | Excess (\$) | 0.00 |
| | Assign From | Assign Date | 26/11/2019 |
| 2. Vehicle Particulars & Condition | | | |
| | Make & Model | HYUNDAI AVANTE | c.c 1591 |
| | Engine No. | HIDDEN | Year of Reg. 2019 |
| | Chassis No. | KMHD841CMKU878889 | Colour SILVER |
| | Odometer | 8779 | Steering IN ORDER |
| | Brakes | IN ORDER | Modification SPORTS RIM |
| | General | GOOD | |
| 3. Conditions of Tyres | | | |
| | | Size | Make Balance |
| | R/H Front Tyre | 205/55 R16 | KUMHO 6 mm |
| | L/H Front Tyre | 205/55 R16 | KUMHO 6 mm |
| | R/H Rear Tyre | 205/55 R16 | KUMHO 6 mm |
| | L/H Rear Tyre | 205/55 R16 | KUMHO 6 mm |
| 4. Description of Damages | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | |
| 5. General Information | | | |
| | Accident Date | 22/11/2019 | Inspection Date 26/11/2019 |
| | Survey held at | CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT | |
| 5a. Remarks | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | |
| 5b. Estimate Days of Repair | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 10 Working Days |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 9858B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BOOTLID | DENTED | 1,853.60 | 1,853.60 |
| 2 | REAR BOOTLID HINGES @\$128.50 | BENT | 257.00 | 257.00 |
| 1 | REAR BOOTLID INNER LOCK | DAMAGED | 185.70 | 185.70 |
| 1 | REAR BOOTLID OUTER LOCK ASSY | CRACKED | 236.50 | 236.50 |
| 1 | REAR BOOTLID SMARTKEY ANTENNA | CRACKED | 189.70 | 189.70 |
| 1 | REAR BOOTLID INNER TRIM | NOT NECESSARY | 195.80 | - |
| 1 | REAR BOOTLID LATCH | NOT NECESSARY | 38.50 | - |
| 2 | REAR BOOTLID LAMP @\$664.20 | CUT | 1,328.40 | 1,328.40 |
| 2 | BOOTLID HINGE TORSION BAR LH/RH @\$68.70 | NOT NECESSARY | 68.70 | - |
| 1 | REAR BOOTLID LOGO | NECESSARY | 79.60 | 79.60 |
| 1 | REAR BOOTLID "AVANTE" EMBLEM | NECESSARY | 98.70 | 98.70 |
| 1 | REAR BOOTLID "ELITE" EMBLEM | NECESSARY | 76.80 | 76.80 |
| 1 | REAR BOOTLID WEATHERSTRIP | CUT | 145.60 | 145.60 |
| 1 | SPARE TYRE FLOOR PANEL | BUCKLED | 685.20 | 685.20 |
| 1 | SPARE TYRE TOP BOARD | NOT NECESSARY | 305.60 | - |
| 1 | SPARE TYRE WHEEL COVER CAP | NOT NECESSARY | 68.90 | - |
| 1 | REAR SILENCER BOX | NOT NECESSARY | 68.90 | - |
| 1 | REAR SILENCER BOX MOUNTING | NOT NECESSARY | 702.50 | - |
| 1 | END PANEL | DENTED | 657.80 | 657.80 |
| 1 | END PANEL SMART KEY RELEASE | CRACKED | 187.50 | 187.50 |
| 1 | END PANEL TOP GARNISH | DEFORMED | 175.90 | 175.90 |
| 1 | END PANEL BOOT RELEASE ANTENNA | REPEATED | 265.70 | - |
| 2 | TAILLAMPS @\$897.50 | CRACKED | 1,795.00 | 1,795.00 |
| 2 | TAILLAMPS PANEL @\$245.60 | TO REPAIR SEE LABOUR | 491.20 | - |
| 2 | REAR CORNER BLIND SPOT DETECTOR @\$1177.80 | CRACKED | 2,355.60 | 2,355.60 |
| 1 | REAR BUMPER | DISTORTED | 598.70 | 598.70 |
| 1 | REAR BUMPER GUARD RH | NOT NECESSARY | 75.60 | - |
| 2 | REAR BUMPER NUMBER PLATE LAMPS @\$68.50 | NOT NECESSARY | 137.00 | - |
| 1 | REAR BUMPER LOWER | CRACKED | 398.20 | 398.20 |
| 1 | REAR BUMPER LOWER COVER LH | CRACKED | 185.70 | 185.70 |
| 2 | REAR BUMPER RETAINERS @\$85.90 | NECESSARY | 171.80 | 171.80 |
| 2 | REAR BUMPER REFLECTOR @\$289.50 | CRACKED | 579.00 | 579.00 |
| 1 | REAR BUMPER REINFORCEMENT | CRACKED | 398.70 | 398.70 |

Report Ref No. CS/TP19021017/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| 3 | REINFORCEMENT BRACKETS (BOTTOM) @\$76.80 | DAMAGED | 230.40 | 230.40 |
| 2 | REINFORCEMENT BRACKETS (TOP) @\$76.80 | NOT NECESSARY | 153.60 | - |
| 2 | REINFORCEMENT BRACKETS METAL @\$198.80 | BENT | 397.60 | 397.60 |
| 2 | REAR FENDER @\$1768.60 | TO REPAIR SEE LABOUR | 3,537.20 | - |
| 2 | REAR FENDER INNER COWLING @\$165.90 | NOT NECESSARY | 331.80 | - |
| 2 | REAR FENDER INNER TRIM @\$279.90 | NOT NECESSARY | 559.80 | - |
| | LESS 20% DISCOUNT | | -4,053.90 | -2,653.74 |
| | | | 16,215.60 | 10,614.96 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET REVERSE SENSORS (SN) | DAMAGED | 250.00 | 250.00 |
| 1 | SET REAR NUMBER PLATE WITH CASING (SN) | BENT | 50.00 | 50.00 |
| 1 | SET REAR BUMPER CLIPS (SN) | NECESSARY | 30.00 | 30.00 |
| 1 | SET END PANEL TOP GARNISH CLIPS (SN) | NECESSARY | 30.00 | 20.00 |
| 1 | SET REAR BOOTLID INNER TRIM CLIPS (SN) | NOT NECESSARY | 30.00 | - |
| 2 | END PANEL SEALANT (SN) | NECESSARY | 80.00 | 60.00 |
| 1 | SET FLOOR PANEL INSULATOR CLIPS (SN) | NECESSARY | 200.00 | 200.00 |
| 2 | SET REAR FENDER INNER TRIM CLIPS (SN) | NOT NECESSARY | 60.00 | - |
| 2 | SET REAR FENDER INNER COWLING CLIPS (SN) | NOT NECESSARY | 60.00 | - |
| 1 | SET REAR BUMPER LOWER COVER CLIPS (SN) | NECESSARY | 30.00 | 30.00 |
| | | | 820.00 | 640.00 |
| | LABOUR | | | |
| | TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMPS PANEL AND REAR FENDER. | | 3,600.00 | 1,500.00 |
| | TO RESPRAY AFFECTED AREAS. | | 2,800.00 | 1,400.00 |
| | TO TUFFCOAT AFFECTED AREA. | | 200.00 | 160.00 |
| | TO CONDUCT WIRING CHECK ON THE REAR TAILLAMPS. | | 150.00 | 30.00 |
| | TO REMOVE/REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING. | | 180.00 | 60.00 |
| | TO REMOVE/REFIT & REPLACE REAR SILENCER BOX. | NOT NECESSARY | 180.00 | - |
| | TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY. | | 180.00 | 120.00 |
| | TO CONDUCT WATER LEAKAGE TEST. | NOT NECESSARY | 120.00 | - |
| | TO APPLY UNDERCOATING TO THE AFFECTED AREAS. | | 200.00 | 120.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|-----------|---------------------------|-------------------|
| | TO REMOVE AND REPLACE BOOTLID MECHANISM. | | 150.00 | 100.00 |
| | | | 7,760.00 | 3,490.00 |
| GRAND TOTAL | | | 24,795.60 | 14,744.96 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 11,800.00 |

Report Ref No. CS/TP19021017/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.