

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST401/19/TP

Your Ref: TP claim against SHA4013L

20-Oct-19

India International Insurance

64 Cecil Street #04-05

IOB Building

Singapore 049711

Xiao Tony

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Honda CB190R no: FBL3048G

Date of accident: 15-10-2019

Parts supply:

2 pcs Handle bar @\$78.00	RH Bent	SS	156.00	78
2 pcs Handle bar grip @\$25.00	new		50.00	+
2 pcs Handle bar balancer @\$12.00	RH cut		24.00	12
1 pc Brake lever	cut		25.00	✓
1 pc Headlamp	new		155.00	7
1 pc Headlamp stay	new		45.00	7
1 pc Headlamp top nose garnish	new		45.00	+
2 pcs Headlamp side garnish (red & white) @\$65.00	RH cut		130.00	65
2 pcs Front signal lamp @\$25.00	new		50.00	+
1 pc R/h mirror with bracket assy	new		65.00	+
2 pcs Front side fairing @\$160.00	new RH could		320.00	160
1 set Front side fairing stickers	new		65.00	+
2 pcs Front fork @\$250.00	Bent		500.00	2
1 pc Front fork centre bracket	Bent		65.00	✓
1 pc Front fork top bracket	Bent		80.00	✓
1 pc Front fork centre shaft	Bent		80.00	✓
2 pcs Front fork lower holder bracket @\$25.00	Bent		50.00	2
1 pc Front brake disc	Bent		65.00	✓
1 pc Front brake caliper	cut		250.00	✓
1 pc Front rim	cut		180.00	✓
1 pc Front mudguard	del		55.00	✓
1 pc Front R/h footrest with bracket	Broken		45.00	✓
1 pc Front R/h footbrake lever	Bent		25.00	✓
1 pc Rear R/h footrest with bracket assy	cut		45.00	✓
1 pc Rear rim	Worpped		180.00	✓
			2,750.00	
		Less 10%:	(275.00)	
			170.00	+
			120.00	+
			220.00	200
			60.00	+
			3,045.00	

S/Nett Items

- 1 pc IU unit (S/Nett) new
- 1 pc Front tyre (S/Nett) new
- 1 pc Rear box (S/Nett) cut
- 1 pc Rear box bracket (S/Nett) new

200

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Honda CB190R no: FBL3048G

Date of accident: 15-10-2019

Parts supply:

Balance b/f:

S\$ 3,045.00

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To apply underseal

To respray affected part.

Transportation charges

To check wirings.

600

500.00	280
50.00	✓
350.00	250
40.00	✓
30.00	✓
<u>S\$ 4,015.00</u>	

Adrian Lj
L/s 27/11/19
04/12/19

total: 2564
L/s: 2050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: