



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005994
INV Date 02/09/2020
Reference CC6/CTI19021029/Qda3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SKZ 2568Z
Insured Veh. CB 6274R
Claim No. SNM19D205667
Policy No. DMB1SN3027401900
Accident Date 25/11/2019
Inspection Date 21/04/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19021029/Qda3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-09-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 6274R	Veh. Inspected	SKZ 2568Z
Policy No.	DMB1SN3027401900	Coverage (\$)	0.00
Claim No.	SNM19D205667	Excess (\$)	0.00
Assign From		Assign Date	21/04/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11106677	Colour	BLUE
Odometer	51941	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	FALKEN	6 mm
L/H Front Tyre	225/45 R18	FALKEN	6 mm
R/H Rear Tyre	225/45 R18	FALKEN	6 mm
L/H Rear Tyre	225/45 R18	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/11/2019	Inspection Date	21/04/2020
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 2568Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	800.00	800.00
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER RETAINER RH	SERVICEABLE	20.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	20.00	-
1	FRONT REINFORCEMENT	SERVICEABLE	320.00	-
1	HEAD LAMP LH	SCRATCHED	1,780.00	1,780.00
1	HEAD LAMP UPPER BRACKET LH	SERVICEABLE	30.00	-
1	HEAD LAMP UPPER BRACKET RH	SERVICEABLE	30.00	-
1	FRONT FOG LAMP	SERVICEABLE	280.00	-
1	FRONT FOG GARNISH LH	SERVICEABLE	40.00	-
	LESS 20% DISCOUNT		-	-522.00
			3,370.00	2,088.00
	<u>LABOUR</u>			
	SPRAY PAINTING FRONT BUMPER .		400.00	200.00
	REMOVE ,REPLACE AND REFIT ACCIDENT AFFECTED AREAS.		400.00	200.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			830.00	430.00
GRAND TOTAL			4,200.00	2,518.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC6/CTI19021029/Qda3n2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 2568Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

