

ASS. REC. BY: Sun Pm

REF:

NTA C NSI INC 10071030 / Qsf302

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SLQ 8215M

Policy No. 5093444793 02 (30/12/2019 - 29/02/2020)

Claims No. MT/107-2389-002


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 4063 G Yr Regn: 30/04/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 617914 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKN36420569124

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brakes: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 23/11/2019 D.O.I. 26/11/2019

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHC 4063G - NSI INC 10071030 / Qsf302 Pub - 30/04/2013 TP

SLQ 8215M - X

TAX/11/19/2121

RECEIVED 16 DEC 2019

SLQ 8215M

(\$ 5,530.40 Red - 64%)

(Confirm with Poh Suan)

Finalize \$3100 @ 5 days, (L/S)

16/12/2019

Date/Time, File Pass to?

16/12/19

1) Typ4

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: 160

Transportation: \$ + RS \$

Photos

Others

TOTAL

160

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Pop. Form:

Lump Sum / L.B.I.: \$ 3,100 / - 451

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No. (For Motor)  Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5093444793-02		PHOON OI LIN	S7033220E	GPC	drive CLASSIC	SLQ8215M	SLQ8215M	30/07/2019	29/07/2020

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	369K
<b>Vehicle Details</b>	
Vehicle No.:	SHC4063G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5936879
Chassis No.:	JTDKN36U205699124
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	30 Oct 2013
First Registration Date:	30 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2021
PARF Rebate Amount:	\$5,439.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$14,754.00
<b>Total Rebate Amount:</b>	<b>\$20,193.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Nov 2019

OK

**TP Claims against NTUC Income: Follow-Through Survey**

Date : 16/12/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	<b>MT/1073790-002</b>	COMFORT TRANSPORTATION PTE LTD	SHA 4585C	SMC 9871Z	02/12/2019	09:00	\$ 2,588.94	\$ 1,326.76
2	<b>MT/1072889-002</b>	SMRT TAXIS PTE LTD	SHC 4063G	SLQ 8215M	23/11/2019	18:25	\$ 8,650.40	\$ 3,100.00

## Shirley Hiew (LKK Auto)

---

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>  
**Sent:** Saturday, 14 December 2019 9:19 am  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SHC4063G

Hi,

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

**From:** Oi Sun Pin (LKK Auto) [mailto:sunpin@lkkauto.com]  
**Sent:** Friday, 13 December 2019 5:49 PM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
**Subject:** RE: SHC4063G

Dear Poh Suan,

Confirm the finalize amount \$3,100. Repair day 5 days under lump sum repair.

Thank you.

Best Regards,  
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25  
| S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Tuesday, 10 December, 2019 11:22 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** SUR; CS A Team; LEE SHENG AUTO PTE LTD  
**Subject:** SHC4063G

Hi Sun Pin,

Attached herewith the repair estimate of SHC 4063G having Case No: TAX/11/19/2121.

There is no change to the approved amount of \$3,100 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Sent: Monday, 9 December 2019 2:35 PM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: Scan Data from FX-D421D6

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/11/2019 12:55
Date Of Accident	23/11/2019 18:25
Exact Location Of Accident	CTE TOWARDS CITY BEFORE BRADDELL RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC4063G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	ABDUL HALIM BIN YUNOS
NRIC No	S7441316A
Date Of Birth	08/12/1974
Occupation	OUTDOOR
Date Of Driving Pass	30/03/1996
Driving Experience	23 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20191123/2158 ON THE 23/11/19 AT ABOUT 1825HRS, I WAS DRIVING MY SMRT TAXI BEARING SHC4063G ALONG CTE TOWARDS CITY, JUST BEFORE BRADDELL ROAD EXIT ALONE LANE 1 WITH ONE FEMALE PASSENGER SEATED AT THE REAR PASSENGER SEAT. MY PASSENGER WAS ALSO WEARING SEAT BELT AT THAT POINT OF TIME. AT THAT POINT OF TIME, IT WAS HEAVY TRAFFIC, IT WAS DRIZZLING AND THE ROAD WAS WET. AS THE FRONT CARS HAD SLOWED DOWN, I ALSO SLOWED DOWN. EVENTUALLY, ALL THE CARS IN FRONT SLOWED DOWN TO A STOP. AS SUCH, I HAD ALSO SLOWED DOWN MY TAXI GRADUALLY AND STOPPED TO WAIT. AFTER A FEW SECONDS, I FELT AN IMPACT FROM MY TAXI'S REAR. I THEN CHECKED AND REALISED THAT THERE IS A CAR THAT COLLIDED INTO MY TAXI'S REAR. IT IS ONE GREY VOLKSWAGEN CAR BEARING SLQ8215M. AT THAT POINT OF TIME, THERE WAS NO ONE INJURED AS SUCH WE EXCHANGED PARTICULARS AND CONTINUED ON OUR WAY. MY TAXI'S REAR PORTION AND UNDERCARRIAGE WAS DENTED WHEREAS THE GREY VOLKSWAGEN CAR BEARING SLQ8215M HAD A DENT AT THE FRONT PORTION. HOWEVER, LATER ON THE SAME DAY, I THEN WENT TO MOUNT ALVERNIA HOSPITAL TO MSEEK MEDICAL ATTENTION AS I FELT PAIN AT MY NECK AND LOWER BACK. I WAS THEN GIVEN 4 DAYS MC FOR 23/11/2019 TILL 26/11/2019. MY PASSENGER ALSO HAD INFORMED ME THAT SHE WILL BE GOING SEEK MEDICAL ATTENTION AND ALSO LODGE TRAFFIC ACCIDENT REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ8215M
Vehicle Make/Model/Colour	



Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	NICHOLAS YAP JO VAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	ABDUL HALIM BIN YUNOS
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHC4063G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 25/11/2019

Reporting Centre Personnel's Signature  
Name: A  
NRIC/FIN No.: 25/11/19



**SINGAPORE  
POLICE FORCE**



T/20191123/2158

1 of 4

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20191123/2158

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/11/2019 22:49		Vide Report No.:		Station Diary No.: 127	
<b>Informant's Particulars</b>					
Name of Informant: ABDUL HALIM BIN YUNOS			Address: APT BLK 604B TAMPINES AVENUE 9 #06-876 SINGAPORE 522604		
ID Type / ID No.: NRIC NO / S7441316A			Contact No.: Home/Office: Mobile: 98789438		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 44	Date of Birth: 08/12/1974	Type of Informant: Driver		
Race: Malay		Language: English	Institution / School Name:		
Occupation: Taxi driver		Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:	

## General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/11/2019 18:25	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY  heading towards city, before Braddell road exit				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: MOVING VEHICLE AGAINST STATIONARY VEHICLE			Anyone conveyed by ambulance: No	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHC4063G	TAXI				Slightly Damaged	1
SLQ8215M	Car				Slightly Damaged	1

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20191123/2158

2 of 4

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

Report No. T/20191123/2158

## CONTINUATION OF REPORT

<b>Passenger</b>			
Name	CANDICE CHOONG	ID No.	S8515373J
Related Vehicle	SHC4063G (TAXI)	Contact No.	93660792
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	ABDUL HALIM BIN YUNOS	ID No.	S7441316A
Related Vehicle	SHC4063G (TAXI)	Contact No.	98789438
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	23/11/2019	Date Discharge	23/11/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight
<b>Driver</b>			
Name	NICHOLAS YAP JO VAN	ID No.	S9833656G
Related Vehicle	SLQ8215M (Car)	Contact No.	84440923
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 23/11/2019 at about 1825hrs, I was driving my SMRT taxi bearing SHC4063G along CTE towards city, just before Braddel Road exit alone lane 1 with one female passenger seated at the rear passenger seat. My passenger was also wearing seatbelt at that point of time. At that point of time, it was heavy traffic, it was drizzling and the road was wet. As the front cars had slowed down, I also slowed down. Eventually, all the cars in front slowed down to a stop. As such, I had also slowed down my taxi gradually and stopped to wait. After a few seconds, I felt an impact from my taxi's rear. I then checked and realised that there is a car that collided into my taxi's rear. It is one grey Volkswagen car bearing SLQ8215M. At that point of time, there was no one injured as such we exchanged particulars and continued on our way. My taxi's rear portion and undercarriage was dented whereas the grey Volkswagen car bearing SLQ8215M had a dent at the front portion.



**SINGAPORE  
POLICE FORCE**



T/20191123/2158

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

3 of 4

Report No. T/20191123/2158

CONTINUATION OF REPORT

However, later on the same day, I then went to Mount Alvernia Hospital to seek medical attention as I felt pain at my neck and lower back. I was then given 4 days MC for 23/11/2019 till 26/11/2019. My passenger also had informed me that she will be going to seek medical attention and also lodge traffic accident report.



**SINGAPORE  
POLICE FORCE**



T/20191123/2158

4 of 4

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20191123/2158

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 MUHAMMAD DANIYAL BIN  
BAHARUDDIN

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
23/11/2019 22:49

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK  
Contact No.: 65478436

Classification Of Case:

Authentication Stamp  
NP188

SIGNATURE



## Case Details

Case Reference Number :

TAX/11/19/2121

Type of Repair : Accident Repair

Vehicle Registration Number :

SHC4063G

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9476-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 23/11/2019 10:25 AM

Vehicle Age(In Months) : 73

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0.00	Not Give	• X Svc
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace	✓ DD
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	• / NEC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace	✓ NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0.00	Check	• X Svc
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check	• X Svc
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check	• X Svc
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0.00	Check	• X Svc
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace	• / SHOF

Total Spare Part Cost 4,333.83

Surveyor Total 1,359.98

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,467.06

Final Sur Total 1,087.98



SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0.00	Not Give	*X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0.00	Not Give	*X SVC
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0.00	Not Give	*X SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0.00	Not Give	*X SVC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace	* / MIS
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace	* / CRA
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace	* / MIS
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	1	385.8	Replace	* / CRU
One Time Key In	Main			UNDER COVER RR SHIELD	1	83.90	83.90	25.00	47.92	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	*X SVC
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Check	*X SVC
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Check	*X SVC
Total Spare Part Cost									4,333.83	Surveyor Total		1,359.98		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,467.06	Final Sur Total		1,067.98		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	200	/
Total:			507.00	200.00	

1052

600

10069.62

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	375.00	200	✓
2	Main	TO RESPRAY BUMPER BEAM	160.00	0	
3	Main	TO RESPRAY REAR PANEL	180.00	0	
4	Main	TO RESPRAY REAR SPOILER	180.00	0	
Total:			<del>915.00</del> 1438	<del>200.00</del> 450	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	✓ Nec
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ NPC
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ Nec.
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	✓ Nec
Total:			656.88	356.88	

## Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,467.06	1,087.98
Total Labour Cost	507.00	200.00
Total Spray Painting	915.00	200.00
Other	656.88	356.88
Overall Total	5,542.94	1,844.86
Lump Sum Repair Option		✓
Lump Sum Total	5,550.00	1,850.00
Surveyor Approved Amount		1,850.00
No of Repair Days*	5	3

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

Lump Sum Repair, Take after spray photo.

Surveyor Name

Sun Pin (LKK)

Signature

  
3/12/19

Save

Clear

Survey Date

26/11/2019

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Date:

## Section A - Accident Details

Registration Number	SHC4063G
Case Reference Number	TAX/11/19/2121
Registration Date	30/10/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ABDUL HALIM BIN YUNOS
Type of Accident	Head to Rear
Accident Date and Time	23/11/2019 6:25 PM
Accident Reported Date and Time	25/11/2019 1:21 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104534
Special instruction to ARC, if any	TP -SLQ8215M FRONT PORTION DAMAGED TAX-SHC4063G REAR PORTION DAMAGED
Prepared Date and Time	25/11/2019 6:14 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,057.00	\$600.00
Total Spray Cost	\$1,476.00	\$450.00
Total Spare Part Cost	\$5,458.52	\$2,484.69
Total Other Cost	\$656.88	(\$434.69)
TOTAL COST	\$8,650.40	\$3,100.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	29/11/2019 3:09 PM	29/11/2019 1:57 PM
Signature		
Remarks	Initial estimate = 5 days SUP = 2 days	Lump Sum Repair, Take after spray photo.

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0114	Invoice Number	
Quotation Date	09.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
TO REMOVE AND REFIT REAR END PANEL	\$350.00	\$300.00
TO REPAIR REAR SPARE TYRE PANEL	\$200.00	\$100.00
Total Labour	\$1,057.00	\$600.00

Supp  
Supp

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$90.00
TO RESPRAY BUMPER BEAM	\$180.00	\$60.00
TO RESPRAY REAR SPARE TYRE PANEL	\$200.00	\$100.00
Total Spray Painting & Panel Beating	\$1,478.00	\$450.00

Supp  
Supp  
Supp

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIT REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$791.57)
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Total Other Costs	\$656.88	(\$434.69)

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given X
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
85 Woodlands Industrial Park EA, Singapore 737705
FAX Number: 63885102
Estimate Telephone Number: 67862023
Accident Reporting Number: 68862672

Date Generated: 09/12/2019

User ID: PchBuat

89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check	X
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	
52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X
52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace	
76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace	
76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	
58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace	
51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X
81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Check	X
81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Check	X
<b>Total</b>			<b>\$5,346.80</b>		<b>\$1,359.99</b>			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	10.00	\$141.66	Replace	Replace
		84778-47050	PROTECTOR, SPARE	1.00	\$143.70	25.00	\$107.78	Replace	Replace
			SPARE TYPE INSULATOR SHEET	4.00	\$15.00	0.00	\$60.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52018-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace
<b>Total</b>					<b>1,403.10</b>		<b>1,124.70</b>		

CRA  
 CRU  
 NEC  
 BT  
 BT  
 BT  
 DP

} Supp

2484.69  
 + 600.00  
 + 806.88

3891.57  
 - 20%

3113.26

45 \$3100/-

SHC 4067

5 days

# REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX 11/19 0121	Date of Collection	1 1
Vehicle No	SHC 4063 G	Date of Request	27/11/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	42

S/N	Part Number	Part Description	Quantity	Unit Price	
		LABOR TO UNL & REPLACE REAR END PANEL		\$ 350	300
		LABOR TO SPRAY REAR END PANEL		\$ 180	90
		LABOR TO SPRAY REAR <del>END</del> BUMPER BEAM		\$ 180	60
		LABOR TO REPAIR SPARE TYRE PANEL		\$ 200	100
		LABOR TO SPRAY SPARE TYRE PANEL		\$ 200	100
		SPARE TYRE INSULATING COAT	4pts	/ Nec	

<<<Please submit photographs for damaged parts>>>

I, (Name) \_\_\_\_\_

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....  
Signature of person making this declaration  
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

990/2

# **REQUEST FOR SUPPLYMENT PARTS**

Contractor:			
Accident Case Number	TAX/11/19/2121	Date of Collection	1 / 1
Vehicle No	SHC 4063 G	Date of Request	27/11/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	4 2

S/N	Part Number	Part Description	Quantity	Unit Price
		Bumper REINFORCEMENT REAR	1pc	/ BT
		ARM SUB ASSY, REAR Bumper LH	1pc	/ BT
		ARM SUB ASSY, REAR Bumper RH	1pc	/ BT
		ANTENA ELECTRICAL LOWER REAR	1pc	/ CRA
		END PANEL	1pc	/ DO
		SPARE TYRE FOAM	1pc	/ CR4

<<<Please submit photographs for damaged parts>>>

I, (Name) \_\_\_\_\_  
 (Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....  
 Signature of person making this declaration  
 [to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMKT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

99 1/2



**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983358E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19021030/Qsf3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 02-01-2020	
			Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLQ 8215M	Veh. Inspected	SHC 4063G	
Policy No.	5093444793-02	Coverage (\$)	0.00	
Claim No.	MT/1072889-002	Excess (\$)	0.00	
Assign From		Assign Date	26/11/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTDKN36U205699124	Colour	MAROON	
Odometer	617914	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/11/2019	Inspection Date	26/11/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4063G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
1	BUMPER LIP COVER RR/LH (DISC 25%)	MISSING	72.20	54.15
1	BUMPER LIP COVER RR/RH (DISC 25%)	CRACKED	118.10	88.58
1	BUMPER LIP REAR (DISC 25%)	MISSING	228.90	171.68
1	UNDER COVER SUB-ASSY, RR FLOOR (DISC 25%)	CRUSHED	514.50	385.88
1	PROTECTOR, SPARE (DISC 25%)	CRUSHED	143.70	107.78
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	END PANEL (DISC 25%)	DENTED	602.10	451.58
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	CRACKED	157.40	141.66
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
4	SPARE TYPE INSULATOR SHEET @\$15.00 (SN)	NECESSARY	60.00	60.00
1	SPOILER REAR	SERVICEABLE	953.70	-
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER SEAL, RR LH	SERVICEABLE	88.90	-
1	BUMPER SEAL, RR RH	SERVICEABLE	65.70	-
1	UNDER COVER RR SHIELD	SERVICEABLE	63.90	-
1	END PANEL	SERVICEABLE	602.10	-
1	TAIL LAMP RH	SERVICEABLE	557.80	-
1	TAIL LAMP LH	SERVICEABLE	548.40	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
			7,170.68	2,781.57

Report Ref No. NS/INC19021030/Qsf3e2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING & BODY WORK.		1,057.00	600.00
	SPRAY PAINT.		1,478.00	450.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,895.00	1,110.00
	<b>GRAND TOTAL</b>		<b>10,065.68</b>	<b>3,891.57</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>3,100.00</b>

Report Ref No. NS/INC19021030/Qsf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.