

ASS. REC. BY: Sun Pm

REF:

NTUC. NS/ INC 1901031/2 yf352

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SML 1171RPolicy No. 5109 179594 (06/05/2019 - 05/05/2020)Claims No. MT/1072520-002


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB457K Yr Regn: 20/JAN/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 708664 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTPKN384105755943

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: 1.8 / S/Rlm / STD A/Rlm orTyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Newton

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 20/11/2019 D.O.I. 22/11/2019Survey held at SMRTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 457K - NS/INC 1701751/ R1422 201 - 11/09/2017 TP.
	SML 1171R - <u>TAX/11/19/2090</u>
	<u>SML 1171R.</u>
	RECEIVED 08 JAN 2020
	(confirm with Poh Suan)
	Finalize \$ 2,550 @ 4 days (L/S) (Red \$12997-93, 83%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 3/1/20 Typist

Rep. Format:

Lump Sum: \$2550Days Of Repair: 4Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

TP Claims against NTUC Income: Follow-Through Survey

Date : 03/01/2020

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/1072520-002	SMRT	SHB457K	SML1171R	20/11/2019
2	MT/1070598-003	SMRT	SHB1237Y	SLA3155U	08/11/2019

Claim received from LKK Auto

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="20/11/2019 08:41"/>							
Vehicle No.(For Motor)	<input type="text" value="SML1171R"/>	Certificate Number	<input type="text"/>							
<input type="button" value="Search"/>										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5109179594		CHUA SOON HENG	59222892D	GPC	drive CLASSIC	SML1171R	SML1171R	06/05/2019	05/05/2020
<input type="button" value="Continue"/>										

## Oi Sun Pin (LKK Auto)

---

**From:** Oi Sun Pin (LKK Auto)  
**Sent:** Thursday, 2 January, 2020 6:00 PM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
**Cc:** Yvonne Wong (LKK Auto)  
**Subject:** RE: SHB457K

Dear Poh Suan,

Confirm the finalize amount \$2,550. Repair day 4 days under lump sum repair.

Thank you.

Best Regards,  
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]  
Sent: Thursday, 26 December, 2019 2:53 PM  
To: Oi Sun Pin (LKK Auto)  
Cc: SUR; CS A Team  
Subject: SHB457K

Hi Sun Pin,

Attached herewith the repair estimate of SHB 457K having Case No: TAX/11/19/2090.

There is no change to the approved amount of \$2,550 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
Sent: Thursday, 26 December 2019 2:50 PM  
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
Subject: Scan Data from FX-D421D6

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	22/11/2019 11:53
Date Of Accident	20/11/2019 22:05
Exact Location Of Accident	KIM SENG ROAD / HAVELOCK ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB457K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

#### Driver

Name of Driver	ASURAPPULEGE WILFRED NEVILLE DHARMASENA
NRIC No	S7928200F
Date Of Birth	25/08/1979
Occupation	OUTDOOR
Date Of Driving Pass	18/06/2000
Driving Experience	19 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH WEST NPC
Police Station Address	ROAD: 500 BUKIT MERAH VIEW #01-01 , POSTCODE: 159682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20191121/2016

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SML1171R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SABRINA ANG XI PING
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver) \*

**DETAILS OF INJURED PERSON 1**

Name	ASURAPPULEGE WILFRED NEVILLE DHARMASENA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB457K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1




*Handwritten signature*

21/11/19

Kin Sang Rd

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20191121/2016

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

1 of 3

\* Report No. T/20191121/2016

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/11/2019 01:47	Vide Report No.:	Station Diary No.: 11
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: ASURAPPULEGE WILFRED NEVILLE DHARMA SENA	Address: APT BLK 14A TELOK BLANGAH CRESCENT #05-302 SINGAPORE 091014		
ID Type / ID No.: NRIC NO / S7928200F	Contact No.: Home/Office:                      Mobile: 91822442		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 40	Date of Birth: 25/08/1979	Type of Informant: Driver
Race: Sinhalese	Language:		Institution / School Name:
Occupation: Taxi driver	Driving Licence Information: Class: 3                      Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 20/11/2019 22:05	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 KIM SENG ROAD HAVELOCK ROAD Turning from Kim Seng road towards Havelock road at lane 1 and lane 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No	Type	Make	Model	Color	Condition	No. of Passenger
SHB457K	Car				Seriously Damaged	0
SML1171R	Car				Slightly Damaged	2

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20191121/2016

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

2 of 3

Report No. T/20191121/2016

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	ASURAPPULEGE WILFRED NEVILLE DHARMASENA		ID No. S7928200F
Related Vehicle	SHB457K (Car)		Contact No. 91822442
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
<b>Driver</b>			
Name	SABRINA		ID No. NIL
Related Vehicle	SML1171R (Car)		Contact No. 97489765
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 20/11/2019 at about 2205hrs, I driving along looking for passengers. While travelling along Kim Seng Road turning towards Havelock road, I felt a bang on the left side of my vehicle. I then noticed that a vehicle SML1171R had hit onto my left side of my vehicle. We then stop and alighted our vehicle. I then took picture of her vehicle and exchange contact number and we subsequently left the location. I wish to state at that point of the accident I felt an impact however I did not feel much pain. However when I reach home I felt a sharp pain on the left side of my back. I am making this report for insurance claim for my company reference.



**SINGAPORE  
POLICE FORCE**



T/20191121/2018

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

3 of 3

Report No. T/20191121/2018

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 WEE WEI XIONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant:

Date/Time:


21/11/2019 01:47

Classification Of Case:

SN 45

Authentication Stamp

NP158



> Back to OneMotoring


## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB457K
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1485602
Chassis No.:	JTDKN36U105755943
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	20 Jan 2015
First Registration Date:	20 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2023
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,486.00
COE Rebate Amount:	\$20,669.00
Total Rebate Amount:	\$26,735.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Nov 2019

OK

Accident Photo



Accident Photo





# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
40 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/11/2019



User ID : TuckFoo

## Section A - Accident Details

Registration Number	SHB457K
Case Reference Number	TAX/11/19/2090
Registration Date	1/20/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ASURAPPULEGE WILFRED NEVILLE DHARMASENA
Type of Accident	Side Swipe
Accident Date and Time	11/20/2019 10:05 PM
Accident Reported Date and Time	11/21/2019 12:54 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104461
Special Instruction to ARC, if any	TP/ TOWED \$40
Prepared Date and Time	11/21/2019 2:52 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	


## Section B - Summary of Repair Estimates

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$2,790.00	\$850.00
Total Spare Part Cost	\$10,510.97	\$1,120.35
Total Other Cost	\$895.00	\$140.00
<b>TOTAL COST</b>	<b>\$15,041.97</b>	<b>\$2,610.35</b>
Lump Sum Total	\$0.00	\$2,600.00
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	25/11/2019 11:40 AM	22/11/2019 5:04 PM
Signature		
Remarks		Lump Sum repair, Take after spray photo.

Repair day - 4 days.

L/s Repair  
After spray photo.

  
29/11/19

## Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 62662672

Date Generated : 26/11/2019

User ID : TuckFoo

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LABOUR	\$845.00	\$500.00 ✓
<b>Total Labour</b>	<b>\$845.00</b>	<b>\$500.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT & REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY RIM	\$360.00	\$50.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$2,790.00</b>	<b>\$850.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$40.00 ✓
TO TEST AND REFIT SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$80.00	\$0.00
<b>Total Other Costs</b>	<b>\$896.00</b>	<b>\$140.00</b>

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
	✓	52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair X B
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given X SVC
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check X SVC
		52115-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X SVC
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given X SVC
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given X SVC
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X SVC
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X SVC
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given X SVC
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X SVC
		51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given X SVC
		51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X SVC
		51443-12080	UNDER COVER SIDE/RH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X SVC

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/11/2019

User ID : TuckFoo

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53301-47080	HOOD PANEL	0.00	\$748.10	0.00	\$0.00	Replace	Not Given X SVC
		53420-47070	HOOD HINGE LH	1.00	\$55.90	100.00	\$0.00	Replace	Old Damage X SVC
		53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given X SVC
		55084-47011	WIPER GARNISH COVER, LH	1.00	\$23.80	100.00	\$0.00	Replace	Old Damage X SVC
		55083-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given X SVC
		67002-47070	DOOR FRT/LH	1.00	\$894.40	25.00	\$670.80	Replace	Replace / bp 25%
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace / NEC 0%
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given X SVC
	LN	81740-52040	MIRROR LAMP LH	1.00	\$65.30	10.00	\$58.77	Replace	Replace / R 10%
		87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair X R
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace / bp 25%
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	Replace / NEC 25%
		53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X SVC
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given X SVC
		53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	100.00	\$0.00	Replace	Old Damage X SVC
		53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given X SVC
		53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given X SVC
	LN	42611-47140	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair X R
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X SVC
		75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given X SVC
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given X SVC
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X SVC
		67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair X SVC
	LN	61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair X R
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace / NEC 0%
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace / NEC 0%
		42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given X SVC
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X SVC
		42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given X SVC
		52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given X SVC
		90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given X SVC
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X SVC
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given X SVC
		52016-47030	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X SVC
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X SVC
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given X SVC
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X SVC
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X SVC
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X SVC
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X SVC

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/11/2019

User ID : TuckFoo

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given X SVC
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X SVC
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given X SVC
		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given X SVC
Total					\$17,035.29		\$1,400.44		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

22007.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/11/19/2090	Date of Collection	/ /
Vehicle No	SHB 457 K	Date of Request	26/11/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	X 0

S/N	Part Number	Part Description	Quantity	Unit Price
		FRONT DOOR HINGE LH (UPPER) 1pc	1	BT
		FRONT DOOR HINGE LH (LOWER) 1pc	1	BT
	LABOR	TO SPRAY REAR FENDER LH		\$ 378

200

<<<Please submit photographs for damaged parts>>>

I, (Name) \_\_\_\_\_  
 (Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....  
 Signature of person making this declaration  
 [to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission


Section A - Accident Details

Registration Number	SHB457K
Case Reference Number	TAX/11/19/2090
Registration Date	20/1/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ASURAPPULEGE WILFRED NEVILLE DHARMASENA
Type of Accident	Side Swipe
Accident Date and Time	20/11/2019 10:05 PM
Accident Reported Date and Time	21/11/2019 12:54 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104461
Special Instruction to ARC, if any	TP/ TOWED \$40
Prepared Date and Time	21/11/2019 2:52 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

L/S = 2550

4 days

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$3,168.00	\$1,050.00
Total Spare Part Cost	\$13,266.66	\$1,528.41
Total Other Cost	\$896.00	(\$528.41)
<b>TOTAL COST</b>	<b>\$18,175.66</b>	<b>\$2,550.00 (L/S)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	29/11/2019 3:13 PM	29/11/2019 2:50 PM
Signature		
Remarks	Initial estimate = 8 days SUP = 0 day	Lump Sum repair, Take after spray photo.



Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0296	Invoice Number	
Quotation Date	20.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LABOUR	\$845.00	\$500.00
<b>Total Labour</b>	<b>\$845.00</b>	<b>\$500.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT & REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY RIM	\$360.00	\$50.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$3,168.00</b>	<b>\$1,050.00</b>

supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$668.41)
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$40.00
TO TEST AND REFIT SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$896.00</b>	<b>(\$528.41)</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number : 63665592  
Estimator Telephone Number : 80002623  
Accident Reporting Number : 66062672

Date Generated : 26/12/2019  
User ID : Poh Guan

52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X
52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X
52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X
57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X
51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
51443-12080	UNDER COVER SIDE/RH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
53301-47060	HOOD PANEL	0.00	\$748.10	0.00	\$0.00	Replace	Not Given	X
53420-47070	HOOD HINRE LH	1.00	\$55.90	100.00	\$0.00	Replace	Old Damage	X
53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X
55084-47011	WIPER GARNISH COVER,LH	1.00	\$23.80	100.00	\$0.00	Replace	Old Damage	X
55083-47011	WIPER GARNISH COVER,RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
67002-47070	DOOR FRT/LH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	X
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	X
87940-47310	MIRROR ASSY,LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given	X
81740-52040	MIRROR LAMP LH	1.00	\$65.30	10.00	\$58.77	Replace	Replace	X
87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair	R
53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given	X
53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	100.00	\$0.00	Replace	Old Damage	X
53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given	X
42611-47140	WHEEL DISC, FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X
43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R
61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
	STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X
52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given	X

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number : 63666692  
Estimate Telephone Number : 68662623  
Accident Reporting Number : 68662672

Date Generated : 26/12/2019  
User ID : PehSuan

90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given	X
52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given	X
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
76086-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X
58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>			<b>\$17,035.29</b>		<b>\$1,400.45</b>			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		68720-15151	HINGE UPPER LHF, DOOR	1.00	\$80.50	25.00	\$60.38	Replace	Replace
		68740-12120	HINGE LOWER LHF, DOOR	1.00	\$90.10	25.00	\$67.58	Replace	Replace
<b>Total</b>					<b>170.60</b>		<b>127.96</b>		

supp  
supp

1528.41/-  
+ 500.00/-  
+ 1190.00/-

3218.41

- 207

2574.73/-

4/5 \$2550/-





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19021031/Qyf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 17-01-2020

189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SML 1171R	Veh. Inspected	SHB 457K
Policy No.	5109179594	Coverage (\$)	0.00
Claim No.	MT/1072520-002	Excess (\$)	0.00
Assign From		Assign Date	22/11/2019

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDKN36U105755943	Colour	MAROON
Odometer	708664	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEUTON	5 mm
L/H Front Tyre	195/65 R15	NEUTON	5 mm
R/H Rear Tyre	195/65 R15	NEUTON	5 mm
L/H Rear Tyre	195/65 R15	NEUTON	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	20/11/2019	Inspection Date	22/11/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 457K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	DOOR FRT/LH (DISC 25%)	DENTED	894.40	670.80
1	FENDER FRT/LH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.91
1	HINGE UPPER LHF, DOOR (DISC 25%)	BENT	80.50	60.38
1	HINGE LOWER LHF, DOOR (DISC 25%)	BENT	90.10	67.58
1	MIRROR LAMP LH (DISC 10%)	SCRATCHED	65.30	58.77
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER CLIPS	SERVICEABLE	1.61	-
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	BUMPER LIP FRT	SERVICEABLE	139.60	-
1	UNDER COVER CENTER	SERVICEABLE	448.30	-
1	UNDER COVER SIDE/LH	SERVICEABLE	46.10	-
1	UNDER COVER SIDE/RH	SERVICEABLE	46.10	-
1	HOOD PANEL	SERVICEABLE	748.10	-
1	HOOD HINGE LH	SERVICEABLE	55.90	-
1	HOOD HINGE RH	SERVICEABLE	55.90	-
1	WIPER GARNISH COVER, LH	SERVICEABLE	23.80	-
1	WIPER GARNISH COVER, RH	SERVICEABLE	23.80	-
1	MIRROR ASSY, LH	SERVICEABLE	1,224.90	-
1	FENDER PROTECTOR FRT/LH UPPER	SERVICEABLE	46.10	-
1	PROTECTOR, FRONT FENDER SIDE PANEL LH	SERVICEABLE	114.50	-
1	FENDER LINER FRT/LH	SERVICEABLE	171.70	-

Report Ref No. NS/INC19021031/Qyf3s2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER LINER PAD, FR WHEEL, LH	SERVICEABLE	49.30	-
1	FENDER APRON SUB FRT/LH	SERVICEABLE	637.80	-
1	TYRE	SERVICEABLE	126.74	-
1	MOULDING BODY, LH	SERVICEABLE	673.60	-
1	WHEEL HUB FRT	SERVICEABLE	549.70	-
1	PIXEL STICKER	SERVICEABLE	60.00	-
1	DOOR RR/LH	SERVICEABLE	954.50	-
1	WHEEL DISC	SERVICEABLE	1,484.20	-
1	TYRE	SERVICEABLE	126.74	-
1	WHEEL HUB REAR	SERVICEABLE	489.40	-
1	BUMPER REAR	SERVICEABLE	458.60	-
1	BUMPER CLIPS	SERVICEABLE	2.10	-
1	PIXEL STICKER	SERVICEABLE	60.00	-
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	UNDER COVER SUB-ASSY, RR FLOOR	SERVICEABLE	514.50	-
1	UNDER COVER RR SHIELD	SERVICEABLE	63.90	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
1	WHEEL DISC, FRONT	TO REPAIR SEE LABOUR	1,484.20	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
			17,098.49	1,528.39

Report Ref No. NS/INC19021031/Qyf3s2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT; WHEEL DISC, FRONT AND FENDER RR/LH.		845.00	500.00
	SPRAY PAINT.		3,168.00	1,050.00
	TOWING CHARGE.		56.00	-
	TO TRANSFER DOOR MECHANISM.		120.00	60.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	40.00
	TO TEST AND REFIT SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			4,909.00	1,690.00
	<b>GRAND TOTAL</b>		<b>22,007.49</b>	<b>3,218.39</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>2,550.00</b>

Report Ref No. NS/INC19021031/Qyf3s2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.