

ASS. REC. BY:

REF: (S/FC119021036/ Rmf352

Special Instruction:

Surveyor

Rasu I

ASSIGNMENT (Office)

From (Person): Radul Wu Li Mu

of FCI

Date/Time: 27.11.19 5.13p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 6747P

Insured:

SHC 8298U

at Workshop m/s

Sin shung

Tel:

68639595

at NO 8 Tuas Ave 18 (Level 3)

Policy No:

Claim No: D19004762 MPST

Sum Insured:

Excess:

Make of Veh:

D.O.A. 19.1.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 28.11.19 9.50a.m

Person Contacted:

Pai Jin

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBE 6747P - X
	SHC 8298U - (S/FC119014335/ Dmf3n2
	ROA - 21/03/2019

ASS. REC. BY:

Pam

REF: FC1

196N

ASSIGNMENT

From: _____ Date: 28.11.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBE 6747P

at Workshop m/s Sin sheng

of NO 8 TUNAS AVE 18 (Level 3)

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 51K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'my'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBE 6747P Yr Regn: 2016 / PER

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA HIACE DX 3.0 LA c.c. 2982

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 233462 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH 2010181662

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NIP / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ASTONIC

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/07/19 D.O.I. 28/11/19

Survey held at SIN SHENG

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/12/19 Sent Preli by email

13/1/20 finalized and \$10,000 / 10 days L/S (Red \$6961-80, 41%)

RECEIVED 14 JAN 2020

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Date/Time, File Return to?

13/1/20 Typist

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S. + FS. \$

Phone

Other

TOTAL

6x15=90

170+90

50

50

103

463

Report Formed:

Long \$10000

MOTOR SURVEY ASSIGNMENT

Date	22-07-2019	Our Ref No. D19004762MFSH
Accident Date	19-07-2019	Claim Type. Third Party
Insured Vehicle	SHC8298U	Third Party Vehicle. GBE6747P
Survey Location	NO 8 TUAS AVE 18 (LEVEL 3)	
Contact Person.	PEI JIN	
Contact No.	6863 9595/ 0	Fax No. 6863 6477
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	RACHELWU LIMEI	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, January 13, 2020 5:46 PM
To: sinsheng engineeringservices
Subject: RE: PRI REQUEST : FC REF: SHC8298U. (D19004762MFSH) & TP REF: GBE6747P. (SLG 8524Z/LT/JP/CA) ACCIDENT ON 19-07-2019

Hi Pei Jin

Kindly send final invoice and all supporting documents directly to MS FIRST CAPITAL Insurance.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineeringservices [mailto:sinsheng1981@gmail.com]

Sent: Friday, January 10, 2020 4:51 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: Re: PRI REQUEST : FC REF: SHC8298U. (D19004762MFSH) & TP REF: GBE6747P. (SLG 8524Z/LT/JP/CA) ACCIDENT ON 19-07-2019

Hi Mr. Rasul,

We are agreed your offer.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services

No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

On Fri, 10 Jan 2020 at 10:56, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Pei Jin,

Refer to attachment

Finalised amount is \$ 10,000 / 10 days of repair lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]

Sent: Thursday, 9 January, 2020 6:00 PM

To: Rasul (LKKAuto)

Subject: Re: PRI REQUEST : FC REF: SHC8298U. (D19004762MFSH) & TP REF: GBE6747P. (SLG 8524Z/LT/JP/CA)
ACCIDENT ON 19-07-2019

Hi Mr. Rasul,

Please be informed that we have email the after repair photos on dated 12/12/2019.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004762MFSH

Date: 03 Dec 2019

Our Ref: CS/FCI19021036/R1yf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE6747P.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/11/2019 at the premises of M/s SIN SHENG ENGINEERING SERVICES. and have the following to report:-

Workshop Estimate Amount	: S\$ 16,961.80 .
Revised Estimate Amount	: S\$ 10,892.50 .
"Check" Items Amount	: S\$ 3,016.85 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Yours faithfully

Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2019 22:18
Date Of Accident	19/07/2019 21:30
Exact Location Of Accident	ALONG LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE6747P
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29090793
Cover Note Number	

Driver

Name of Driver	VASU DEVAN RAJENDIRAN
NRIC No	S8662390J
Date Of Birth	21/10/1986
Occupation	OUTDOOR
Date Of Driving Pass	19/07/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91874040
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKG5355B
Vehicle Make/Model/Colour	CITROEN
Details Of Properties	VEH C
Vehicle Category	PRIVATE CAR
Name of Driver	FADZIL BIN ABDULLAH
NRIC/Passport Number	S1681343E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR PORTION
No. Of Passenger (Including Driver)	1

Sketch Plan #2

SKETCH PLAN

- (A) GBE 6747 P.
- (B) SHC 8298U
- (C) SKG 5355 B.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report filed on 20/07/2019 at 2.37 p.m.
 (Report No.: T/20190720/2015).

p.t. *[Signature]*
 08 Aug 19
 1800HRS.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20190720/2015

2 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20190720/2015

CONTINUATION OF REPORT

Driver			
Name	VASU DEVAN RAJENDIRAN	ID No.	S8662390J
Related Vehicle	GBE6747P (Van)	Contact No.	91874040
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	FADZIL BIN ABDULLAH	ID No.	S1681343E
Related Vehicle	SKG5355B (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/7/2019 at about 2130hrs, I was driving my van GBE6747P on the right lane. I then saw the car SKG5355B in front of me jammed brake and as such I too did the same and managed to stop in time. Suddenly a taxi collided onto my rear causing me to move forward and collide into the rear of SKG5355B. The taxi driver then told us to make a police report and he drove off. He did not give me or the other car his particulars and we too did not manage to take down the vehicle number. The taxi driver is a Chinese man in his 50s.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

GBE6747P

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2019

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE DX 3.0L AUTO

Primary Colour:

Silver

Manufacturing Year:

2015

Engine No.:

1KD2563592

Chassis No.:

KDH2010181662

Maximum Power Output:

-

Open Market Value:

\$30,206.00

Original Registration Date:

19 Feb 2016

First Registration Date:

19 Feb 2016

Transfer Count:

0

Actual ARF Paid:

\$1,511.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

18 Feb 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$4,539.00

COE Rebate Amount:

\$2,785.00

Total Rebate Amount:

\$2,785.00

The information contained herein is correct as at 25 Nov 2019

OK

51,000
2,785

48,215

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003009

Date : 26/11/2019
Vehicle Num. : GBE6747P
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : KDH2010181662/1KD2563592
Accident Date : 19/07/2019
Claim No. :
Reference : SHC8298U
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER <i>de</i>		677.50
2.	6	BUMPER CLIP <i>de</i>	5.00	30.00
3.	2	BUMPER SIDE BRACKET <i>bt</i>	123.50	247.00
4.	1	REAR DOOR <i>buc</i>		2,150.50
5.	1	REAR DOOR LOCK <i>jam</i>		275.10
6.	1	REAR DOOR GARNISH <i>X</i> <i>svc</i>		365.90
7.	1	REAR DOOR PARTITION <i>X</i> <i>svc</i>		295.45
8.	1	TOYOTA EMBLEM <i>de</i> <i>(svc)</i>		53.50
9.	<i>2 pc</i>	REAR LAMP RH-CA, LH-X <i>inconsistent NC</i>	365.90	731.80
10.	2	REAR LAMP GARNISH <i>X</i> <i>svc</i>	165.20	330.40
11.	1	REAR END PANEL <i>bt</i>		585.90
12.	1	REAR END PANEL INNER <i>bt</i>		572.10
13.	1	STEP PANEL <i>bt</i>		319.60
14.	1	SPARE TYRE BRACKET <i>bt</i>		268.50
15.	1	SPARE TYRE HOOK, BOLT ?		104.20
16.	1	EXHAUST BOX <i>X</i> <i>svc</i>		568.20
17.	1	REAR BODY WEATHERSTRIP <i>de</i>		312.10
18.	1	FRONT BUMPER <i>de</i>		577.40
19.	2	BUMPER SIDE BRACKET ?	123.50	247.00
20.	1	BUMPER GARNISH, CTR <i>de</i>		268.50
21.	6	BUMPER CLIP <i>de</i>	5.00	30.00
22.	1	FRONT GRILLE <i>sc</i>		695.21
23.	1	FRONT CROSSMEMBER ?		456.20

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

Estimate : ES003009

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Date : 26/11/2019
Vehicle Num. : GBE6747P
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : KDH2010181662/1KD2563592
Accident Date : 19/07/2019
Claim No. :
Reference : SHC8298U
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
24.	1	FRONT PANEL <i>bt</i> ✓		795.10
25.	1	TOYOTA LOGO <i>na</i> ✓		53.20
26.	2	BUMPER TOWING COVER <i>MIS</i> ✓	31.20	62.40
27.	2	HEADLAMP <i>cr</i> ✓	645.20	1,290.40
28.	1	PANEL LOCK <i>X</i>		246.20
29.	1	WASHER TANK <i>X</i>		195.20
30.	1	AIR-CON CONDENSER <i>bt</i> ✓		760.20
31.	1	RADIATOR ?		1,895.87
32.	1	RADIATOR COWLING ?		468.20
33.	2	RADIATOR FAN ?	425.50	851.00
34.	1	RADIATOR SUPPORT PANEL <i>bt</i> ✓		335.90
List Total S\$:				17,115.73
25.00% Discount S\$:				4,278.93
				12,836.80
NETT ITEMS :				
1.	2	NUMBER PLATE WITH CASING <i>cut</i> ✓	40.00	80.00 ✓
2.	1	SEALANT <i>na</i> ✓		40.00 ✓
3.	1	8 PAX STICKER <i>acc</i> ✓		20.00 ✓
4.	1	70km/h Sticker <i>na</i> ✓		20.00 ✓
5.	1	REVERSE SENSOR <i>na</i> ✓		250.00 <i>220</i>
6.	1	COOLANT <i>na</i> ✓		40.00
Nett Total S\$:				450.00
10.00% Discount S\$:				45.00
				405.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003009

Date : 26/11/2019
Vehicle Num. : GBE6747P
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : KDH2010181662/1KD2563592
Accident Date : 19/07/2019
Claim No. :
Reference : SHC8298U
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO DISMANTLE/REPLACE REAR WINDSCREEN		120.00
		TO DISMANTLE/REPLACE AIR-CON CONDENSER		150.00
		TO PANEL BEAT/REPAIR FR BODY		1,950.00
		TO PANEL BEAT/REPAIR REAR BODY		1200
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		TO SPRAY PAINTING		1,100.00
		TO APPLY NEW LOGO		800
		TO APPLY TUFF-KOTE		250.00
		LOSS OF USE : 14 DAYS @ S\$120/DAY		150.00
		Labour Total S\$:		3,720.00

Resul
Hp 900/10068
10 days
4s
28/11/19 @ 1600
Resury after
repair

Total S\$: 16,961.80

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003009

Date : 26/11/2019
Vehicle Num. : GBE6747P
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : KDH2010181662/1KD2563592
Accident Date : 19/07/2019
Claim No. :
Reference : SHC8298U
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER <i>de</i>		677.50
2.	6	BUMPER CLIP <i>ne</i>	5.00	30.00
3.	2	BUMPER SIDE BRACKET <i>bt</i>	123.50	247.00
4.	1	REAR DOOR <i>buc</i>		2,150.50
5.	1	REAR DOOR LOCK <i>thm</i>		275.10
6.	1	REAR DOOR GARNISH <i>Xsuc</i>		365.90 X
7.	1	REAR DOOR PARTITION <i>Xsuc</i>		295.45 X
8.	1	TOYOTA EMBLEM <i>ne</i>		53.50
9.	2 <i>1pc</i>	REAR LAMP <i>RH-cn, LH-X inconsistent ne</i>	365.90	731.80 X
10.	2	REAR LAMP GARNISH <i>Xsuc</i>	165.20	330.40 X
11.	1	REAR END PANEL <i>bt</i>		585.90
12.	1	REAR END PANEL INNER <i>bt</i>		572.10
13.	1	STEP PANEL <i>bt</i>		319.60
14.	1	SPARE TYRE BRACKET <i>bt</i>		268.50
15.	1	SPARE TYRE HOOK, BOLT <i>? Xsuc</i>		104.20 X
16.	1	EXHAUST BOX <i>Xsuc</i>		568.20 X
17.	1	REAR BODY WEATHERSTRIP <i>ne</i>		312.10
18.	1	FRONT BUMPER <i>de</i>		577.40
19.	2	BUMPER SIDE BRACKET <i>? Xsuc</i>	123.50	247.00 X
20.	1	BUMPER GARNISH, CTR <i>de</i>		268.50
21.	6	BUMPER CLIP <i>ne</i>	5.00	30.00
22.	1	FRONT GRILLE <i>suc</i>		695.21
23.	1	FRONT CROSSMEMBER <i>? Xsuc</i>		456.20 X

CONTINUE / ...

7428.81

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003009

Date : 26/11/2019
Vehicle Num. : GBE6747P
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : KDH2010181662/1KD2563592
Accident Date : 19/07/2019
Claim No. :
Reference : SHC8298U
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
				5439.27
24.	1	FRONT PANEL <i>bt</i>		795.10
25.	1	TOYOTA LOGO <i>na</i>		53.20
26.	2	BUMPER TOWING COVER MIS		62.40
27.	2	HEADLAMP <i>cm</i>	31.20	1,290.40
28.	1	PANEL LOCK <i>bt</i>	645.20	246.20
29.	1	WASHER TANK <i>X svc</i>		195.20 X
30.	1	AIR-CON CONDENSER <i>bt</i>		760.20
31.	1	RADIATOR <i>bt</i>		1,895.87
32.	1	RADIATOR COWLING <i>? X svc</i>		468.20 X
33.	2	RADIATOR FAN <i>? X svc</i>	425.50	851.00 X
34.	1	RADIATOR SUPPORT PANEL <i>bt</i>		335.90
List Total S\$:				17,115.73
25.00% Discount S\$:				4,278.93
				12,836.80
NETT ITEMS :				
1.	2	NUMBER PLATE WITH CASING <i>cut</i>	40.00	80.00
2.	1	SEALANT <i>na</i>		40.00
3.	1	8 PAX STICKER <i>na</i>		20.00
4.	1	70km/h Sticker <i>na</i>		20.00
5.	1	REVERSE SENSOR <i>na</i>		250.00
6.	1	COOLANT <i>na</i>		40.00
Nett Total S\$:				450.00
10.00% Discount S\$:				45.00
				405.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003009

Date : 26/11/2019
Vehicle Num. : GBE6747P
Make/Model : TOYOTA KDH 201-2015
Chassis/Eng# : KDH2010181662/1KD2563592
Accident Date : 19/07/2019
Claim No. :
Reference : SHC8298U
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

LABOUR :
TO DISMANTLE/REPLACE REAR WINDSCREEN
,
TO DISMANTLE/REPLACE AIR-CON CONDENSER
,
TO PANEL BEAT/REPAIR FR BODY
TO PANEL BEAT/REPAIR REAR BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS
,
TO SPRAY PAINTING
,
TO APPLY NEW LOGO
,
TO APPLY TUFF-KOTE
,
LOSS OF USE : 14 DAYS @ SS120/DAY
Labour Total SS :

Resul
4900/10068
10 days
4/3
28/11/19 @ 1600
Resum after repair

120.00
150.00
1,950.00
1,100.00
250.00
150.00
100.00
3,720.00

SIN SHENG ENGINEERING SERVICES

Total SS : 16,961.80

9651.06

378.10

2470.00

12499.06

20%

9,999.24

4/3 - \$10,000

10 days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19021036/R1yf3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-01-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8298U	Veh. Inspected	GBE 6747P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004762MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU LI MEI	Assign Date	27/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX 3.0L A	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDH2010181662	Colour	WHITE	
Odometer	233462	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	AUSTONE	6 mm	
L/H Front Tyre	195 R15C	AUSTONE	6 mm	
R/H Rear Tyre	195 R15C	AUSTONE	6 mm	
L/H Rear Tyre	195 R15C	AUSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/07/2019	Inspection Date	28/11/2019	
Survey held at	NO.8 TUAS AVE 18 (LEVEL 3)			
Repairer	SIN SHENG ENGINEERING SERVICES			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6747P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	677.50	677.50
6	BUMPER CLIP @\$5.00	NECESSARY	30.00	30.00
2	BUMPER SIDE BRACKET @ \$123.50	BENT	247.00	247.00
1	REAR DOOR	BUCKLED	2,150.50	2,150.50
1	REAR DOOR LOCK	JAMMED	275.10	275.10
1	REAR DOOR GARNISH	SERVICEABLE	365.90	-
1	REAR DOOR PARTITION	SERVICEABLE	295.45	-
1	TOYOTA EMBLEM	NECESSARY	53.50	53.50
2	REAR LAMP @ \$365.90 (N/S SERVICEABLE)	O/S CRACKED / N/S NOT CONSISTENT WITH THE IMPACT	731.80	365.90
2	REAR LAMP GARNISH @ \$165.20	SERVICEABLE	330.40	-
1	REAR END PANEL	BENT	585.90	585.90
1	REAR END PANEL INNER	BENT	572.10	572.10
1	STEP PANEL	BENT	319.60	319.60
1	SPARE TYRE BRACKET	BENT	268.50	268.50
1	SPARE TYRE HOOK BOLT	SERVICEABLE	104.20	-
1	EXHAUST BOX	SERVICEABLE	568.20	-
1	REAR BODY WEATHERSTRIP	NECESSARY	312.10	312.10
1	FRONT BUMPER	DEFORMED	577.40	577.40
2	BUMPER SIDE BRACKET @ \$123.50	SERVICEABLE	247.00	-
1	BUMPER GARNISH, CTR	DEFORMED	268.50	268.50
6	BUMPER CLIP @ \$5.00	NECESSARY	30.00	30.00
1	FRONT GRILLE	SCRATCHED	695.21	695.21
1	FRONT CROSSMEMBER	SERVICEABLE	456.20	-
1	FRONT PANEL	BENT	795.10	795.10
1	TOYOTA LOGO	NECESSARY	53.20	53.20
2	BUMPER TOWING COVER @\$31.20	MISSING	62.40	62.40
2	HEADLAMP @ \$645.20	CRACKED	1,290.40	1,290.40
1	PANEL LOCK	BENT	246.20	246.20
1	WASHER TANK	SERVICEABLE	195.20	-

Report Ref No. CS/FCI19021036/R1yf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR-CON CONDENSER	BENT	760.20	760.20
1	RADIATOR	BENT	1,895.87	1,895.87
1	RADIATOR COWLING	SERVICEABLE	468.20	-
2	RADIATOR FAN @\$425.50	SERVICEABLE	851.00	-
1	RADIATOR SUPPORT PANEL	BENT	335.90	335.90
	LESS 25% DISCOUNT		-4,278.93	-3,217.02
			12,836.80	9,651.06
	NETT ITEMS			
2	NUMBER PLATE WITH CASING @ \$40.00 (N)	CUT	80.00	80.00
1	SEALANT (N)	NECESSARY	40.00	40.00
1	8 PAX STICKER (N)	NECESSARY	20.00	20.00
1	70KM/H STICKER (N)	NECESSARY	20.00	20.00
1	REVERSE SENSOR (N)	NOT WORKING	250.00	220.00
1	COOLANT (N)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-45.00	-42.00
			405.00	378.00
	LABOUR			
	TO DISMANTLE / REPLACE REAR WINDSCREEN.		120.00	120.00
	TO DISMANTLE / REPLACE AIR-CON CONDENSER.		150.00	100.00
	TO PANEL BEAT / REPAIR FR BODY. TO PANEL BEAT / REPAIR REAR BODY. TO DISMANTLE / REPLACE ABOVE MENTIONED PARTS.		1,950.00	1,200.00
	TO SPRAY PAINTING.		1,100.00	800.00
	TO APPLY NEW LOGO.		250.00	150.00
	TO APPLY TUFF-KOTE.		150.00	100.00
			3,720.00	2,470.00
GRAND TOTAL			16,961.80	12,499.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,000.00

Report Ref No. CS/FCI19021036/R1yf3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.