

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30890

Vehicle Insured : SHC 3614 Z
Accident Date : 26-Nov-2019

Date : 28-Nov-2019

Our Ref : 190713 (III) / SANDRA

PAGE : 1

WEE JIAN WEI, LESTER (MR)
Singapore

Not Authorized
6/11/19

ESTIMATED COST OF REPAIR FOR B.M.W 316I 1.6 AT (2013) SLZ112G

6 days

- 1 pc n/s rear door
- 1 pc n/s rear door hinges - top
- 1 pc n/s rear door hinges - bottom
- 1 pc n/s rear door checker
- 1 pc n/s rear door weatherstrip
- 1 pc n/s rear door window regulator
- 1 pc n/s rear door window regulator motor
- 1 pc n/s rocker panel
- 1 pc n/s rocker panel rear step garnish
- 1 pc n/s side skirting
- 1 pc n/s side skirting bracket -centre
- 1 pc n/s side skirting bracket -rear
- 1 pc n/s rear shock absorber
- 1 pc n/s rear shock absorber mounting
- 1 pc n/s rear shock absorber stopper
- 1 pc n/s rear knuckle arm
- 1 pc n/s rear knuckle arm bearing
- 1 pc n/s rear bearing hub
- 1 pc n/s rear upper arm
- 1 pc n/s rear upper control arm
- 1 pc n/s rear lower arm
- 1 pc n/s rear lower control arm
- 1 pc n/s rear trailing arm

R 1,273.85 ✓
R 58.90 X
R 58.90 X
Sm 81.48 X
Mr 141.40 *50% in*
D's 252.70 ✓
319.85 ?

R 1,643.30 X
Not Re Author 93.89 ✓
Not/Gr 408.90 ✓
Mr 47.95 ✓

47.95 ?

340.50 ?

Sm 147.55 X

Sm 42.90 X

1,106.95 ?

155.80 ?

165.55 ?

318.85 ?

Sm 127.55 X

350.75 ?

271.05 ?

111.60 ?

7,568.12

Less 10% : -756.81

6,811.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 3614 Z
Our Ref : 190713

Page : 2
No. : 30890

1 pc n/s rear tyre
1 pc n/s rear rim

380.00 sn ?
650.00 sn ✓

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

900.00 600

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 80

To dismantle and check rear under-
carriage. To replace affected
portions.

120.00 ?

To conduct rear wheel alignment
test.

100.00 60

To putty and respray on affected
portions.

1,100.00 1000

Total : S\$10,181.31
=====

Singapore Dollars Ten Thousand One Hundred and
Eighty One and Cents Thirty One Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.