

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Nov 2019 Edit Reg		27 Nov 2019 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD, Co. Reg. No.: 199803778Z	
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K	
Vehicle Reg. No.:	SHB9965B	Date of Loss: 26/11/2019 11:00 - :59 [73 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8589461191SG	Policy/Cover Note No.: 0999994169 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD4527B	Policy No. (Claimant): VPX/P1680520
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com	
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/12/2019]	
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
<ul style="list-style-type: none"> AIG_SG_EXPRESS (06/08/2020): Alert - Adj Mandate Approved (S\$4239.27) - SHB9965B - Claim Handler: Loh, Chee-H... AIG_SG (29/11/2019): Request to upload TP GIA Report 		
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?		
No results.		

Claim Documents

***SHB9965B (8589461191SG)
[GBD4527B]**

TP

TRANS-CAB SERVICES PTE LTD

Nov 26 2019 11:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD]

Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼
Video			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail Print
1	29/11/19 14:55	Video - Accident	Load MP4
2	29/11/19 14:55	Video - Accident	Load MP4
Letters/Correspondences			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	06/08/20 15:35	Adjuster Immediate Advice	Load HTM
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
2	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
3	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
4	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
5	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
6	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
7	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
8	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
9	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
10	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
11	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
12	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
13	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
14	06/08/20 15:23	General View	Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	03/12/19 11:23	TP ESTIMATE - MARKED	Load PDF
2	03/12/19 11:23	TP GIA REPORT	Load PDF
3	19/04/20 17:09	EMAIL TO OI	Load PDF
4	06/08/20 15:25	POLICE INVESTIGATION RESULT	Load PDF
5	06/08/20 15:25	TP LOD, REPAIR BILL, ATA,LTA SEARCH, RENTAL LETTER	Load PDF
6	02/09/20 11:34	Authorisation to Act	Load PDF
7	02/09/20 11:34	LETTER TO OI	Load PDF
8	02/09/20 11:34	LOD	Load PDF
9	02/09/20 11:34	LTA SEARCH	Load PDF
10	02/09/20 11:34	PIR	Load PDF
11	02/09/20 11:34	Release Voucher	Load PDF
12	02/09/20 11:34	RENTAL MILEAGE	Load PDF
13	02/09/20 11:34	RENTAL RECEIPT	Load PDF
14	02/09/20 11:34	WORKSHOP INVOICE	Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail Print
1	29/11/19 14:54	OI GIA REPORT	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBD4527B (Insd veh)	Model:	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A)
	SHB9965B (TP veh)		
Date of Accident:	26/11/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$		29,965.56
Final Repair Cost	:\$		4,230.00
Loss of Use	:\$		_____ days at \$0.00 per day
Rental (if any)	:\$		6 days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$		4,230.00

Is Third Party Workshop GIA Registered?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u>:	Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u>:	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks	_____		

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:\$	4,230.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

02 Sep
2020

Date

**Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19021057/KKA3S2**Date:** 02/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994169
Claimant Vehicle No :	SHB9965B	Insured Vehicle No :	GBD4527B
Date of Loss:	26/11/2019	Nature of Claim:	TP
		Claim No:	8589461191SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9965B	Engine No:	M9R8839C000482
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC273441
Reg. Date:	30/09/2013 (Man. Year: 2013)	Odometer:	567433 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,495.20	2,552.71	10,942.49	81.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,510.00	1,820.00	12,690.00	87.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,005.20	4,372.71	23,632.49	84.39
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	28,005.20	3,500.00	24,505.20	87.50
+ GST 7.00/7.00% (S\$)	1,960.36	245.00	1,715.36	87.50
Nett Amount (S\$)	29,965.56	3,745.00	26,220.56	87.50
+ Car Rental (6.0 x S\$81.13/day) (S\$)		486.78		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,239.27		
Global Sum Settlement (S\$)		4,230.00		

INSPECTION

Date of Assignment:	27/11/2019		
Date Inspected:	27/11/2019	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Bent	758.70 FL	*758.70 FL
2	1		*DOOR HANDLE OUTER REAR RH	Serviceable	42.10 FL	*- FL
3	1		*DOOR HANDLE CAP REAR RH L70Y	Serviceable	57.90 FL	*- FL
4	1		*DOOR HANDLE SEAL REAR RH L70Y	Serviceable	1.60 FL	*- FL
5	1		*DOOR HANDLE COVER REAR RH L70Y	Serviceable	6.10 FL	*- FL
6	1		*DOOR HANDLE MODULE REAR RH L70Y	Serviceable	111.00 FL	*- FL
7	1		*DOOR REGULATOR REAR RH L70Y	Serviceable	758.10 FL	*- FL
8	1		*DOOR REGULATOR MOTOR REAR RH L70Y	Serviceable	450.60 FL	*- FL
9	1		*DOOR BLIND REAR RH L70Y	Serviceable	506.90 FL	*- FL
10	1		*DOOR WEATHERSTRIP REAR RH L70Y	Serviceable	311.60 FL	*- FL
11	1		*DOOR SEAL REAR RH L70Y	Serviceable	119.80 FL	*- FL
12	1		*DOOR GLASS RUNNER SEAL REAR RH L70Y	Serviceable	116.10 FL	*- FL
13	1		*DOOR WAIST SEAL OUTER REAR RH L70Y	Serviceable	99.40 FL	*- FL
14	1		*DOOR LOCK REAR RH	Serviceable	467.30 FL	*- FL
15	1		*DOOR GUIDE REAR RH	Serviceable	136.40 FL	*- FL
16	1		*DOOR FINISHER REAR RH	Serviceable	206.40 FL	*- FL
17	1		*DOOR MOULDING REAR RH	Serviceable	100.50 FL	*- FL
18	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
19	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
20	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
21	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
22	1		*FENDER PANEL REAR RH	Bent	1,933.20 FL	*1,933.20 FL
23	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
24	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
25	1		*BUMPER COVER REAR	Repair	561.70 FL	*- FL
26	1		*BUMPER LOWER REAR	Repair	411.90 FL	*- FL
27	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
28	1		*BUMPER BRACKET SIDE RH REAR	Repair	82.10 FL	*- FL
29	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
30	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
31	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL
32	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
33	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS
34	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
35	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
36	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
37	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
39	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
40	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
41	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
42	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
43	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
44	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
45	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
46	1		*SET BUMPER RETAINER CLIP RH RR	Not Necessary	20.00 FS	*- FS
47	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
48	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
49	1		*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,767.89	2,821.90
- List Item Discount on L Items 10.00/10.00% (\$)	1,272.69	269.19
Total Parts (\$)	13,495.20	2,552.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	6,000.00	800.00
2	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	100.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
5	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	120.00
6	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
7	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	60.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
12	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	660.00
14	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
Gross Labour Cost (\$\$)			14,510.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >