

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9965B

AAD1911-210

*Not Authorised
L/Sing @ 3500k*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

27 NOV 2019

SHB 9965B

VF1ABL15AUC273441

RENAULT

LATITUDE

26.11.19

AIG

30/9/2013

PART			LIST	
1	DOOR PANEL REAR RH	\$	B1 758.70	✓
1	DOOR HANDLE OUTER REAR RH	\$	S2 42.10	} X
1	DOOR HANDLE CAP REAR RH L70Y	\$	S2 57.90	
1	DOOR HANDLE SEAL REAR RH L70Y	\$	S2 1.60	
1	DOOR HANDLE COVER REAR RH L70Y	\$	S2 6.10	
1	DOOR HANDLE MODULE REAR RH L70Y	\$	S2 111.00	
1	DOOR REGULATOR REAR RH L70Y	\$	S2 758.10	
1	DOOR REGULATOR MOTOR REAR RH L70Y	\$	S2 450.60	
1	DOOR BLIND REAR RH L70Y	\$	S2 506.90	
1	DOOR WHEATHESTRIIP REAR RH L70Y	\$	S2 311.60	
1	DOOR SEAL REAR RH L70Y	\$	S2 119.80	
1	DOOR GLASS RUNNER SEAL REAR RH L70Y	\$	S2 116.10	
1	DOOR WAIST SEAL OUTER REAR RH L70Y	\$	S2 99.40	
1	DOOR LOCK REAR RH	\$	S2 467.30	
1	DOOR GUIDE REAR RH	\$	S2 136.40	
1	DOOR FINISHER REAR RH	\$	S2 206.40	
1	DOOR MOULDING REAR RH	\$	S2 100.50	
1	ROCKER PANEL INNER GARNISH RH	\$	S2 466.51	
1	ROCKER PANEL INNER RH	\$	N 1,024.79	
1	ROCKER PANEL OUTER RH	\$	N 1,184.99	
1	ROCKER PANEL CENTER RH	\$	N 990.25	
1	FENDER PANEL REAR RH	\$	B2 1,933.20	✓
1	FENDER PANEL INNER TRIM REAR RH	\$	S2 671.45	X
1	WHEELARCH REAR RH	\$	S2 275.40	X
1	BUMPER COVER REAR	\$	N 561.70	X
1	BUMPER LOWER REAR	\$	N 411.90	X
1	BUMPER BRACKET CTR REAR	\$	S2 98.10	X

Trans-cab Auto Services Pte Ltd

AAD1911-210

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9965B

1	BUMPER BRACKET SIDE RH REAR	\$	R	82.10	X
1	BUMPER RETAINER RH REAR	\$	Sn	59.80	X
1	BOOT REFLECTOR LAMP RH	\$	Sn	277.70	X
1	TAILLAMP RH	\$	Sn	313.10	X
1	EXHAUST CAP REAR	\$	Sn	125.40	X
TOTAL		\$		12,726.89	
10%		\$		1,272.69	
		\$		11,454.20	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	Mc	80.00	60sn
1	FENDER INNER TRIM CLIP RH	\$	Nn	28.00	X
1	TAILLAMP CLIP RH	\$	Nn	5.00	X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	Nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	Mc	80.00	40sn
1	WINDSCREEN MOULDING	\$	Nn	100.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Mc	100.00 100.00	30sn
1	REAR RIGHT TYRE	\$	Sn	300.00	} X
1	REAR RIGHT TYRE RIM	\$	Sn	380.00	
1SET	PARKING AID	\$	Sn	700.00	
1SET	REAR BUMPER CLIP	\$	Nn	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	Nn	33.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	Nn	10.00	
1SET	BUMPER RETAINER CLIP RH RR	\$	Nn	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	Nn	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	Nn	66.00	
1	EXHAUST MOUNTING REAR	\$	Nn	16.00	
TOTAL		\$		2,041.00	

TOTAL PARTS \$ 13,495.20

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00

8000

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9965B

AAD1911-210

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	<i>100</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$		170.00	<i>120</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$		170.00	<i>60</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
To rust-proofing of the affected areas.	\$		170.00	<i>60</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>20</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i>	170.00	X
Putty and spray painting of the affected portion.	\$		6,000.00	<i>660</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i>	170.00	X

TOTAL \$ 14,510.00

Over All Total \$ 28,005.20

LUMP SUM (REPAIR DAY)

20 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: